

Product discontinuation notification (PDN)

Title / short description Discontinuation Low-Runners
Affected article category Terminal blocks
Change category Discontinuation
Change number IBE260015-00
Reason for PCN/PDN Revision

Purpose/objective of the change

Discontinuation due to portfolio optimization

Detailed description of the change

Discontinuation due to portfolio streamlining.

Identifying characteristics

Attached article list

Start of Production (SOP)	-	Last Time Delivery (LTD)	2027-07-31
Effective date (EOP)	2027-04-30	End of Service (EOSR)	-
End of Sales (EOS)	2027-04-30		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure | <input type="checkbox"/> Product improvement with customer benefits | |
| <input type="checkbox"/> Others | | |

Attachments

- Material_list.csv
- PDN-IBE260015-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
3060487	UTTB 2,5/2P-PV BU			3060377	UTTB 2,5/2P-PV
1914823	HCC 4-CLIP				
3031309	ST 2,5-QUATTRO/2P-D				
3212444	PTTB 1,5/S/2P BK				
1027883	PTS 1,5/S-3PV/3P				
3061897	PP-H 2,5/24				
3061733	PP-H 6/ 1-R OG				
3043912	SC 2,5/ 6 X82				
1170812	NS 35/ 7,5 BW UNPERF 1000MM				
1277647	NS 35/15 BW LPERF 1000MM				
1037088	PTTBS 2,5 BN			3209604	PTTBS 2,5
3208198	PT 1,5/S-QUATTRO-LA 24 RD				
3210280	PT 2,5-QUATTRO-LA 24 RD				
1054011	DP-CLIPFIX 35-5				
3049440	HV M5/1-VS 3				
3049644	HV M12/1-VS 3				
1067276	DP-HV M12/1 NFF				
1033193	UTT 2,5-2MT-R250/O-U				
3048564	PS-8/2,3MM RD				
3060500	UT 2,5-TWIN/1P BU				
0790620	OTTA 6 YE			0790433	OTTA 6
0804505	CLIPFIX 35/WU				
0803772	NS 35/ 7.5 930MM				

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

3060487;UTTB 2

1914823;HCC 4-CLIP;;;;;27141190;

3031309;ST 2

3212444;PTTB 1

1027883;PTS 1

3061897;PP-H 2

3061733;PP-H 6/ 1-R OG;;;;;27250306;

3043912;SC 2

1170812;NS 35/ 7

1277647;NS 35/15 BW LPERF 1000MM;;;;;27400602;

1037088;PTTBS 2

3208198;PT 1

3210280;PT 2

1054011;DP-CLIPFIX 35-5;;;;;

3049440;HV M5/1-VS 3;;;;;27141190;

3049644;HV M12/1-VS 3;;;;;27141190;

1067276;DP-HV M12/1 NFF;;;;;27250301;

1033193;UTT 2

3048564;PS-8/2

3060500;UT 2

0790620;OTTA 6 YE;;;0790433;OTTA 6;27250101;

0804505;CLIPFIX 35/WU;;;;;27250302;

0803772;NS 35/ 7.5 930MM;;;;;27400602;

5/2P-PV BU;;;3060377;UTTB 2

5/2P-PV;27250102;

5-QUATTRO/2P-D;;;;;27250117;

5/S/2P BK;;;;;27250117;

5/S-3PV/3P;;;;;27250102;

5/24;;;;;27250306;

5/ 6 X82;;;;;27141106;

5 BW UNPERF 1000MM;;;;;27400602;

5 BN;;;3209604;PTTBS 2

5;27250102;

5/S-QUATTRO-LA 24 RD;;;;;27250101;

5-QUATTRO-LA 24 RD;;;;;27250101;

5-2MT-R250/O-U;;;;;

3MM RD;;;;;27250304;

5-TWIN/1P BU;;;;;27250117;

PCN/PDN Number	Customer Number	Company Name	Street
IBE260015	401641	TTI, INC.	2441 NORTHEAST PKWY

Postcode/Zip Code	City	Phoenix Contact Item-Nr. (changed/discontinued article)
76106	FORT WORTH	0804505

Phoenix Contact Item Designation (changed/discontinued article)

CLIPFIX 35/WU

Phoenix Contact Article-Nr. (customer specific)

8191413

Phoenix Contact Article Designation (customer specific)
CANRIG-PUSH-IN-RAIL

Report Date **Substitute Item**
08.06.2026

Replacement Product Designation