

Product Name:	HPL – 833	
	Customized BTB connector	
Product Manager:	Nina Zhou	
Subject:	Notification of Planned Change	
Distribution:	Affected customers	
Type of Change:	Location Change	
Change Description:	Production location change from Amphenol Nantong China to Amphenol Cochin India	
Reason for Change:	Customer requirement	
Affected Parts:	See Affected Parts.xls	
Effective Date of Change:	November,01 2026	
Last Time Buy Date:	NA	
Earliest Disty Return Date:	NA	
Last Time Shipment Date	NA	
Datasheet Attached?	No	
Qual/Test Data Attached?	No	
Samples Availability Date:	01 November ,2026	
Available Alternatives?		
Questions?	<i>Contact your local ACS Representative, or Product Manager</i>	
	<i>Nina Zhou / Product Manager</i>	
	<i>Nina.Zhou@amphenol-fci.com</i>	

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date
PCN26166	10191094-210111RLF	LOCATION CHANGE	NOVEMBER 1, 2026
PCN26166	10191094-210111VLF	LOCATION CHANGE	NOVEMBER 1, 2026
PCN26166	10191094-418111RLF	LOCATION CHANGE	NOVEMBER 1, 2026
PCN26166	10191094-418111VLF	LOCATION CHANGE	NOVEMBER 1, 2026
PCN26166	10191095-210113VLF	LOCATION CHANGE	NOVEMBER 1, 2026
PCN26166	10191095-418113VLF	LOCATION CHANGE	NOVEMBER 1, 2026
PCN26166	10191244-A32111VLF	LOCATION CHANGE	NOVEMBER 1, 2026
PCN26166	10191244-B32111VLF	LOCATION CHANGE	NOVEMBER 1, 2026
PCN26166	10191244-Z32111VLF	LOCATION CHANGE	NOVEMBER 1, 2026
PCN26166	10191245-A32113VLF	LOCATION CHANGE	NOVEMBER 1, 2026
PCN26166	10191245-B32113VLF	LOCATION CHANGE	NOVEMBER 1, 2026
PCN26166	10191245-Z32113VLF	LOCATION CHANGE	NOVEMBER 1, 2026

[illegible]

[illegible]

Affected finshed goods part number List	Customer part number List	
10191094-210111RLF	4241202-00-A	LOCATION CHANGE
10191094-210111VLF	4241203-00-A	LOCATION CHANGE
10191094-418111RLF	4242202-00-A	LOCATION CHANGE
10191094-418111VLF	4242203-00-A	LOCATION CHANGE
10191095-210113VLF	4241201-00-B	LOCATION CHANGE
10191095-418113VLF	4242201-00-B	LOCATION CHANGE
10191244-A32111VLF	4233202-20-B	LOCATION CHANGE
10191244-B32111VLF	4233202-30-B	LOCATION CHANGE
10191244-Z32111VLF	4233202-10-B	LOCATION CHANGE
10191245-A32113VLF	4233201-20-C	LOCATION CHANGE
10191245-B32113VLF	4233201-30-C	LOCATION CHANGE
10191245-Z32113VLF	4233201-10-C	LOCATION CHANGE