**ITT Cannon LLC**
56 Technology Drive
Irvine, CA 92618

**Date:** 9/25/26
**Subject:** Notice of Addition to Component Supply Source

Dear Valued Customer:

This Notice of Change in Component Supply Source is to inform you that ITT Cannon LLC ("ITT") is adding **Aerospace Contacts, LLC** ("AC"), an ITT affiliate located at **1343 N. Colorado St., Suite #107, Gilbert, Arizona 85233**, as an additional supplier within ITT's existing supply base for contacts, hardware, housings, and shells (collectively, "Components") used in its connector products.

ITT expects to begin using these Components in its connector products ("Affected Products") in **Q4 2026**. ITT's incumbent source(s) for the Components will remain qualified to maintain appropriate inventory coverage and supply flexibility. Adding AC to ITT's supply base is expected to benefit customers by enhancing supply continuity, increasing available capacity, and improving responsiveness to customer demand.

Please note that this change will not affect the form, fit, or function of the Affected Products. AC will manufacture these Components to the same released drawings and specifications currently in effect. All applicable specifications, qualifications, and quality requirements of the Components will continue to be met under AC production. In order to maintain the highest quality, ITT is performing First Article Inspections ("FAI") per AS9102 on Components manufactured by AC prior to shipping any Affected Products. AC holds AS9100 certification and utilizes NADCAP-accredited suppliers for applicable special processes.

For your reference, enclosed is a list of Affected Products that you have either purchased from ITT over the past 3 years and/or are in ITT's backlog as of the date of this letter.

If you have any questions, please contact your Regional Sales Manager.

Best regards,

ITT Cannon LLC

## AFFECTED PRODUCTS

This is information is provided to the customer indicated below in conjunction with ITT Cannon's September 2026 letter regarding the addition of **Aerospace Contacts, LLC** ("AC"), an ITT affiliate located at **1343 N. Colorado St., Suite #107, Gilbert, Arizona 85233**, as an additional supplier within ITT's existing supply base for contacts, hardware, housings, and shells (collectively, "Components") used in its connector products.

| **76000298** | **TTI INC. PASSIVE WAREHOUSE** |
|---|---|

| ITT Part # | Customer Part No | Part Number Description | Customer PO # |
|---|---|---|---|
| 009310-0024 | 1159SCAV200-3 | CE9310-24 | 4716769 |
| 009346-0041 | | CE9346-41 TERMINAL | 4707116 |
| 019776-0076 N | 3256650-2 | GS19776-76 (NADCAP) | 4824841 |
| 020420-0108 | | D20420-108 | 4858388 |
| 021000-1792 | CANDPXB-13-34P-0101 | DPXB-13-34P-0101. | 4840015 |
| 021000-2512 | CANDPXBMA-10-34S-0029 | DPXBMA-10-34S-0029 | 4007807 |
| 021000-2690 | | DPXBMA-D8-34P-0107. | 4873982 |
| 030-1975-009 | GAC835PC22P | CNT P DPXMA-2222 ALU | 4930333 |
| 030-2097-015 | CAN030-2097-015 | CNT P KJ-22D-8 P/C H/D | 4923838 |
| 030-2286-000 | CAN030-2286-000 | CONTACT,PIN,DPXMA/BKAD 1212 LOW FORCE | 4953186 |
| 031-0486-081 | CAN031-0486-081 | CNT ASM S MS-R-8 | 4848872 |
| 031-1007-048 | CAN031-1007-048 | CONT SKT D*MA-2026 | 4846375 |
| 031-1007-048 | | | 4914116 |
| 031-1007-054 | CAN031-1007-054 | CONT SKT D*MA-2018HD A156 | 4950337 |
| 031-1147-014 | CAN031-1147-014 | CNT ASM *VMI* | 4923029 |
| 031-1302-000 | CANGAC835PA20S | CONTACT ASSY.,SKT,DPXMA/BKAD #2020 | 4930334 |
| 031-1308-000 | GAC835PA12S | CNT ASSY **VMI** | 4840861 |
| 031-8929-002 MS | CAN031-8929-002 MS | D*M A/C R1 SKT 50 | 4898721 |
| 031-8929-012 MS | CAN031-8929-012 MS | D*M A/C R2 SKT 50 | 4941136 |
| 031-8931-012 MS | CAN031-8931-012 MS | D*M G/K/W R2 SKT 50 | 4914885 |
| 031-8932-012 MS | CAN031-8932-012 MS | D*M J/L/S R2 SKT 50 | 4868541 |
| 031-9540-005 | CAN031-9540-005 | CONT ASSY, PIN, CENTI-LOCK | 4891436 |
| 036571-0059 | CANDPXB36571-59 | DPXB36571-59. | 4892690 |
| 037255-0006 | CANCA3106HR10SL-4S | CA3106HR10SL-4S. | 4891288 |

| | | | |
|---|---|---|---|
| 041414-0602 | | CA41414-602. | 4938733 |
| 041700-0751 | CANDPDRMA7834P1G-A176 | DPDRMA-78-34P-1G-A176 | 4931102 |
| 041723-0139 | | DPX2NE41723-139. | 4934770 |
| 041783-1745 | CAN041783-1745 | DPX2MA-67MP33Q4MP-34B-2302. | 4781658 |
| 042226-1000 | 05A079W403A46 | TBKB-150 | 4512517 |
| 042941-0830 | | DPKB-64SX-7. | 4826089 |
| 044999-0016 | CANDPX2DA26S7S33B1401 | DPX2DA-26S7S-33B-1401. | 4766824 |
| 045527-0395 | | KPT45527-395. | 4910083 |
| 045621-0006 MS | MS3116P8-4S | KPT06P8-4S. | 4896957 |
| 045927-0003 | CANKPTB2024PS | KPTB20-24PS. | 4924298 |
| 045927-0011 | | KPTB20-41PS | 4945985 |
| 050912-0399 | CANDCMA37PNM | DCMA37PNM | 4912361 |
| 050913-0302 | 922776-3C | DDMA50913-302 | 4663695 |
| 051521-0157 | CANDAMM3V3SNF225 | DAMM3V3SNF225 | 4894211 |
| 051522-0193 | 11472547-2 | DBM51522-193 | 4870716 |
| 053512-3077 | CANDAME15SEA159 | DAME15SEA159 | 4776196 |
| 053513-2275 | CANDBMZ25PNK87 | DBMZ25PNK87 | 4886686 |
| 053515-3043 | 3GPDE066-015 | DDM53515-3043 | 4862217 |
| 053516-0482 | | DEM9PX | 4795943 |
| 053742-0001 | CANDM53742-1 | DM53742-1 | 4832252 |
| 053744-0007 | CANDM53744-7 | DM53744-7 | 4909916 |
| 053744-0007 | | | 4928266 |
| 053745-0028 | CANDM53745-28 | DM53745-28 | 4864182 |
| 067299-0001 | CANKPDL07EN8-4P | KPDL07EN8-4P. | 4939626 |
| 067318-0296 | CANDPX2NA67318-296 | DPX2NA67318-296. | 4868545 |
| 067322-0180 | | DPX2NE67322-180-04 | 4934772 |
| 067322-0455 | 5M1972-05P01P | #DPX2NE67322-455-14 | 4835182 |
| 067322-0605 | 17B9E4004-593 | DPX2NA-67322-605 | 4511032 |
| 067323-0054 | | DPX3NE67323-54-04 | 4829990 |
| 067323-0054 | | | 4934772 |
| 067400-0001 | CANBKAD1-125-30029 | BKAD1-125-30029 | 4712139 |
| 067400-0001 | | BKAD1-125-30034 | 4930333 |
| 067400-0001 | | BKAD1-125-30069 | 4930333 |
| 067402-0563 | | BKAD2-A283-300. | 4930333 |
| 067402-0597 | CANBKAD2-Q174-33388 | BKAD2-Q174-33388. | 4825418 |
| 067402-0637 | CANBKAD2-QA138-333 | BKAD2-QA138-333. | 4904563 |
| 067404-0201 | | BKAD3-271C-30140. | 4930333 |
| 067404-0510 | | BKAD3-619-32301. | 4824097 |

| | | | |
|---|---|---|---|
| 068101-0094 | 223-7150-8002 | BKAF2-68101-94. | 4764368 |
| 068101-0426 | | BKAF2-68101-426. | 4863449 |
| 095254-0003 | | MTB1-3PS | 4683666 |
| 095264-0051 | CANMTB1-8PS | MTB1-8PS | 4685178 |
| 096260-0009 | CAN2DA31S-F171 | 2DA31S-F171 | 4899394 |
| 096264-0015 | CAN2DC79SA160 | 2DC79SA160 | 4907179 |
| 096511-0076 | | MDM-9SSB | 4831389 |
| 096511-0646 | | MDM-9SH230P-A172 | 4938747 |
| 096511-0657 | | MDM-9SCBRP-11-A174 | 4907477 |
| 096511-0903 | CANMDM-9SSM5 | MDM-9SSM5 | 4914884 |
| 096512-1016 | | MDM-15PH025F | 4927860 |
| 096513-0047 | CANMDM-15SH003B | MDM-15SH003B | 4836740 |
| 096513-0149 | CANMDM-15SH006B | MDM-15SH006B | 4882592 |
| 096513-0149 | | | 4934166 |
| 096515-0491 | | MDM-21SH196P-A172 | 4938747 |
| 096517-0038 | CAN096517-0038 | MDM-25SSB | 4684246 |
| 096519-0223 | | MDM-31SSP-A174 | 4802334 |
| 096521-0011 | CANMDM-37SH006B | MDM-37SH006B | 4941136 |
| 096521-0023 | | MDM-37SL2B | 4718425 |
| 096521-0059 | CANMDM-37SSB | MDM-37SSB | 4785232 |
| 096521-0552 | CANMDM-37SSM5-A174 | MDM-37SSM5-A174 | 4913361 |
| 096521-0552 | | | 4924932 |
| 096523-0038 | CANMDM-51SSB | MDM-51SSB. | 4903735 |
| 097195-0124 | CANMIKQ6-7SH94GE | MIKQ6-7SH94GE | 4869671 |
| 097195-0236 | CANMIKQ6-7SH177GE | MIKQ6-7SH177GE | 4869671 |
| 097323-0053 | CANMIKM0-7SH074 | MIKM0-7SH074 | 4935401 |
| 097333-0008 | | MJSB-10SH003 | 4734369 |
| 097333-0011 | CANMJSB-10SH034 | MJSB-10SH034 | 4928266 |
| 097333-0059 | | MJSB-10SH23 | 4869643 |
| 097345-0087 | CANMDVB1-15SH23 | MDVB1-15SH23 | 4919896 |
| 097397-0014 | CANMJSV-16SH003 | MJSV-16SH003 | 4950747 |
| 097530-0005 | 5190220 | MDV1-9SS-1 | 4712816 |
| 098479-0015 | | MDM98479-15 | 4859911 |
| 098479-0090 | | MDM98479-90 | 4899109 |
| 098579-0004 | | MJSR-34SL56-1 | 4953001 |
| 098579-0006 | | MJSR-34SL56-3 | 4953002 |
| 098579-0008 | | MJSR-34SL56-5 | 4953008 |
| 100071-0039 | CANKPT1H833PN | KPT1H8-33PN | 4751754 |
| 107004-2033 | 4079357-0702 | TMDM107004-2033 | 4946258 |
| 110824-0001 | CANCA110824-1 | CA110824-1. | 4725533 |
| 110831-0093 | CANKJ5E10B5PN21 | KJ5E10B5PN21. | 4944067 |

| | | | |
|---|---|---|---|
| 111079-0074 | CANKJL6T17B6SN | KJL6T17B6SN. | 4950747 |
| 111400-2660 | | PHD111400-2660 | 4923360 |
| 111400-2661 | | PHD111400-2661 | 4923360 |
| 111426-0257 | | KJA111426-257. | 4825076 |
| 111434-0935 | CANKJA0T25F64PN27 | KJA0T25F64PN27. | 4899130 |
| 111931-0001 | 11472560-1 | D111931-1 | 4814522 |
| 111931-0004 | 11472560-4 | D111931-4 | 4885398 |
| 112230-0036 | | DBMA25PPNMBK128K134 | 4874585 |
| 112288-0106 | | MKJ4NW-CS-A-036 | 4898004 |
| 130774-0088 MS | M24308/24-35F | M24308/24-35F | 4917583 |
| 142005-0010 | 05A070W309B31 | BKW4E309-0031SE | 4511049 |
| 151700-0485 | | BKB TRIAX-SKT. | 4839553 |
| 154169-0009 MS | M83513/02-AN | MDM02-A9A174 | 4826077 |
| 154171-0009 MS | M83513/02-BN | MDM02-B15A174 | 4826079 |
| 154171-0009 MS | | | 4902360 |
| 154175-0000 MS | M83513/02-DC | MDM02-D25 | 4826078 |
| 154175-0009 MS | M83513/02-DN | MDM02-D25A174 | 4826079 |
| 154177-0009 MS | M83513/02-EN | MDM02-E31A174 | 4919898 |
| 154179-0000 MS | M83513/02-FC | MDM02-F37 | 4848872 |
| 154179-0000 MS | | | 4924292 |
| 154179-0009 MS | M83513/02-FN | MDM02-F37A174 | 4826078 |
| 154181-0009 MS | M83513/02-GN | MDM02-G51A174 | 4924292 |
| 155122-2001 | CANMKJ1A6Z7-10PA | MKJ1A6Z7-10PA | 4940876 |
| 155123-0301 | | MKJ1A6F9-210PA | 4786489 |
| 155123-1000 | | MKJ1A6W9-19SA | 4914691 |
| 155141-0301 | CANMKJ1A7F6-23SA | MKJ1A7F6-23SA | 4786490 |
| 155200-0106 | | MKJ1C7F5-3BA-518 | 4805212 |
| 155203-1100 | MKJ1C7W9-19BA | MKJ1C7W9-19BA | 4943925 |
| 155203-1100 | | MKJ1C7W9-19BA | 4914698 |
| 155208-1125 | | #MKJ1C7W16-55HC-518 | 4786498 |
| 155209-0105 | | MKJ1C7F17-85HA-518 | 4786504 |
| 155643-0500 | CANMKJ1B6F9-4PA | MKJ1B6F9-4PA | 4786498 |
| 155643-0501 | CANMKJ1B6F9-4SA | MKJ1B6F9-4SA | 4786505 |
| 155681-0106 | CANMKJ1C75F6-7GA | MKJ1C75F6-7GA | 4841886 |
| 155682-0003 | CANMKJ1C75F7-10HA | MKJ1C75F7-10HA | 4841886 |
| 155701-0005 | CANMKJ1A26F6-6SA | MKJ1A26F6-6SA | 4786506 |
| 155715-0105 | | MKJ1C7F21-130HA-518 | 4786504 |
| 155900-0057 | CANMKJ4C7-155900-57 | MKJ4C7-155900-57 | 4796040 |
| 155900-0057 | | MKJ4C7-155900-57 | 4825405 |

| | | | |
|---|---|---|---|
| 224-1001-010 | | #PIN CONT ASSY,TWINAX,SZ5,REV GENDER... | 4682030 |
| 249-3033-000 | CAN249-3033-000 | SHELL ASSM KPT 00E-12 A66 | 4941136 |
| 249-3035-000 | CAN249-3035-000 | SHELL ASSM KPT 00E 16 A66 | 4842275 |
| 249-3035-000 | | | 4865086 |
| 249-3035-200 | CAN249-3035-200 | SHELL ASSY., KPT00E16-A206 | 4897428 |
| 249-3035-200 | | | 4948622 |
| 249-3051-200 | CAN249-3051-200 | SHELL ASSY., KPT02E8-A206 | 4945589 |
| 249-3053-200 | CAN249-3053-200 | SHELL ASSY KPT02E12-A206 | 4751330 |
| 249-3055-200 | CAN249-3055-200 | SHELL ASSY., KPT02E16-A206 | 4936199 |
| 249-3061-000 | CAN249-3061-000 | SHELL ASSEM KPT07E-8 | 4939621 |
| 249-3064-000 | CAN249-3064-000 | SHELL ASSEMBLY-KPT07E-14 | 4868540 |
| 249-3162-000 | CAN249-3162-000 | SHELL ASSEMBLY KPT07-A-10 | 4879174 |
| 330-8929-012 MS | CAN330-8929-012 MS | D*M AC R2 P 50 | 4888601 |
| 330-8932-010 | CAN330-8932-010 | D*M J/L/5 R2 PIN | 4938498 |
| 330-8932-012 MS | CAN330-8932-012 MS | CONTACT D*M J/L/S R2 PIN 50 | 4919896 |
| 330-8934-002 | CAN330-8934-002 | D*M F179 P 50 | 4891856 |
| 349-1087-004 | CAN349-1087-004 | SHELL ASSY,RECEPT BGG #8 | 4930334 |
| 357-1045-002 | CN447-03 | RETAINER ASSY,RECEPT,AIMS-2,137 POS... | 4678315 |
| 357-1045-014 | 4089222-7 | RETAINER ASSY,RECEPT,AIMS2 137 POS SPCL | 4897599 |
| 360-6019-000 | CAN360-6019-000 | CONN ASSY GM103641-504 47 | 4619092 |
| 51114309-029 | | CT,PIN0,CP,MS/C,LGBUCK,T9,0AWG | 4899545 |
| Z30874 | CANCIR07RG20-3P-F80 | CIR07RG-20-3P-F80. | 4946258 |
| Z44746 | CANCIR030G2W-36-5P-F80 | CIR030G2W-36-5P-F80 | 4853889 |
| Z44750 | CANCIR06G2W1-36-5P-F80 | CIR06G2W1-36-5P-F80 | 4853889 |
| Z80023 | CANCIR06G-32-17PW-F80 | CIR06G-32-17PW-F80 | 4920461 |
| Z86586 | CANCIR06CD6-10SL-55S-9 | CIR06CD6-10SL-55S-98-TCC | 4914116 |
| Z86586 | | CIR06CD6-10SL-55S-98-TCC | 4835664 |
| Z98163 | | CIR030FP-32-1P-F80-T104 | 4899545 |
| Z98163 | | | 4918145 |
| Z98686 | | CIR030RVFP-28-10P-F80-T104 | 4859908 |
| Z99152 | Z99152 | CIR030FP-32-5P-F80-T104 | 4945460 |