



Product Change Notification

Current Date: 05-Oct-2026

TE Connectivity

Product Change Notification: P-26-031485

PCN Date: 16-SEP-26

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Raw Material Change impacting -3,-125 and CES Molded Parts

Description of Changes

This notice informs you that due to Mitsubishi Chemical Group (MCG) announcing that the manufacturing of products from their plant will be discontinued in stages starting in March 2026 and fully terminated by the end of March 2027. TE connectivity is enforced to change a cross-linking additive within -3, -125 and CES molded parts with a drop-in, like-for-like alternative (same CAS Number). Based on internal testing, there will be no impact on the fit, form, or function of the finished product.

Other attachments:

[Communication Letter](#)

Reason for Changes:

Product improvement. The replacement additive will be phased into production as relevant approvals are obtained. As a result, there will be a transition period during which shipments may contain products manufactured using either the existing additive or the new additive; TE will maintain full traceability to be able to identify the additive used in the supplied customer product. If you have any questions or require further information regarding this change, please contact your TE Connectivity representative.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

16-SEP-2026

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

30-SEP-2027

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
019265-000	NO			3-1190150-9, 462A023-3-G08-0			
156266-000	NO			8-1191128-6, 243D022-3-G04-0			
274243-000	NO			1192031-2, 243D012-3-G04-0			
276339-000	NO			6-1192046-3, 342A124-3-G02-0			
293826-000	NO			7-1192226-7, 202A132-3/86-0			
409534-001	NO			1-1193089-7, CES-1			
419820-000	NO			7-1193162-4, 202K132-3/86-0			
510141-000	NO			1194010-7, 222A111-3/86-0			
808167-000	NO			1196270-3, 222D921-3-0			
808396-000	NO			6-1196274-3, 222D211-3-0			
812836-000	NO			4-1196323-1, 222K121-3-0			
812841-000	NO			5-1196323-3, 202K132-3-0			
812842-000	NO			6-1196323-1, 202K153-3-0			
812843-000	NO			6-1196323-8, 222K142-3-0			
812846-000	NO			7-1196323-8, 222K152-3-0			
812860-000	NO			9-1196323-1, 202K163-3-0			
812996-000	NO			8-1196324-3, 202K142-3-0			
812997-000	NO			9-1196324-3, 42FLS202K121-3-M, 202K121-3-0			
813788-000	NO			1196332-6, 202A142-3-0			
813848-000	NO			5-1196332-0, 202A132-3-0			
813856-000	NO			7-1196332-1, 222A163-3-0			
814300-000	NO			8-1196337-7, 202A174-3-0			
814308-000	NO			1-1196338-0, 202A111-3-0			
814316-000	NO		SS7073-0201	2-1196338-9, 202A121-3-0			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
814409-000	NO			8-1196340-1, 214A011-3-0			
814511-000	NO			7-1196342-0, 222A121-3-0			
814777-000	NO			1196348-6, 202A111-3/42-0			
822283-000	NO			7-1196412-4, 204K012-3-0			
822521-000	NO			7-1196414-0, 202K121-3-01-0			
822596-000	NO			2-1196416-7, 202K142-3/42-0			
822747-000	NO			8-1196417-6, 222K174-3-0			
822799-000	NO			3-1196418-6, 202K232-3-01-0			
822840-000	NO			6-1196418-5, 222K132-3-0			
822841-000	NO			7-1196418-6, 222K163-3-0			
823184-000	NO			5-1196422-0, 382A023-3-00-0			
823211-000	NO			1196423-4, 301A011-3-0			
823774-000	NO			1-1196433-8, 462A023-3-0			
823776-000	NO			2-1196433-6, 382A012-3-0			
843031-000	NO			1196576-4, 101A011-3-0			
843921-000	NO			9-1196583-5, 202K174-3-0			
936829-000	NO			6-1197257-0, 462A011-3/86-0			
E84696-001	NO			8-1201236-0, CES-2-D1			



Product Change Notification

Current Date: 05-Oct-2026

TE Connectivity

Product Change Notification: P-26-031485

PCN Date: 16-SEP-26

Customer: TTI Inc (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Raw Material Change impacting -3,-125 and CES Molded Parts

Description of Changes

This notice informs you that due to Mitsubishi Chemical Group (MCG) announcing that the manufacturing of products from their plant will be discontinued in stages starting in March 2026 and fully terminated by the end of March 2027. TE connectivity is enforced to change a cross-linking additive within -3, -125 and CES molded parts with a drop-in, like-for-like alternative (same CAS Number). Based on internal testing, there will be no impact on the fit, form, or function of the finished product.

Other attachments:

[Communication Letter](#)

Reason for Changes:

Product improvement. The replacement additive will be phased into production as relevant approvals are obtained. As a result, there will be a transition period during which shipments may contain products manufactured using either the existing additive or the new additive; TE will maintain full traceability to be able to identify the additive used in the supplied customer product. If you have any questions or require further information regarding this change, please contact your TE Connectivity representative.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

16-SEP-2026

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

30-SEP-2027

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
005121-000	NO			1-1190039-1, 234A711-3-02/42-0			
019265-000	NO			3-1190150-9, 462A023-3-G08-0			
042421N001	NO			3-1190325-0, 202D211-3-61/42-0-CS5077			
063499N001	NO			6-1190479-4, 202D163-3-60/42-0-CS5077			
147733-000	NO			7-1191067-4, 222D152-3-60-0-CS5078			
154183N001	NO			8-1191113-6, 202A312-3-12/42-0-CS6687			
156266-000	NO			8-1191128-6, 243D022-3-G04-0			
182179N001	NO			9-1191323-2, 102A981-3/42-8-CS5182			
224645N002	NO			8-1191654-7, 202D163-3-60-0-CS5077			
235705-000	NO			7-1191733-0, 222D211-3-0-CS5429			
254643-000	NO			3-1191864-4, 382A023-3-0-CS5075			
268769-000	NO			7-1191983-8, 222A255-3-01/42-0			
274243-000	NO			1192031-2, 243D012-3-G04-0			
276339-000	NO			6-1192046-3, 342A124-3-G02-0			
293826-000	NO			7-1192226-7, 202A132-3/86-0			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
324529-000	NO			1192456-6, 202D253-3-61-0- CS5077			
361649N002	NO			2-1192712-2, 202D211-3-61-0- CS5077			
404927-000	NO			1-1193056-1, 227W256-3-A03- 0			
409534-001	NO			1-1193089-7, CES-1			
419820-000	NO			7-1193162-4, 202K132-3/86-0			
422691-000	NO			1-1193183-3, 222D263-3- 03/86-0			
510141-000	NO			1194010-7, 222A111-3/86-0			
544121-000	NO			2-1194268-4, 234A621-3- 03/42-0			
559237-000	NO			5-1194414-3, 342A024-3-0- CS5666			
564255N001	NO			2-1194457-7, 202A312-3- 10/42-0-CS6687			
575934-000	NO			1-1194570-8, 202D921-3/86-0			
629224-000	NO			8-1200836-1, CES-2A-D1			
663825N002	NO			6-1195231-2, 202D121-3-60-0- CS5077			
697689-000	NO			8-1195475-5, 202A333-3-0- CS5847			
715055-000	NO			8-1195595-2, 202K132-3- 01/86-0			
742955-000	NO			1195797-6, 222A152-3-0- CS6634			
751843-001	NO			3-1195862-7, CES-3A-F1			
796081-000	NO			3-1196162-7, 202D221-3/180- 0			
806352N001	NO			1196235-3, 202D163-3-60-0- CS5503			
806374N002	NO			5-1196235-0, 202D132-3-60-0- CS5503			
806534N001	NO			2-1196238-3, 222D163-3-60-0- CS5078			
807708N001	NO			7-1196261-7, 222D121-3-60-0- CS5078			
808167-000	NO			1196270-3, 222D921-3-0			
808284N003	NO			2-1196272-0, 222D221-3-0- CS5429			
808286N001	NO			3-1196272-4, 222D242-3-0- CS5429			
808396-000	NO			6-1196274-3, 222D211-3-0			
809061N001	NO			6-1196285-0, 202D121-3-60-0- CS5503			
812836-000	NO			4-1196323-1, 222K121-3-0			
812841-000	NO			5-1196323-3, 202K132-3-0			
812842-000	NO			6-1196323-1, 202K153-3-0			
812843-000	NO			6-1196323-8, 222K142-3-0			
812846-000	NO			7-1196323-8, 222K152-3-0			
812860-000	NO			9-1196323-1, 202K163-3-0			
812996-000	NO			8-1196324-3, 202K142-3-0			
812997-000	NO			9-1196324-3, 42FLS202K121-3- M, 202K121-3-0			
813788-000	NO			1196332-6, 202A142-3-0			
813848-000	NO			5-1196332-0, 202A132-3-0			
813848N008	NO			4-1201164-3, 202A132-3-0- CS6634			
813856-000	NO			7-1196332-1, 222A163-3-0			
814300-000	NO			8-1196337-7, 202A174-3-0			
814308-000	NO			1-1196338-0, 202A111-3-0			
814310-000	NO			2-1196338-1, 234A121-3-0			
814316-000	NO		SS7073-0201	2-1196338-9, 202A121-3-0			
814321-000	NO			4-1196338-5, 234A632-3-0			
814409-000	NO			8-1196340-1, 214A011-3-0			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
814439-000	NO			3-1196341-2, 214A021-3-0			
814458-000	NO			9-1196341-3, 234A011-3-0			
814511-000	NO			7-1196342-0, 222A121-3-0			
814678-000	NO			8-1196345-3, 403A134-3-0			
814728-000	NO			1196347-4, 202A142-3/42-0			
814777-000	NO			1196348-6, 202A111-3/42-0			
820034N001	NO			3-1196390-9, 202D142-3-60/42-0-CS5077			
820672-000	NO			2-1196399-0, 222K142-3/42-0			
822283-000	NO			7-1196412-4, 204K012-3-0			
822521-000	NO			7-1196414-0, 202K121-3-01-0			
822596-000	NO			2-1196416-7, 202K142-3/42-0			
822747-000	NO			8-1196417-6, 222K174-3-0			
822799-000	NO			3-1196418-6, 202K232-3-01-0			
822840-000	NO			6-1196418-5, 222K132-3-0			
822841-000	NO			7-1196418-6, 222K163-3-0			
823184-000	NO			5-1196422-0, 382A023-3-00-0			
823211-000	NO			1196423-4, 301A011-3-0			
823363N004	NO			8-1196426-3, 322A514-3-0-CS5425			
823370-000	NO			1196427-8, 462A214-3-0			
823563-000	NO			2-1196429-2, 323A222-3-0			
823757-000	NO			4-1196432-8, 342A012-3-0			
823774-000	NO			1-1196433-8, 462A023-3-0			
823776-000	NO			2-1196433-6, 382A012-3-0			
827807N002	NO			1196465-8, 202D221-3-61-0-CS5077			
843031-000	NO			1196576-4, 101A011-3-0			
843107N001	NO		ST5M1237-001	8-1196576-9, 102A911-3/42-8-CS5182			
843187N001	NO			4-1196577-3, 102A961-3/42-8-CS5500			
843921-000	NO			9-1196583-5, 202K174-3-0			
856497-001	NO			7-1196675-0, CES-3A-T1			
901307-000	NO			6-1197005-7, 234A752-3-02/42-0			
923793-000	NO			5-1197166-5, 234A721-3-02/42-0			
936829-000	NO			6-1197257-0, 462A011-3/86-0			
A50759-001	NO			1-1201719-7, CES-2R			
C21703N001	NO			7-1201572-9, 101A041-3-06-0-CS5504			
CC3674-000	NO			234A142-3-00-0			
CL9153-000	NO			222D242-3-21/42-0			
CL9429-000	NO			"CES-5-T4"			
CM2767-000	NO			"222D211-3-0-CS8912"			
CP5629-000	NO			222D921-3-27/42-0			
D24840-000	NO			1-1200792-7, CES-4S			
E84696-001	NO			8-1201236-0, CES-2-D1			