



Product Change Notification

Current Date: 09-Oct-2026

TE Connectivity

Product Change Notification: P-26-031534

PCN Date: 22-SEP-26

Customer: TTI Inc (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AFFECTS USA CUSTOMERS - Distribution Center change from Tullahoma, TN to El Paso, TX

Description of Changes

This is a notification only that our current shipping location will change as described. Current location: TE Connectivity Corporation, Customer Fulfillment Center (CFC), 67 Murray Drive, Tullahoma, Tennessee, 37388 USA (DUNS 11-884-4485). New location: TE Connectivity Corporation, TE Global Logistics Organization (GLOG) / El Paso Distribution Center (EPDC), 1740 Joe Battle Blvd., Bldg. 3, El Paso, Texas 79936 USA (DUNS Code: 11-917-1131). The GLOG/EPDC organization in El Paso is expected to begin supporting CFC distribution operations in November 2026 and begin shipping directly to customers in February 2027. The closure of the CFC will take place in stages, with activities being phased out over time. Full CFC closure is currently planned for the end of February 2027. No fit/form/function change, No manufacturing location change, No materials change related to this notification. See attached Customer Letter.

Other attachments:

[Customer Letter](#)

Reason for Changes:

Part status change. Dear Customer, we hereby inform you about the distribution center change utilizing the existing TE Global Logistics Organization allowing for economies of scale and streamline our fulfillment processes, enhancing ICT's operational efficiency and sustainability. In parallel, an optimized distribution network will create a more seamless experience for both TE and our customers, enabling ICT to respond more effectively to current and future market demands and growth opportunities.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

30-NOV-2026

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

28-FEB-2027

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0413-214-1205	NO			"ZPF000000000131736"			
0460-010-20141	NO			"ZPF000000000167816"			
0460-202-1631	NO			"ZPF000000000133619", "0460-202-1631-AS", "0460-202-1631-MS", "\$0460-202-1631"			
0460-215-1631	NO			"ZPF000000000131868"			
0460-241-16141	NO			"ZPF000000000131872"			
0462-201-2031	NO			"ZPF000000000131890", "0462-201-2031-AS", "499002"			
0462-210-1231	NO			"ZPF000000000131885", "0462-210-1231-MS", "0462-210-1231-M", "2-1899848-1"			
0528-002-6005	NO			"ZPF000000000131514", "0528-002-6005-LD", "0528-002-6005-LS", "5-1899776-5", "0528-002-6005-L"			
1-1564532-1	NO						
1-1670901-1	NO						
1-776267-1	NO						
1-776280-1	NO						
1010-066-0406	NO			"ZPF000000000131818"			
1011-227-0205	NO			"ZPF000000000131515", "8202608536"			
1011-231-0305	NO			"ZPF000000000137959"			
1011-237-0405	NO			"ZPF000000000131525"			
1011-240-0605	NO			"ZPF000000000131528"			
1011-248-1205	NO			"ZPF000000000131536"			
1011-256-0205	NO			"ZPF000000000131539"			
1011-259-0305	NO			"ZPF000000000131542"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1011-261-0305	NO			"ZPF000000000131544", "73000930-F"			
1011-263-0405	NO			"ZPF000000000131546"			
1011-267-0605	NO			"ZPF000000000131550"			
1011-273-0205	NO						
1011-344-0205	NO			"ZPF000000000146861", "1011-344-0205-MS", "1011-344-0205-M"			
1011-349-1205	NO						
1027-001-0800	NO			"ZPF000000000131778"			
1027-014-0800	NO			"ZPF000000000131775"			
1028-043-1205	NO						
1060-16-0144	NO			"ZPF000000000131903", "1060-16-0144-LS", "1060-16-0144-L"			
1060-16-1222	NO			"ZPF000000000131912", "2113497-1", "61.309.00"			
1062-12-0222	NO			"ZPF000000000131922"			
1062-16-0144	NO			"ZPF000000000131934", "1062-16-0144-LS", "1062-16-0144-SC", "1062-16-0144-S", "1062-16-0144-L"			
1062-16-1222	NO			"ZPF000000000131944", "1062-16-1222SAMPLE", "1949119-3"			
1062-20-0122	NO			"ZPF000000000131949", "1062-20-0122-AS", "1062-20-0122-LS", "1062-20-0122-MS", "1062-20-0122SAMPLE", "1062-20-0122-SC", "1062-20-0122-E", "1062-20-0122-S", "1062-20-0122-L", "1062-20-0122-M"			
1062-20-0144	NO			"ZPF000000000131951", "1062-20-0144-AS", "1062-20-0144-LD", "1062-20-0144-LS", "1062-20-0144-MS", "\$1062-20-0144", "1062-20-0144-L", "1062-20-0144-M", "7-1899794-7"			
114017-ZZ	NO			"114017", "114017-AS", "114017-LD", "114017-LS", "114017-MS", "11814", "\$114017", "114017-ZZ-E", "114017-E", "114017-L", "114017-A", "114017-B", "114017-M", "8B.118.00"			
1241414-1	NO						
1241416-1	NO						
1326160-2	NO						
1670144-1	NO						
1670146-1	NO						
1670364-1	NO						
2-1563759-1	NO						
2112291-1	NO						
2112293-1	NO						
2112303-1	NO						
2292937-1	NO						
2411-002-1805	NO			"ZPF000000000137751", "2411-002-1805-AS", "21670"			
2414-002-1886	NO			"ZPF000000000137753", "2414-002-1886-AS", "60974"			
2428-008-2405	NO			"ZPF000000000131576", "2428-008-2405-AS", "2428-008-2405-LD", "2428-008-2405-MS", "2428-008-2405-L", "2428-008-2405-M"			
2428-011-2405	NO						
4-1437284-3	NO			"3400130"			
5960-203-04141	NO						
5962-203-04141	NO						
776364-1	NO						
776455-1	NO						
776522-3	NO			"AS16-ST-06-02SC-E"			
776533-1	NO			"AS16-ST-06-12SA-E"			
927770-3	NO						
964972-1	NO						
967652-1	NO						
DRB102-BT	NO						
DRC12-70PA	NO			"ZPF000000000131393", "ZPF000000000146160", "DRC12-70PA-LD", "DRC12-70PA-LS", "DRC12-70PA-			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				MS", "DRC12-70PA-E", "DRC12-70PA-M", "DRC12-70PA-L"			
DRC40-BT	NO						
DT04-08PA	NO			"6-1899776-1"			
DT04-08PB	NO						
DT06-08SB-P012	NO						
DT06-12SC-EP06	NO						
DT06-12SC-P012	NO						
DT06-2S-CE01	NO						
DT06-2S-CE04	NO			"8202614114"			
DT06-2S-CE05	NO						
DT06-2S-CE06	NO			"ZPF000000000140939", "820P-37546"			
DT06-2S-CE13	NO						
DT06-3S-CE01	NO						
DT06-3S-CE04	NO						
DT06-3S-CE06	NO						
DT06-3S-CE13	NO						
DT06-3S-P006	NO			"6-1899776-0"			
DT06-6S-C015	NO						
DT06-6S-CE01	NO						
DT06-6S-CE05	NO						
DT06-6S-CE06	NO						
DT12S-BT	NO						
DT15-12PA	NO						
DT15-2P	NO						
DT15-4P	NO						
DT15-6P	NO						
DT16-18SA-K004	NO						
DT2S-BT-BK	NO						
DT8S-BT	NO						
DTHD04-1-8P	NO			"ZPF000000000130113", "DTHD04-1-8P-AS", "DTHD04-1-8P-LS", "DTHD04-1-8P-L"			
DTM04-12PA	NO			"ZPF000000000130567", "DTM04-12PA-LS", "DTM04-12PA-L"			
DTM04-12PB	NO			"ZPF000000000130571", "DTM04-12PB-AS", "DTM04-12PB-SC", "DTM04-12PB-S"			
DTM04-2P	NO			"ZPF000000000130131", "DTM04-2P-AS", "DTM04-2P-LS", "DTM04-2P-L"			
DTM04-3P	NO			"ZPF000000000130198", "DTM04-3P-LD", "DTM04-3P-LS", "DTM04-3P-L"			
DTM04-4P	NO			"ZPF000000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			
DTM04-6P	NO			"ZPF000000000130335", "DTM04-6P-LD", "DTM04-6P-LS", "DTM04-6P-L"			
DTM06-08SA	NO			"ZPF000000000130399", "DTM06-08SA-AS"			
DTM06-12SA-E003	NO			"ZPF000000000130576", "DTM06-12SA-E003-RU"			
DTM06-12SA-E007	NO			"ZPF000000000130577"			
DTM06-2S	NO			"ZPF000000000130139", "DTM06-2S-LS", "DTM06-2S-L", "8202609944"			
DTM12P-BT-BK	NO						
DTM13-12PA	NO			"ZPF000000000130584"			
DTM13-12PA-R008	NO			"ZPF000000000139426"			
DTM1312PA12PBR008	NO			1899781-5, DTM13-12PA-12PB-R008			
DTMH04-2PB	NO						
DTP04-2P	NO			"ZPF000000000130147", "DTP04-2P-AS", "DTP04-2P-LS", "DTP04-2P-L"			
DTP04-4P	NO			"ZPF000000000130270", "DTP04-4P-AS", "DTP04-4P-SC", "DTP04-4P-S"			
DTP06-2S	NO			"ZPF000000000130150", "DTP06-2S-AS", "DTP06-2S-LS", "ZPF000000000140916"			
DTP2S-BT	NO						
DTP4S-BT	NO						
HD10-3-96P	NO			"ZPF000000000130253"			
HD10-5-16P	NO			"ZPF000000000130329"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
HD16-3-96S	NO			"ZPF000000000130257", "HD16-3-96S-MS", "HD16-3-96S-M"			
HD18-009	NO			"ZPF000000000131684", "HD18-009-AS"			
HD30-24BT	NO						
HD30-24BT-BK	NO			"51.029.00"			
HD34-24-31PE	NO			"ZPF000000000131161", "HD34-24-31PE-LD", "HD34-24-31PE-LS", "\$\$HD34-24-31PE", "HD34-24-31PE-L"			
HDC16-9-E004	NO			"ZPF000000000131712"			
HDC26-18	NO						
HDC34-18	NO			"ZPF000000000131723", "\$\$HDC34-18"			
HDC34-24	NO			"ZPF000000000131728", "\$\$HDC34-24", "8B.102.00"			
HDC36-24	NO			"ZPF000000000131726"			
HDP24-24-19PE	NO			"ZPF000000000130850", "HDP24-24-19PE-LS", "HDP24-24-19PE-MS", "HDP24-24-19PE-L", "HDP24-24-19PE-M"			
HDP24-24-9PE	NO			"ZPF000000000133674", "HDP24-24-9PE-AS"			
HDP26-24-31PE	NO			"ZPF000000000131149", "HDP26-24-31PE-LS", "\$\$HDP26-24-31PE", "HDP26-24-31PE-L"			
HDP26-24-31PT	NO			"ZPF000000000131152", "HDP26-24-31PT-LD", "HDP26-24-31PT-MS", "HDP26-24-31PT-L", "HDP26-24-31PT-M"			
HDP26-24-31SE	NO			"ZPF000000000131155", "HDP26-24-31SE-AS", "HDP26-24-31SE-LS", "HDP26-24-31SE-MS", "\$\$HDP26-24-31SE", "HDP26-24-31SE-L", "HDP26-24-31SE-M"			
M902-2041	NO						
M902-2042	NO						
M902-2053	NO						
M902-2054	NO						
M902-2243	NO						
M902-2244	NO						
WP-4P	NO			"ZPF000000000131484"			
WP-4S	NO			"ZPF000000000131485", "WP-4S-LD", "WP-4S-LS", "WP-4S-L"			
WV-18P	NO			"ZPF000000000131486"			



Product Change Notification

Current Date: 09-Oct-2026

TE Connectivity

Product Change Notification: P-26-031534

PCN Date: 22-SEP-26

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AFFECTS USA CUSTOMERS - Distribution Center change from Tullahoma, TN to El Paso, TX

Description of Changes

This is a notification only that our current shipping location will change as described. Current location: TE Connectivity Corporation, Customer Fulfillment Center (CFC), 67 Murray Drive, Tullahoma, Tennessee, 37388 USA (DUNS 11-884-4485). New location: TE Connectivity Corporation, TE Global Logistics Organization (GLOG) / El Paso Distribution Center (EPDC), 1740 Joe Battle Blvd., Bldg. 3, El Paso, Texas 79936 USA (DUNS Code: 11-917-1131). The GLOG/EPDC organization in El Paso is expected to begin supporting CFC distribution operations in November 2026 and begin shipping directly to customers in February 2027. The closure of the CFC will take place in stages, with activities being phased out over time. Full CFC closure is currently planned for the end of February 2027. No fit/form/function change, No manufacturing location change, No materials change related to this notification. See attached Customer Letter.

Other attachments:

[Customer Letter](#)

Reason for Changes:

Part status change. Dear Customer, we hereby inform you about the distribution center change utilizing the existing TE Global Logistics Organization allowing for economies of scale and streamline our fulfillment processes, enhancing ICT's operational efficiency and sustainability. In parallel, an optimized distribution network will create a more seamless experience for both TE and our customers, enabling ICT to respond more effectively to current and future market demands and growth opportunities.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

30-NOV-2026

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

28-FEB-2027

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0413-214-1205	NO			"ZPF000000000131736"			
0460-010-20141	NO			"ZPF000000000167816"			
0460-202-1631	NO			"ZPF000000000133619", "0460-202-1631-AS", "0460-202-1631-MS", "\$0460-202-1631"			
0460-215-1631	NO			"ZPF000000000131868"			
0460-241-16141	NO			"ZPF000000000131872"			
0462-201-2031	NO			"ZPF000000000131890", "0462-201-2031-AS", "499002"			
0462-210-1231	NO			"ZPF000000000131885", "0462-210-1231-MS", "0462-210-1231-M", "2-1899848-1"			
0528-002-6005	NO			"ZPF000000000131514", "0528-002-6005-LD", "0528-002-6005-LS", "5-1899776-5", "0528-002-6005-L"			
1-1564532-1	NO						
1-776267-1	NO						
1-776280-1	NO						
1010-066-0406	NO			"ZPF000000000131818"			
1011-227-0205	NO			"ZPF000000000131515", "8202608536"			
1011-231-0305	NO			"ZPF000000000137959"			
1011-237-0405	NO			"ZPF000000000131525"			
1011-240-0605	NO			"ZPF000000000131528"			
1011-248-1205	NO			"ZPF000000000131536"			
1011-259-0305	NO			"ZPF000000000131542"			
1011-261-0305	NO			"ZPF000000000131544", "73000930-F"			
1011-263-0405	NO			"ZPF000000000131546"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1011-267-0605	NO			"ZPF000000000131550"			
1011-273-0205	NO						
1011-344-0205	NO			"ZPF000000000146861", "1011-344-0205-MS", "1011-344-0205-M"			
1011-349-1205	NO						
1027-001-0800	NO			"ZPF000000000131778"			
1027-014-0800	NO			"ZPF000000000131775"			
1028-043-1205	NO						
1060-16-0144	NO			"ZPF000000000131903", "1060-16-0144-LS", "1060-16-0144-L"			
1060-16-1222	NO			"ZPF000000000131912", "2113497-1", "61.309.00"			
1062-12-0222	NO			"ZPF000000000131922"			
1062-16-0144	NO			"ZPF000000000131934", "1062-16-0144-LS", "1062-16-0144-SC", "1062-16-0144-S", "1062-16-0144-L"			
1062-16-1222	NO			"ZPF000000000131944", "1062-16-1222SAMPLE", "1949119-3"			
1062-20-0122	NO			"ZPF000000000131949", "1062-20-0122-AS", "1062-20-0122-LS", "1062-20-0122-MS", "1062-20-0122SAMPLE", "1062-20-0122-SC", "1062-20-0122-E", "1062-20-0122-S", "1062-20-0122-L", "1062-20-0122-M"			
1062-20-0144	NO			"ZPF000000000131951", "1062-20-0144-AS", "1062-20-0144-LD", "1062-20-0144-LS", "1062-20-0144-MS", "\$1062-20-0144", "1062-20-0144-L", "1062-20-0144-M", "7-1899794-7"			
114017-ZZ	NO			"114017", "114017-AS", "114017-LD", "114017-LS", "114017-MS", "11814", "\$114017", "114017-ZZ-E", "114017-E", "114017-L", "114017-A", "114017-B", "114017-M", "8B.118.00"			
1241416-1	NO						
1326160-2	NO						
1670144-1	NO						
1670146-1	NO						
1670364-1	NO						
2-1563759-1	NO						
2112291-1	NO						
2112293-1	NO						
2112303-1	NO						
2292937-1	NO						
2411-002-1805	NO			"ZPF000000000137751", "2411-002-1805-AS", "21670"			
2414-002-1886	NO			"ZPF000000000137753", "2414-002-1886-AS", "60974"			
2428-008-2405	NO			"ZPF000000000131576", "2428-008-2405-AS", "2428-008-2405-LD", "2428-008-2405-MS", "2428-008-2405-L", "2428-008-2405-M"			
2428-011-2405	NO						
4-1437284-3	NO			"3400130"			
5960-203-04141	NO						
5962-203-04141	NO						
776364-1	NO						
776522-3	NO			"AS16-ST-06-02SC-E"			
776533-1	NO			"AS16-ST-06-12SA-E"			
927770-3	NO						
964972-1	NO						
967652-1	NO						
DRB102-BT	NO						
DRC12-70PA	NO			"ZPF000000000131393", "ZPF000000000146160", "DRC12-70PA-LD", "DRC12-70PA-LS", "DRC12-70PA-MS", "DRC12-70PA-E", "DRC12-70PA-M", "DRC12-70PA-L"			
DRC40-BT	NO						
DT04-08PA	NO			"6-1899776-1"			
DT04-08PB	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DT06-08SB-P012	NO						
DT06-12SC-EP06	NO						
DT06-12SC-P012	NO						
DT06-2S-CE04	NO			"8202614114"			
DT06-2S-CE05	NO						
DT06-2S-CE06	NO			"ZPF000000000140939", "820P-37546"			
DT06-2S-CE13	NO						
DT06-3S-CE01	NO						
DT06-3S-CE04	NO						
DT06-3S-CE06	NO						
DT06-3S-CE13	NO						
DT06-3S-P006	NO			"6-1899776-0"			
DT06-6S-C015	NO						
DT06-6S-CE01	NO						
DT06-6S-CE05	NO						
DT06-6S-CE06	NO						
DT12S-BT	NO						
DT15-12PA	NO						
DT15-2P	NO						
DT15-4P	NO						
DT15-6P	NO						
DT16-18SA-K004	NO						
DT2S-BT-BK	NO						
DT8S-BT	NO						
DTHD04-1-8P	NO			"ZPF000000000130113", "DTHD04-1-8P-AS", "DTHD04-1-8P-LS", "DTHD04-1-8P-L"			
DTM04-12PA	NO			"ZPF000000000130567", "DTM04-12PA-LS", "DTM04-12PA-L"			
DTM04-12PB	NO			"ZPF000000000130571", "DTM04-12PB-AS", "DTM04-12PB-SC", "DTM04-12PB-S"			
DTM04-2P	NO			"ZPF000000000130131", "DTM04-2P-AS", "DTM04-2P-LS", "DTM04-2P-L"			
DTM04-3P	NO			"ZPF000000000130198", "DTM04-3P-LD", "DTM04-3P-LS", "DTM04-3P-L"			
DTM04-4P	NO			"ZPF000000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			
DTM04-6P	NO			"ZPF000000000130335", "DTM04-6P-LD", "DTM04-6P-LS", "DTM04-6P-L"			
DTM06-08SA	NO			"ZPF000000000130399", "DTM06-08SA-AS"			
DTM06-12SA-E003	NO			"ZPF000000000130576", "DTM06-12SA-E003-RU"			
DTM06-12SA-E007	NO			"ZPF000000000130577"			
DTM06-2S	NO		B3-02-00178	"ZPF000000000130139", "DTM06-2S-LS", "DTM06-2S-L", "8202609944"			
DTM12P-BT-BK	NO						
DTM13-12PA	NO			"ZPF000000000130584"			
DTM13-12PA-R008	NO			"ZPF000000000139426"			
DTM1312PA12PBR008	NO			1899781-5, DTM13-12PA-12PB-R008			
DTMH04-2PB	NO						
DTP04-2P	NO			"ZPF000000000130147", "DTP04-2P-AS", "DTP04-2P-LS", "DTP04-2P-L"			
DTP04-4P	NO		B3-02-04839	"ZPF000000000130270", "DTP04-4P-AS", "DTP04-4P-SC", "DTP04-4P-S"			
DTP06-2S	NO			"ZPF000000000130150", "DTP06-2S-AS", "DTP06-2S-LS", "ZPF000000000140916"			
DTP2S-BT	NO						
DTP4S-BT	NO						
HD10-3-96P	NO			"ZPF000000000130253"			
HD10-5-16P	NO			"ZPF000000000130329"			
HD16-3-96S	NO			"ZPF000000000130257", "HD16-3-96S-MS", "HD16-3-96S-M"			
HD18-009	NO			"ZPF000000000131684", "HD18-009-AS"			
HD30-24BT	NO						
HD30-24BT-BK	NO			"51.029.00"			
HD34-24-31PE	NO			"ZPF000000000131161", "HD34-24-31PE-LD", "HD34-24-31PE-LS", "\$\$HD34-24-31PE", "HD34-24-			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				31PE-L"			
HDC16-9-E004	NO			"ZPF000000000131712"			
HDC26-18	NO						
HDC34-18	NO			"ZPF000000000131723", "\$\$HDC34-18"			
HDC34-24	NO			"ZPF000000000131728", "\$\$HDC34-24", "8B.102.00"			
HDC36-24	NO			"ZPF000000000131726"			
HDP24-24-19PE	NO			"ZPF000000000130850", "HDP24-24-19PE-LS", "HDP24-24-19PE-MS", "HDP24-24-19PE-L", "HDP24-24-19PE-M"			
HDP24-24-9PE	NO			"ZPF000000000133674", "HDP24-24-9PE-AS"			
HDP26-24-31PE	NO			"ZPF000000000131149", "HDP26-24-31PE-LS", "\$\$HDP26-24-31PE", "HDP26-24-31PE-L"			
HDP26-24-31PT	NO			"ZPF000000000131152", "HDP26-24-31PT-LD", "HDP26-24-31PT-MS", "HDP26-24-31PT-L", "HDP26-24-31PT-M"			
HDP26-24-31SE	NO			"ZPF000000000131155", "HDP26-24-31SE-AS", "HDP26-24-31SE-LS", "HDP26-24-31SE-MS", "\$\$HDP26-24-31SE", "HDP26-24-31SE-L", "HDP26-24-31SE-M"			
M902-2041	NO						
M902-2042	NO						
M902-2053	NO						
M902-2054	NO						
M902-2243	NO						
M902-2244	NO						
WP-4P	NO		B3-02-04840	"ZPF000000000131484"			
WP-4S	NO			"ZPF000000000131485", "WP-4S-LD", "WP-4S-LS", "WP-4S-L"			
WV-18P	NO			"ZPF000000000131486"			