VISHAY
The DNA of tech.™

Product Information Notification

PIN

Product Group: OPT/Friday October 2, 2026/PIN-OPT-1454-2025-REV-0

Upgrade of VSMY1940ITX01 and VSMY1850ITX01 from MSL4 to MSL3

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas

Vishay Intertechnologies, Inc., Business Marketing The Americas - Opto
2585 Junction Avenue
-
San Jose California United States 95134-1923
Phone: +1-408-567-8358
Fax: +1-408-240-5687
jim.toal@vishay.com

Europe

VISHAY Semiconductor GmbH, Business Marketing Europe - Opto
Theresienstr. 2
-
Heilbronn Germany 74072
Phone: +49-7131-7498-516
Fax: +49-7131-67-3144
boris.lazic@vishay.com

Asia

Vishay Intertechnology Asia Pte Ltd
37A Tampines Street 92 #07-01
-
Singapore Singapore 528886
Phone: +65 6780 7879
Fax: +65 6780 7897
jason.soon@vishay.com

Description of Change: Improved MSL level after further testing

Reason for Change: Improved MSL level after further testing

Expected Influence on Quality/Reliability/Performance: No influence on quality and reliability expected. The customer is asked to test in its application.

Part Numbers/Series/Families Affected: VSMY1940ITX01, VSMY1850ITX01,

Vishay Brand(S): Vishay Semiconductors

Time Schedule:

Start Shipment Date: Sunday January 10, 2027

Sample Availability: Immediately

Product Identification: Date Code

Qualification Data: available upon request

Issued By: Sebastian Riester, sebastian.riester@vishay.com

© 2021 VISHAY INTERTECHNOLOGY, INC. ALL RIGHTS RESERVED.

THIS DOCUMENT IS SUBJECT TO CHANGE WITHOUT NOTICE. THE PRODUCTS DESCRIBED HEREIN AND THIS DOCUMENT ARE SUBJECT TO SPECIFIC DISCLAIMERS, SET FORTH AT www.vishay.com/doc?91000