



PRODUCT CHANGE NOTIFICATION

MAGNETICS



Bourns® RL181S Series Radial Lead RF Chokes

Manufacturing Site Relocation

Riverside, California – January 7, 2026 – In order to support our fast-growing demand, effective March 31, 2026, Bourns will relocate the manufacturing site for the [RL181S Series Radial Lead RF Chokes](#) to a facility with higher production capacity. A list of affected part numbers is included below.

Affected Part Numbers			
RL181S-102J-RC	RL181S-392J-RC	RL181S-153J-RC	RL181S-473J-RC
RL181S-122J-RC	RL181S-472J-RC	RL181S-183J-RC	RL181S-563J-RC
RL181S-152J-RC	RL181S-562J-RC	RL181S-223J-RC	RL181S-683J-RC
RL181S-182J-RC	RL181S-682J-RC	RL181S-273J-RC	RL181S-823J-RC
RL181S-222J-RC	RL181S-822J-RC	RL181S-333J-RC	RL181S-104J-RC
RL181S-272J-RC	RL181S-103J-RC	RL181S-363J-RC	RL181S-124J-RC
RL181S-332J-RC	RL181S-123J-RC	RL181S-393J-RC	RL181S-124H-RC

The form, fit, function, quality, reliability, and country of origin of the affected part numbers will remain the same. The chokes manufactured at the relocated manufacturing site will meet the same data sheet specifications as those manufactured from the existing site. Traceability will be maintained through lot code and date code.

Samples are available upon request. Bourns recommends that customers test the affected part numbers in their specific applications for verification of satisfactory performance.

Implementation dates are as follows:

Date that deliveries of products manufactured at the current manufacturing site will cease: **March 30, 2026**

Date that deliveries of products manufactured at the relocated manufacturing site will begin: **March 31, 2026**

First date code using the above changes: **2614**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.

IC26001