



Customer Product/Process Change Notification

PCN # 131463

Issued Date: 17.Feb.26

Issued By: Pat Lay

Author: Pat Lay

Change affects whole product family?

Yes

Part #'s affected (See attached if entire product family is affected)

1010931, 1010931003, 1010932, 1010932003, 1010933003, 1010934, 1010935003, 1010937, 1010937003, 1010971, 1010971003, 1010972, 1010972003, 1010973, 1010973003, 1010975, 1010975003, 101383009200, 101383009201, 101383009203, 101383009300, 101383009301, 10138300972203, 101463009200, 101503009100, 101503009101, 101503009200, 101503009201, 101503009300, 101503009301, 101503009303, 10150300971203, 101713009200, 101843009200, 101843009201, 101843009203, 10184300931201

Description of Change:

Discontinue parts in series.

Reason for Change:

SKU reduction initiative. Parts have low to no activity in past four years.

Properties of Old vs. Changed Product:

N/A

Disposition of Old Product:

Use stock until depletion.

Expected Implementation Date: Immediate

Customer Feedback Expected by: N/A

Additional Comments: (Include Potential Risks if Appropriate)

Supporting Qualification Data:

Dialight North America

1501 Route 34 South | Farmingdale | New Jersey | 07727 | USA | Tel: 732-919-3119 | www.dialight.com

Affected Part Numbers

PCN # 131463

Part Numbers Affected by the change.

[illegible]

[illegible][illegible]

Key Dates

Effective Date:	17.02.2026
Last Time Buy Date:	N/A
Sample Availability Date:	N/A
Literature Updated:	N/A

Comments