



6th Aug. 2026

To: Valued Customers

From: Littelfuse Product Management

Subject: Additional location of production for certain fuses and fuse holder combinations for assurance of supply

With regards to the above reference, Littelfuse would like to inform you that we would be increasing our production capacity via another plant in Taiwan for assurance of supply for certain fuse+ fuse holder combinations.

There are no changes to the electrical specs as defined in the datasheet,. There are also no changes in the form, fit and function of the fuse and fuse holders.



Please see attached for validation report.

There are 2 differences between the fuse+holder combinations,

1. For fuse ratings with double color code, it is one tubing with color painting for current supply, whereas it is 2 different color tubings for the future supply.
2. For the COO on the fuse, fuse holder and label, it is "MEXICO" for current supply, whereas it is "TW" for the future supply.

Please refer to below for details.

Part Numbers	Current Part	Part from new plant
048107.5HXP 048107.5HXLP 0481010.HXP 0481015.HXP 0481010.HXLP 0481015.HXLP 0481010.VXLP 0481015.VXLP 0481020.H 0481020.HXL 0481020.HXP 0481020.VXL 0481020.VXLP 0481020.HXLP 0481012.HXP	 1 tubing with color painting	 2 different color tubings

All affected part numbers as shown on next page	 COO "MEXICO" on fuse, holder, label	 COO "TW" on fuse, holder, label
--	---	--

There are no changes to the part number.

We would do the running change for shipments from Oct.6th, 2026 in the plant.

Part numbers affected are shown on the next page.

Please let us know should you have further queries.

Best Regards;

Style Liu
Sr. Manager, Product Management
SLiu@Littelfuse.com
Tel - +86 512 67613189-2251

0481002.HXP	04820001ZXBFH
0481003.H	04820001ZXPf
0481003.HXP	04820002ZXBF
0481003.HXLP	04820002ZXB
048107.5HXP	04820003ZXB
0481005.HXP	04820004ZXBF
048107.5HXLP	04820004ZXB
0481005.HXLP	04820005ZXB
0481010.HXP	04820006ZXB
0481012.HXP	04820006ZXBF
0481015.HXP	04820008ZXBF
0481010.HXLP	04820009ZXBF
0481015.HXLP	04820010ZXB
0481010.VXLP	04820010ZXBF
0481015.VXLP	04820010ZXBFH
0481020.H	04820011ZXBF
0481020.HXL	04820012ZXBF
0481020.HXP	04820013ZXBF
0481020.VXL	04820014ZXBF
0481020.VXLP	04820015ZXBF
0481020.HXLP	04820018ZXBF
04822001ZXPf	04820019ZXBF
04822001ZXPfSH	04820020ZXBF
04820001ZXB	04820021ZXBF
04820001ZXBF	