



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631

[www.littelfuse.com](http://www.littelfuse.com)

## Product Discontinuity Notice (PDN)

(03/23/2026)

### EOL of magnetic sensor parts

Dear Valued Customer,

Littelfuse would like to notify you of the obsolescence of magnetic sensors 59150-540 due to product line optimization.

This change will take effect immediately and the last time buy inventory will not be offered.

If you have any additional questions or concerns, pls contact us or your Regional Sales Manager.

Best Regards,  
Julius Venckus  
Global Product Manager – Sensors  
Electronics Business Unit  
Littelfuse Inc.  
E-mail: [jvenckus@littelfuse.com](mailto:jvenckus@littelfuse.com)

Tracy Huang  
Product Manager Asia - Sensors  
Electronics Business Unit  
Littelfuse Inc.  
E-mail: [thuang2@littelfuse.com](mailto:thuang2@littelfuse.com)