

Document Receipt Acknowledgement
Date:
Section:
Name:



Document Number: D08972-A-D7300

Date: Aug. 11, 2025

Attention:

TTI

New Design In Stop Notice

LBBA0ZZ1EK, LBEE5ZZ1FJ, LBAA0ZW1NM, LBEE5HY1MW-174, LBEE5KL1WS,
LBEE5ZZ2AW,
LBEE5PK2BC, LBUA2ZZ2DK, LBWA0ZZ2DS LBEE5HY2DU, CMWC1ZZABR Series

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.

This is the official notification that some of our products detailed below shall be out of sales promotion with the immediate effect.

Please review this, and refrain from designing the products affected into your new models and projects. Your understanding and support are highly appreciated.

1. Product Type, Customer/Murata/Alternative Part Numbers:

(1) LBBA0ZZ1EK Series

(2) LBEE5ZZ1FJ Series

Product Type: (3) LBAA0ZW1NM, LBEE5KL1WS, LBEE5ZZ2AW, LBEE5PK2BC, LBUA2ZZ2DK,
LBWA0ZZ2DS LBEE5HY2DU, CMWC1ZZABR Series

(4) LBEE5HY1MW-174

Please refer to the attached documents for detailed Part Numbers' information.

2. Reasons/Background:

(1) We have been continuously adopted for about 10 years, and we would like to discourage the adoption of new models.

(2) Due To recommend switching to the module adopted in the successor model.

At this time, the EOL schedule has not been confirmed, but we will contact you after confirming future demand and the supply status of parts.

(3) Due to the reduction in requirements, we are planning to withdraw products to improve production efficiency. The specific EOL date has not yet been determined.

(4) To recommend switching to a successor module.

At this time, the EOL schedule has not been confirmed, but we will contact you after confirming future demand and the supply status of parts.

3. Contact Window:

Should you have any questions or concerns, please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.

Connectivity Module Products Dept. / General Manager

Hirokazu Nakae

Parts
LBUA2ZZ2DK-882

Part_Number

LBUA2ZZ2DK-882+UC
LBEE5HY2DU-900+UR
LBEE5ZZ1FJ-957+ZN
LBEE5ZZ2AW-603+UN
CMWC1ZZABR-063+ZC
LBEE5PK2BC-771+UR
CMWC1ZZABR-079+ZC
LBEE5KL1WS-734+UR
LBEE5ZZ1FJ-877+ZN
LBEE5ZZ1FJ-941+ZN
LBAA0ZW1NM-130+UC
CMWC1ZZABR-107+ZC
LBWA0ZZ2DS-688+UC
CMWC1ZZABR-105+ZC
LBUA2ZZ2DK-007+UC
LBEE5ZZ1FJ-889+ZN
LBEE5ZZ1FJ-890+ZN
LBEE5ZZ1FJ-918+ZN
LBEE5HY1MW-174+UR
LBBA0ZZ1EK-849+ZC