

PRODUCT CHANGE NOTIFICATION

Product Category FIBER CONNECTORS 20251112-1

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 12.Nov.25

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☒ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

With the increasing market shift to fusion splicing, all OptiCam kits, connectors, and accessories are now end-of-life. One final production run of OptiCam 2 tool kits will be available beginning in late December 2025. Kits, connectors, and accessories are only available while supplies last. Users should convert to the new OmniSplice fusion-spliced connectors offering, already available for order, for their field termination needs.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2025	11	3
Old product discontinuation date*	2025	11	12

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 CHN-CustomerService@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerService@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

Product Groups

CABLE COPPER, FIBER CABLE AND CONNECTORS

CONVERGED INFRASTRUCTURE

COPPER & NETKEY COPPER, FIBER, CABLE

DATA CENTER SOFTWARE

DC CONNECTIVITY

DUCT AND ABRASION

ID, SAFETY AND ACCESSORIES

IMS SMARTZONE HARDWARE

INDUSTRIALNET COPPER

INDUSTRIALNET FIBER

INDUSTRIALNET OUTLETS

IOT SOFTWARE

IOT SOLUTIONS

MISC

OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT

POWER CONNECTORS, GROUNDING AND STEEL

PRE-CONFIGURED IA

TIES AND TERMINALS

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1
FOCTT2-KIT3	No Replacement	NO-REPLACEMENT
FOCTT2-PKIT3	No Replacement	NO-REPLACEMENT
FCCVR2	No Replacement	NO-REPLACEMENT
FLCC2	No Replacement	NO-REPLACEMENT
FSCC2	No Replacement	NO-REPLACEMENT
FSTC2	No Replacement	NO-REPLACEMENT
FOLPC-1.25SM	No Replacement	NO-REPLACEMENT
FOLPC-1.25MM	No Replacement	NO-REPLACEMENT
FOLPC-2.5SM	No Replacement	NO-REPLACEMENT
FOLPC-2.5MM	No Replacement	NO-REPLACEMENT
FOCTT2CORD	No Replacement	NO-REPLACEMENT
OCTTR1.25SS	No Replacement	NO-REPLACEMENT
OCTTR2.5SS	No Replacement	NO-REPLACEMENT
FJQCVR	No Replacement	NO-REPLACEMENT
FJQCVRB	No Replacement	NO-REPLACEMENT
FLCSMCXAQY	Complex	FSOCLCX
FLCSMCXAQY-C	Complex	FSOCLCX
FLCDMCXAQY	Complex	FSOCLCX
FLCSSCBUY	Complex	FSOCLC9
FLCSSCBUY-C	Complex	FSOCLC9
FLCSMC6BLY	No Replacement	NO-REPLACEMENT
FLCSMC6BLY-C	No Replacement	NO-REPLACEMENT
FLCSMC6EIY	No Replacement	NO-REPLACEMENT
FLCSMC6EIY-C	No Replacement	NO-REPLACEMENT
FLCSMC5BLY	Complex	FSOCLCX
FLCDMC5BLY	Complex	FSOCLCX
FLCSSCAG	Complex	FSOCLCA
FSC2MCXAQ	Complex	FSOCSCX
FSC2MCXAQ-C	Complex	FSOCSCX
FSC2DMCXAQ	Complex	FSOCSCX
FSC2SCBU	Complex	FSOCSC9
FSC2SCBU-C	Complex	FSOCSC9
FSC2DSCBU	Complex	FSOCSC9
FSC2MC6EI	No Replacement	NO-REPLACEMENT
FSC2MC6EI-C	No Replacement	NO-REPLACEMENT
FSC2DMC6EI	No Replacement	NO-REPLACEMENT
FSC2MC5BL	Complex	FSOCSCX
FSC2MC5BL-C	Complex	FSOCSCX
FSC2DMC5BL	Complex	FSOCSCX
FSC2SCAG	Complex	FSOCSCA
FLCC	No Replacement	NO-REPLACEMENT
FSCC	No Replacement	NO-REPLACEMENT
FSTC	No Replacement	NO-REPLACEMENT
OPTICAMCOMP-BAG	No Replacement	NO-REPLACEMENT
FVFLPC-1.25SMY	No Replacement	NO-REPLACEMENT
FVFLPC-2.5SMY	No Replacement	NO-REPLACEMENT
FVFLPCY	No Replacement	NO-REPLACEMENT

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

Replacement Type Definition

DIRECT REPLACEMENT

Exact same part in a different package or form factor. The replacement part has any other update that does not change the function of the product itself

COMPATIBLE

The replacement part is different from the original part but allows it to be used for some applications. The replacement is not the same part. The difference could be in color, size, material, or performance (e.g., CAT5 to CAT6), etc.

COMPLEX

The replacement part(s) are too different from the original part to assume it can easily replace the original part, however Panduit can provide a replacement which may be used in some applications. Customer Experience team should be contacted.

NO REPLACEMENT


NO REPLACEMENT

No replacement product is

package size, or
n't change the

nt in a way that
applications, but
erence can be
ormance (like
c.

o dissimilar to
e discontinued
n offer a
ed in certain
nce should be



available.