

PRODUCT CHANGE NOTIFICATION

Product Category FIBER CASSETTES YYYYMMDD-X

Product Group DC CONNECTIVITY

ISSUE DATE: 07.Jän.26

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☒ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

FHC9N-12C-RCBN will be obsoleted, BN is only available in Multimode. We greatly value and thank you for your ongoing support.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2026	4	7

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 CHN-CustomerService@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerService@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

Product Groups

CABLE COPPER, FIBER CABLE AND CONNECTORS

CONVERGED INFRASTRUCTURE

COPPER & NETKEY COPPER, FIBER, CABLE

DATA CENTER SOFTWARE

DC CONNECTIVITY

DUCT AND ABRASION

ID, SAFETY AND ACCESSORIES

IMS SMARTZONE HARDWARE

INDUSTRIALNET COPPER

INDUSTRIALNET FIBER

INDUSTRIALNET OUTLETS

IOT SOFTWARE

IOT SOLUTIONS

MISC

OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT

POWER CONNECTORS, GROUNDING AND STEEL

PRE-CONFIGURED IA

TIES AND TERMINALS

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

Replacement Type Definition

DIRECT REPLACEMENT

Exact same part in a different package or form factor. The replacement part has any other update that does not change the function of the product itself

COMPATIBLE

The replacement part is different from the original part but allows it to be used for some applications. The replacement part is not the same part. The difference could be in color, size, material, or performance (e.g., CAT5 to CAT6), etc.

COMPLEX

The replacement part(s) are too different from the original part to assume it can easily replace the original part, however Panduit can provide a replacement which may be used in some applications. Customer Experience team should be contacted.

NO REPLACEMENT

NO REPLACEMENT

No replacement product is

package size, or
n't change the

nt in a way that
applications, but
erence can be
ormance (like
c.

o dissimilar to
e discontinued
n offer a
ed in certain
nce should be



available.