

Product discontinuation notification (PDN)

Title / short description Discontinuation of various connectors and headers from the M, L and XL product lines
Affected article category PCB terminal blocks and PCB connectors
Change category Discontinuation
Change number IAA260002-00
Reason for PCN/PDN Revision

Purpose/objective of the change
Discontinuation of the items

Detailed description of the change

As part of our ongoing portfolio optimization, the listed article will be discontinued from our product range. This decision was made after careful evaluation to ensure we continue providing the most innovative and effective solutions.

The discontinued items can be ordered in the usual quantities until distribution capacity comes to an end. Large order to build up inventory must be discussed with the sales team.

Identifying characteristics

Start of Production (SOP)	-	Last Time Delivery (LTD)	2027-07-31
Effective date (EOP)	-	End of Service (EOSR)	-
End of Sales (EOS)	2027-01-31		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PDN-IAA260002-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1012203	BCP-500- 5 BK VPE250				
1013903	BCH-500HS- 5 GN PA1,3,5				
1020215	MSTBTP 2,5/ 3-ST 2CPBD:-A1SO				
1039174	BCH-508HS- 3 GY PA1,3				
1047115	FKC 2,5/ 3-ST-5,08 BKBDWH:48VQ				
1058049	MSTBTP 2,5/ 2-ST-RDB CP1BD14SO				
1058097	TVFKC 1,5/ 2-ST-RDB CP1 BD:S34				
1058098	TVFKC 1,5/ 2-ST-RDB CP12 BDS22				
1058100	TVFKC 1,5/ 2-ST-RDB CP1 BD14SO				
1058102	MSTBTP 2,5/ 2-ST-RDB CP1BDS34				
1058104	MSTBTP 2,5/ 2-ST-RDB CP12BDS22				
1058105	MSTBTP 2,5/ 2-ST-RDB CP2BDS11				
1058106	MSTBTP 2,5/ 2-ST-RDB CP12BDSO				
1064947	BCH-500H- 4 GN VPE500				
1064948	BCP-500- 4 GN VPE500				
1064949	BCH-500H- 5 BK VPE500				
1064950	BCP-500- 5 BK VPE500				
1064951	BCH-500H- 5 GN VPE500				
1065175	BCP-500- 5 GN VPE500				
1068639	MSTB 2,5/18-GF-5,08 ZZP2AN				
1093659	BCP-508-14 GN BD:1-14				
1096124	BCP-508- 8 GN BD:J1-1-J1-8				
1103512	FKCOW 2,5/18-ST-5,08 BD36-19SO				
1104427	BCH-508VS-3 GY VPE500				
1105831	BCP-500-20 GN BD:1-20Q				
1105836	BCP-500F-12 GN BD:1-12Q				
1105837	BCP-500F-14 GN BD:1-14Q				
1105838	BCP-500F-4 GN BD:1-4Q				
1106032	BCP-500F-6 GN BD:1-6Q				
1106340	PC 5/ 6-G-7,62 P26				
1107542	BCH-500H- 3 GN PA1,3				
1108014	IPC 5/ 3-ST-7,62 BD:3-1				
1108073	GIC 2,5 HCV/ 3-ST-7,62BD:3-1				
1110205	IPC 5/ 3-ST-7,62 GY35 BD:6-4				
1110560	PC 5/ 4-ST1-7,62 BD:1-PE				
1135464	TMSTBP 2,5/ 2-STFS59-5,08 AU				
1185850	BCH-508HF- 2 BK BDWH:1-2				
1187909	BCP-500- 2 GN BDWH:NZ				

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1188095	SPTA 1/ 3-5-6 BD SET				
1218753	BCP-508- 3 BK BDWH:NO2-NO1 SO				
1218754	BCP-508- 3 BK BDWH:C6-NO6 SO				
1223442	BCP-508- 3 BK BDWH:0-LSO				
1223443	BCP-508- 3 BK BDWH:0+-				
1245724	BCP-508- 5 GN BDWH:J9				
1245731	BCP-508- 5 GN BDWH:J10				
1252867	LPC 6/ 4-STL4-7,62 BK				
1272161	BCH-500H- 6 GN VPE500				
1340828	BCP-508-10 GY PA1,3,5,7,9,10				
1340834	BCH-508HS-10 GY PA1,3,5,7,9,10				
1340840	BCH-508HF- 8 GY PA1,2,4,5,7,8				
1387888	BCP-508F-18 GN BD:19-36				
1393365	MVSTBR 2,5/12-ST-5,08GYBD2:-7				
1459572	PC 5/ 3-G-7,62 BK CP1				
1459576	PC 5/ 3-G-7,62 BK CP2				
1460426	PC 5/ 6-G-7,62 PIN 3,4				
1515821	BCS-508F- 2 GY				
1515823	BCS-508F- 3 GY				
1515827	BCS-508F- 5 GY				
1515829	BCS-508F- 6 GY				
1515830	BCS-508F- 7 GY				
1515833	BCS-508F- 8 GY				
1515834	BCS-508F- 9 GY				
1515835	BCS-508F-11 GY				
1651803	KGG-MSTB 2,5/ 7 GY				
1665680	FKC 2,5 HC/ 7-ST-5,08BKLCBUBDX				
1700143	MVSTBW 2,5/ 2-STEH KMGY LUB				
1700598	FRONT-MSTB 2,5/12-ST-5,08BD1SO				
1701291	MSTBT 2,5/ 4-ST CP2,3BD:S12SO				
1701293	TVFKCL 1,5/ 4-ST CP2,3BD:S12SO				
1702032	MSTB 2,5/ 3-ST-5,08 OGBDAP SO				
1702452	KGG-MSTB 2,5/ 4 GY				
1702920	MVSTBW 2,5/ 3-ST BK BDWH:+,-				
1703022	FKCN 2,5/ 3-STF-5,08BKBDWH48VD				
1703215	MSTBA 2,5/12-G-5,08 6PA				
1703401	MSTBT 2,5/ 5-ST BD:V-V+				
1703622	TVFKC 1,5/ 4-ST BKCPBDWH24V SO				
1703625	TVFKC 1,5/ 4-STBKCP2,4BDI8-I11				

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1703626	TVFKC 1,5/ 4-ST BKCP1,4BDI4-I7				
1703627	TVFKCL 1,5/ 4-ST BKCPBDT1-T0SO				
1703628	TVFKCL 1,5/ 4-ST BK2PBDI12-I15				
1703642	TVFKCL 1,5/ 4-STBK2CPBDI16-I19				
1703648	TVFKCL 1,5/ 4-ST BK2CPBDA2-SO				
1704668	MSTBT 2,5/ 3-ST CP2 BD:L,LO,N				
1704672	MSTBT 2,5/ 3-ST CP1BD:NI-LO SO				
1704684	TVFKC 1,5/ 3-ST CP2 BD:L,LO,N				
1704685	TVFKC 1,5/ 3-ST CP1BD:NI-LO SO				
1704692	TVFKCL 1,5/ 3-ST CP3 BD:L,NI,N				
1704695	TVFKCL 1,5/ 3-ST CP13BD:-A1 SO				
1704787	MVSTBW 2,5/ 8-ST-5,08 BEIGE				
1705848	MVSTBW 2,5/ 2-ST BD:20,19				
1708190	FKIC 2,5/ 6-STF-5,08 BD:NZ				
1708759	GMSTB 2,5/ 4-ST-7,62 BD:Q1-Q2				
1708887	MSTB 2,5/ 3-ST-5,08 BKBD:4-6				
1708952	MVSTBR 2,5/16-ST-5,08 BU BD:54				
1708956	MDSTBVA 2,5/16-G-5,08 BUBD:M1				
1708958	MDSTBVA 2,5/16-G-5,08 BUBD:M17				
1708959	MDSTBVA 2,5/16-G-5,08 BUBD:M25				
1709672	TVFKC 1,5/ 2-ST CP1BDS34SO				
1710139	MSTB 2,5/ 5-GF-5,08 AU P66				
1711972	MSTBT 2,5/ 3-ST BK2CPBDWHSO				
1711973	MSTBT 2,5/ 3-ST BKCP1BDWHSO				
1711974	MSTBT 2,5/ 3-ST BKCP2BDWH4.1				
1712542	ICV 2,5/ 8-GF-5,08 BG				
1714659	MSTBT 2,5/ 3-ST CP12BD:24VSO				
1714660	MSTBT 2,5/ 3-ST CP13BD:TP3SO				
1714687	MSTBT 2,5/ 2-ST-RDB BD:S22SO				
1715131	MSTBT 2,5/ 2-ST-RDBCP1BD-M1SO				
1715181	TFKC 2,5 HC/ 7-ST-5,08BKLCBUBD				
1715942	TVFKC 1,5/ 2-ST RDB2CP BD:6.1				
1717343	PST 1,3/11-H-5,0				
1717369	PST 1,3/13-H-5,0				
1717385	PST 1,3/15-H-5,0				
1736739	MDSTBV 2,5/ 4-G1				
1737631	MVSTBR 2,5/10-ST-5,08 GY SO1				
1740093	MSTBVA 2,5/ 9-G BK PIN13,9				
1748820	MSTB 2,5 HC/16-ST-5,08				

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1759376	MSTB 2,5/14-STZ				
1759389	MSTB 2,5/15-STZ				
1762453	MSTB 2,5/10-ST-5,08 CP1,10BD2-				
1762466	MSTB 2,5/10-ST-5,08 CP2,9BD1+				
1762884	MDSTBV 2,5/ 6-G1				
1762907	MDSTBV 2,5/ 8-G1				
1762910	MDSTBV 2,5/ 9-G1				
1762949	MDSTBV 2,5/12-G1				
1762981	MDSTBV 2,5/16-G1				
1778292	GMSTB 2,5/ 5-ST-15,24-1				
1778438	GMSTB 2,5/12-ST-15,24-1				
1778496	GMSTB 2,5/ 5-G-15,24-1				
1778535	GMSTB 2,5/ 7-G-15,24-1				
1779006	MSTBT 2,5/ 4-ST CP1,2BD13-43				
1779019	MSTBT 2,5/ 4-ST CP2,3 BD14-44				
1784020	PC 5/ 4-STFL1-7,62 GY NZ X7				
1785036	MDSTB 2,5/18-G-5,08ODKL BS:M-7				
1785638	GMSTBV 2,5/ 8-G-7,62 AU				
1795200	MDSTBVA 2,5/ 4-G-5,08 2CR				
1795213	MDSTBVA 2,5/ 2-G BK 2CR				
1800517	FKCT 2,5/ 6-ST-5,08 BK				
1800953	MSTBV 2,5/ 2-GF BK				
1800958	MSTBV 2,5/ 7-GF BK				
1801164	PCV 4/ 3-G-7,62 BK				
1811747	MDSTB 2,5/15-GF-5,08				
1825018	TVFKC 1,5/ 4-ST CP1,4BD:11-I4				
1825021	TVFKC 1,5/ 4-ST CP1,3BD:S35-A2				
1828138	KGS-MSTBN 2,5/18 GY				
1833657	MSTB 2,5-3HAC OO53-2-SET				
1863547	MSTBA 2,5/ 4-G GY				
1872994	MDSTBW 2,5/12-G-5,08 AU-AH-SE				
1875836	SMSTB 2,5/ 7-ST GY NZ:390451				
1875852	SMSTB 2,5/ 4-ST GY NZ:390457				
1875878	SMSTB 2,5/ 3-ST GY NZ:390461				
1894529	PC 4/ 8-GU-7,62 BK NZ2261				
1902932	GMSTBA 2,5/ 3-G-7,62 BK PIN9,5				
1902974	PC 4/ 5-GU-7,62 BK NZ2291				
1905078	GMSTBAL 2,5/ 3-G-7,62				
1916216	GMSTBA 2,5/ 7-G-15,24 PIN 9,5				

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1918560	MSTB 2,5/ 7-STZF-5,08				
1922323	FRONT-MSTB 2,5/14-STF-5,08 GY				
1926523	PCV 4/ 2-G-7,62 PIN 3,5				
1937156	MSTB 2,5 HC/14-STF-5,08				
1937224	MSTB 2,5 HC/14-ST-5,08				
1950887	ZEC 1,5/ 3-ST-5,0 C3 R1,3				
1965034	MSTB 2,5/18-STZ-5,08				
1965869	MSTBVA 2,5/ 4-G GYBN				
1975969	MVSTBR 2,5/ 5-ST-5,08 BK 1RN L				
1975972	MVSTBR 2,5/11-ST-5,08 BK 1RN L				
5430152	BCP-500- 7 GN BD:20-14 SO				
5430154	BCP-500- 13 GN BD:1-13 SO				
5430167	BCH-500HS- 3 GN BD:12V				
5430168	BCH-500HS- 4 GN BD:-GND				
5430169	BCH-500HS- 4 GN BD:+12VDC-				
5430170	BCH-500HS- 4 GN BD:+5V				
5430171	BCH-500HS- 2 GN BD:+VALVE-				
5430172	BCH-500HS- 2 GN BD:-LED				
5430243	BCP-500- 5 GN BDWH-EX VPE250				
5430262	BCP-381- 2 GN BDWH:TX,2 VPE500				
5430264	BCP-500- 3 GN BDWH:24-0 VPE500				
5430282	BCP-500- 2 GN BDWHL1-L2 VPE500				
5430287	BCP-500-12 GN BDWH:C3-10SO				
5430291	BCP-500-12 GN BDWH:C-RA1SO				
5430305	BCP-500- 2 GN BDWH:-,+SO				
5430306	BCP-500-13 GN BDWH:TS-10SO				
5430307	BCP-500- 3 GN BDWH:ENC1-M1SO				
5430308	BCP-500- 3 GN BDWH:ENC2-M2SO				
5430309	BCP-500- 9 GN BDWH:B2-10SO				
5430310	BCP-500-15 GN BDWH:-10SO				
5430324	BCP-500- 7 GN BDWH:10-C1				
5430329	BCP-500- 7 GN BDWH:1-7				
5430332	BCP-500- 3 GN BDWH:0-26VSO				
5430335	BCP-500-12 GN BDWH:TS-10SO				
5430354	BCP-500- 2 GN BDWH:NZ				
5430362	BCP-508- 3 GN BDWH:J9				
5441090	BCP-508- 8 GY BD:1-8				
5441841	BCVP-500W- 4 BK VPE500				
5454456	BCP-508- 7 BK BDWH NZ				

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
5455332	BCH-508VS- 3 GY 2PA				
5474614	BCP-508- 2 GY VPE500				
5474708	BCP-381- 2 GY VPE500				
5474737	BCH-381V- 3 GY VPE500				
5474740	BCH-508HS- 2 GY VPE500				
5474753	BCP-508- 3 GY VPE500				
5601025	7003931 MSTB 2.5/8-ST-5.08 BLK				
1808996	MSTB 2,5/13-ST-5,08-LR				
1809005	MSTB 2,5/14-ST-5,08-LR				
1809018	MSTB 2,5/15-ST-5,08-LR				
1809021	MSTB 2,5/16-ST-5,08-LR				
1809034	MSTB 2,5/17-ST-5,08-LR				
1793600	DFK-IPCV 35 HC/ 2-GF-15,00				
1793613	DFK-IPCV 35 HC/ 3-GF-15,00				
1793626	DFK-IPCV 35 HC/ 4-GF-15,00				
1793639	DFK-IPCV 35 HC/ 5-GF-15,00				
1793642	DFK-IPCV 35 HC/ 6-GF-15,00				
1975956	MVSTBR 2,5/ 3-ST-5,08 BK 1RN L				

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

1012203;BCP-500- 5 BK VPE500;;;;;27460202;
1013903;BCH-500HS- 5 GN PA1
1020215;MSTBTP 2
1039174;BCH-508HS- 3 GY PA1
1047115;FKC 2
1058049;MSTBTP 2
1058097;TVFKC 1
1058098;TVFKC 1
1058100;TVFKC 1
1058102;MSTBTP 2
1058104;MSTBTP 2
1058105;MSTBTP 2
1058106;MSTBTP 2
1064947;BCH-500H- 4 GN VPE500;;;;;27460201;
1064948;BCP-500- 4 GN VPE500;;;;;27460202;
1064949;BCH-500H- 5 BK VPE500;;;;;27460201;
1064950;BCP-500- 5 BK VPE500;;;;;27460202;
1064951;BCH-500H- 5 GN VPE500;;;;;27460201;
1065175;BCP-500- 5 GN VPE500;;;;;27460202;
1068639;MSTB 2
1093659;BCP-508-14 GN BD:1-14;;;;;27460202;
1096124;BCP-508- 8 GN BD:J1-1-J1-8;;;;;27460202;
1103512;FKCOW 2
1104427;BCH-508VS-3 GY VPE500;;;;;27460201;
1105831;BCP-500-20 GN BD:1-20Q;;;;;27460202;
1105836;BCP-500F-12 GN BD:1-12Q;;;;;27460202;
1105837;BCP-500F-14 GN BD:1-14Q;;;;;27460202;
1105838;BCP-500F-4 GN BD:1-4Q;;;;;27460202;
1106032;BCP-500F-6 GN BD:1-6Q;;;;;27460202;
1106340;PC 5/ 6-G-7
1107542;BCH-500H- 3 GN PA1
1108014;IPC 5/ 3-ST-7
1108073;GIC 2
1110205;IPC 5/ 3-ST-7
1110560;PC 5/ 4-ST1-7
1135464;TMSTBP 2
1185850;BCH-508HF- 2 BK BDWH:1-2;;;;;27460201;
1187909;BCP-500- 2 GN BDWH:NZ;;;;;27460202;
1188095;SPTA 1/ 3-5-6 BD SET;;;;;27440390;
1218753;BCP-508- 3 BK BDWH:NO2-NO1 SO;;;;;27460202;
1218754;BCP-508- 3 BK BDWH:C6-NO6 SO;;;;;27460202;
1223442;BCP-508- 3 BK BDWH:0-LSO;;;;;27460202;
1223443;BCP-508- 3 BK BDWH:0+-;;;;;27460202;
1245724;BCP-508- 5 GN BDWH:J9;;;;;27460202;
1245731;BCP-508- 5 GN BDWH:J10;;;;;27460202;
1252867;LPC 6/ 4-STL4-7
1272161;BCH-500H- 6 GN VPE500;;;;;27460201;

1340828;BCP-508-10 GY PA1
1340834;BCH-508HS-10 GY PA1
1340840;BCH-508HF- 8 GY PA1
1387888;BCP-508F-18 GN BD:19-36;;;;;27460202;
1393365;MVSTBR 2
1459572;PC 5/ 3-G-7
1459576;PC 5/ 3-G-7
1460426;PC 5/ 6-G-7
1515821;BCS-508F- 2 GY;;;;;27460202;
1515823;BCS-508F- 3 GY;;;;;27460202;
1515827;BCS-508F- 5 GY;;;;;27460202;
1515829;BCS-508F- 6 GY;;;;;27460202;
1515830;BCS-508F- 7 GY;;;;;27460202;
1515833;BCS-508F- 8 GY;;;;;27460202;
1515834;BCS-508F- 9 GY;;;;;27460202;
1515835;BCS-508F-11 GY;;;;;27460202;
1651803;KGG-MSTB 2
1665680;FKC 2
1700143;MVSTBW 2
1700598;FRONT-MSTB 2
1701291;MSTBT 2
1701293;TVFKCL 1
1702032;MSTB 2
1702452;KGG-MSTB 2
1702920;MVSTBW 2
1703022;FKCN 2
1703215;MSTBA 2
1703401;MSTBT 2
1703622;TVFKC 1
1703625;TVFKC 1
1703626;TVFKC 1
1703627;TVFKCL 1
1703628;TVFKCL 1
1703642;TVFKCL 1
1703648;TVFKCL 1
1704668;MSTBT 2
1704672;MSTBT 2
1704684;TVFKC 1
1704685;TVFKC 1
1704692;TVFKCL 1
1704695;TVFKCL 1
1704787;MVSTBW 2
1705848;MVSTBW 2
1708190;FKIC 2
1708759;GMSTB 2
1708887;MSTB 2
1708952;MVSTBR 2
1708956;MDSTBVA 2

1708958;MDSTBVA 2
1708959;MDSTBVA 2
1709672;TVFKC 1
1710139;MSTB 2
1711972;MSTBTP 2
1711973;MSTBTP 2
1711974;MSTBTP 2
1712542;ICV 2
1714659;MSTBTP 2
1714660;MSTBTP 2
1714687;MSTBTP 2
1715131;MSTBTP 2
1715181;TFKC 2
1715942;TVFKC 1
1717343;PST 1
1717369;PST 1
1717385;PST 1
1736739;MDSTBV 2
1737631;MVSTBR 2
1740093;MSTBVA 2
1748820;MSTB 2
1759376;MSTB 2
1759389;MSTB 2
1762453;MSTB 2
1762466;MSTB 2
1762884;MDSTBV 2
1762907;MDSTBV 2
1762910;MDSTBV 2
1762949;MDSTBV 2
1762981;MDSTBV 2
1778292;GMSTB 2
1778438;GMSTB 2
1778496;GMSTB 2
1778535;GMSTB 2
1779006;MSTBT 2
1779019;MSTBT 2
1784020;PC 5/ 4-STFL1-7
1785036;MDSTB 2
1785638;GMSTBV 2
1795200;MDSTBVA 2
1795213;MDSTBVA 2
1800517;FKCT 2
1800953;MSTBV 2
1800958;MSTBV 2
1801164;PCV 4/ 3-G-7
1811747;MDSTB 2
1825018;TVFKC 1
1825021;TVFKC 1

1828138;KGS-MSTBN 2
1833657;MSTB 2
1863547;MSTBA 2
1872994;MDSTBW 2
1875836;SMSTB 2
1875852;SMSTB 2
1875878;SMSTB 2
1894529;PC 4/ 8-GU-7
1902932;GMSTBA 2
1902974;PC 4/ 5-GU-7
1905078;GMSTBAL 2
1916216;GMSTBA 2
1918560;MSTB 2
1922323;FRONT-MSTB 2
1926523;PCV 4/ 2-G-7
1937156;MSTB 2
1937224;MSTB 2
1950887;ZEC 1
1965034;MSTB 2
1965869;MSTBVA 2
1975969;MVSTBR 2
1975972;MVSTBR 2
5430152;BCP-500- 7 GN BD:20-14 SO;;;;;27460202;
5430154;BCP-500- 13 GN BD:1-13 SO;;;;;27460202;
5430167;BCH-500HS- 3 GN BD:12V;;;;;27460201;
5430168;BCH-500HS- 4 GN BD:-GND;;;;;27460201;
5430169;BCH-500HS- 4 GN BD:+12VDC;;;;;27460201;
5430170;BCH-500HS- 4 GN BD:+5V;;;;;27460201;
5430171;BCH-500HS- 2 GN BD:+VALVE;;;;;27460201;
5430172;BCH-500HS- 2 GN BD:-LED;;;;;27460201;
5430243;BCP-500- 5 GN BDWH-EX VPE250;;;;;27460202;
5430262;BCP-381- 2 GN BDWH:TX
5430264;BCP-500- 3 GN BDWH:24-0 VPE500;;;;;27460202;
5430282;BCP-500- 2 GN BDWHL1-L2 VPE500;;;;;27460202;
5430287;BCP-500-12 GN BDWH:C3-10SO;;;;;27460202;
5430291;BCP-500-12 GN BDWH:C-RA1SO;;;;;27460202;
5430305;BCP-500- 2 GN BDWH:-
5430306;BCP-500-13 GN BDWH:TS-10SO;;;;;27460202;
5430307;BCP-500- 3 GN BDWH:ENC1-M1SO;;;;;27460202;
5430308;BCP-500- 3 GN BDWH:ENC2-M2SO;;;;;27460202;
5430309;BCP-500- 9 GN BDWH:B2-10SO;;;;;27460202;
5430310;BCP-500-15 GN BDWH:-10SO;;;;;27460202;
5430324;BCP-500- 7 GN BDWH:10-C1;;;;;27460202;
5430329;BCP-500- 7 GN BDWH:1-7;;;;;27460202;
5430332;BCP-500- 3 GN BDWH:0-26VSO;;;;;27460202;
5430335;BCP-500-12 GN BDWH:TS-10SO;;;;;27460202;
5430354;BCP-500- 2 GN BDWH:NZ;;;;;27460202;
5430362;BCP-508- 3 GN BDWH:J9;;;;;27460202;

5441090;BCP-508- 8 GY BD:1-8;;;;;27460202;
5441841;BCVP-500W- 4 BK VPE500;;;;;
5454456;BCP-508- 7 BK BDWH NZ;;;;;27460202;
5455332;BCH-508VS- 3 GY 2PA;;;;;27460201;
5474614;BCP-508- 2 GY VPE500;;;;;27460202;
5474708;BCP-381- 2 GY VPE500;;;;;27460202;
5474737;BCH-381V- 3 GY VPE500;;;;;27460201;
5474740;BCH-508HS- 2 GY VPE500;;;;;27460201;
5474753;BCP-508- 3 GY VPE500;;;;;27460202;
5601025;7003931 MSTB 2.5/8-ST-5.08 BLK;;;;;27460202;
1808996;MSTB 2
1809005;MSTB 2
1809018;MSTB 2
1809021;MSTB 2
1809034;MSTB 2
1793600;DFK-IPCV 35 HC/ 2-GF-15
1793613;DFK-IPCV 35 HC/ 3-GF-15
1793626;DFK-IPCV 35 HC/ 4-GF-15
1793639;DFK-IPCV 35 HC/ 5-GF-15
1793642;DFK-IPCV 35 HC/ 6-GF-15
1975956;MVSTBR 2

3 5;;;;;27460201;

5/ 3-ST 2CPBD:-A1SO;;;;;27460202;

3;;;;;27460201;

5/ 3-ST-5

08 BKBDWH:48VQ;;;;;27460202;

5/ 2-ST-RDB CP1BD14SO;;;;;27460202;

5/ 2-ST-RDB CP1 BD:S34;;;;;27460202;

5/ 2-ST-RDB CP12 BDS22;;;;;27460202;

5/ 2-ST-RDB CP1 BD14SO;;;;;27460202;

5/ 2-ST-RDB CP1BDS34;;;;;27460202;

5/ 2-ST-RDB CP12BDS22;;;;;27460202;

5/ 2-ST-RDB CP2BDS11;;;;;27460202;

5/ 2-ST-RDB CP12BDSO;;;;;27460202;

5/18-GF-5

08 ZP2AN;;;;;27460201;

5/18-ST-5

08 BD36-19SO;;;;;27460202;

62 P26;;;;;27460201;

3;;;;;27460201;

62 BD:3-1;;;;;27460202;

5 HCV/ 3-ST-7

62BD:3-1;;;;;27460202;

62 GY35 BD:6-4;;;;;27460202;

62 BD:1-PE;;;;;27460202;

5/ 2-STFS59-5

08 AU;;;;;27460202;

62 BK;;;;;27460202;

3	5	7 9
3	5	7 9
2	4	5 7

5/12-ST-5	08GYBD2:-7;;;;;27460202;
62 BK CP1;;;;;27460201;	
62 BK CP2;;;;;27460201;	
62 PIN 3	4;;;;;27460201;

5/ 7 GY;;;;;27460291;		
5 HC/ 7-ST-5	08BKLCBUBDX;;;;;27460202;	
5/ 2-STEH KMGY LUB;;;;;27460202;		
5/12-ST-5	08BD1SO;;;;;27460202;	
5/ 4-ST CP2	3BD:S12SO;;;;;27460202;	
5/ 4-ST CP2	3BD:S12SO;;;;;27460202;	
5/ 3-ST-5	08 OGBDAP SO;;;;;27460202;	
5/ 4 GY;;;;;27460402;		
5/ 3-ST BK BDWH:+	-;;;;;27460202;	
5/ 3-STF-5	08BKBDWH48VD;;;;;27460202;	
5/12-G-5	08 6PA;;;;;27460201;	
5/ 5-ST BD:V--V+;;;;;27460202;		
5/ 4-ST BKCPBDWH24V SO;;;;;27460202;		
5/ 4-STBKCP2	4BDI8-I11;;;;;27460202;	
5/ 4-ST BKCP1	4BDI4-I7;;;;;27460202;	
5/ 4-ST BKCPBDT1-T0SO;;;;;27460202;		
5/ 4-ST BK2PBDI12-I15;;;;;27460202;		
5/ 4-STBK2CPBDI16-I19;;;;;27460202;		
5/ 4-ST BK2CPBDA2-SO;;;;;27460202;		
5/ 3-ST CP2 BD:L	LO	N;;;;;27460202;
5/ 3-ST CP1BD:NI-LO SO;;;;;27460202;		
5/ 3-ST CP2 BD:L	LO	N;;;;;27460202;
5/ 3-ST CP1BD:NI-LO SO;;;;;27460202;		
5/ 3-ST CP3 BD:L	NI	N;;;;;27460202;
5/ 3-ST CP13BD:-A1 SO;;;;;27460202;		
5/ 8-ST-5	08 BEIGE;;;;;27460202;	
5/ 2-ST BD:20	19;;;;;27460202;	
5/ 6-STF-5	08 BD:NZ;;;;;27460202;	
5/ 4-ST-7	62 BD:Q1-Q2;;;;;27460202;	
5/ 3-ST-5	08 BKBD:4-6;;;;;27460202;	
5/16-ST-5	08 BU BD:54;;;;;27460202;	
5/16-G-5	08 BUBD:M1;;;;;27460201;	

5/16-G-5	08 BUBD:M17;;;;;27460201;	
5/16-G-5	08 BUBD:M25;;;;;27460201;	
5/ 2-ST CP1BDS34SO;;;;;27460202;		
5/ 5-GF-5	08 AU P66;;;;;27460201;	
5/ 3-ST BK2CPBDWHSO;;;;;27460202;		
5/ 3-ST BKCP1BDWHSO;;;;;27460202;		
5/ 3-ST BKCP2BDWH4.1;;;;;27460202;		
5/ 8-GF-5	08 BG;;;;;27460201;	
5/ 3-ST CP12BD:24VSO;;;;;27460202;		
5/ 3-ST CP13BD:TP3SO;;;;;27460202;		
5/ 2-ST-RDB BD:S22SO;;;;;27460202;		
5/ 2-ST-RDBCP1BD-M1SO;;;;;27460202;		
5 HC/ 7-ST-5	08BKLCBUBD;;;;;27460202;	
5/ 2-ST RDB2CP BD:6.1;;;;;27460202;		
3/11-H-5	0;;;;;27460201;	
3/13-H-5	0;;;;;27460201;	
3/15-H-5	0;;;;;27460201;	
5/ 4-G1;;;;;27460201;		
5/10-ST-5	08 GY SO1;;;;;27460202;	
5/ 9-G BK PIN13	9;;;;;27460201;	
5 HC/16-ST-5	08;;;;;27460202;	
5/14-STZ;;;;;27460202;		
5/15-STZ;;;;;27460202;		
5/10-ST-5	08 CP1	10BD2-;;;;;27460202;
5/10-ST-5	08 CP2	9BD1+;;;;;27460202;
5/ 6-G1;;;;;27460201;		
5/ 8-G1;;;;;27460201;		
5/ 9-G1;;;;;27460201;		
5/12-G1;;;;;27460201;		
5/16-G1;;;;;27460201;		
5/ 5-ST-15	24-1;;;;;27460202;	
5/12-ST-15	24-1;;;;;27460202;	
5/ 5-G-15	24-1;;;;;27460201;	
5/ 7-G-15	24-1;;;;;27460201;	
5/ 4-ST CP1	2BD13-43;;;;;27460202;	
5/ 4-ST CP2	3 BD14-44;;;;;27460202;	
62 GY NZ X7;;;;;27460202;		
5/18-G-5	08ODKL BS:M-7;;;;;27460201;	
5/ 8-G-7	62 AU;;;;;27460201;	
5/ 4-G-5	08 2CR;;;;;27460201;	
5/ 2-G BK 2CR;;;;;27460201;		
5/ 6-ST-5	08 BK;;;;;27460202;	
5/ 2-GF BK;;;;;27460201;		
5/ 7-GF BK;;;;;27460201;		
62 BK;;;;;27460201;		
5/15-GF-5	08;;;;;27460201;	
5/ 4-ST CP1	4BD:l1-l4;;;;;27460202;	
5/ 4-ST CP1	3BD:S35-A2;;;;;27460202;	

5/18 GY,,,,,27440202;		
5-3HAC OO53-2-SET,,,,,27469090;		
5/ 4-G GY,,,,,27460201;		
5/12-G-5	08 AU-AH-SE,,,,,27460201;	
5/ 7-ST GY NZ:390451,,,,,27460202;		
5/ 4-ST GY NZ:390457,,,,,27460202;		
5/ 3-ST GY NZ:390461,,,,,27460202;		
62 BK NZ2261,,,,,27460201;		
5/ 3-G-7	62 BK PIN9	5,,,,,27460201;
62 BK NZ2291,,,,,27460201;		
5/ 3-G-7	62,,,,,27460201;	
5/ 7-G-15	24 PIN 9	5,,,,,27460201;
5/ 7-STZF-5	08,,,,,27460202;	
5/14-STF-5	08 GY,,,,,27460202;	
62 PIN 3	5,,,,,27460201;	
5 HC/14-STF-5	08,,,,,27460202;	
5 HC/14-ST-5	08,,,,,27460202;	
5/ 3-ST-5	0 C3 R1	3,,,,,27460202;
5/18-STZ-5	08,,,,,27460202;	
5/ 4-G GYBN,,,,,27460201;		
5/ 5-ST-5	08 BK 1RN L,,,,,27460202;	
5/11-ST-5	08 BK 1RN L,,,,,27460202;	

2 VPE500,,,,,27460202;

+SO,,,,,27460202;

5/13-ST-5	08-LR,,,,,27460202;
5/14-ST-5	08-LR,,,,,27460202;
5/15-ST-5	08-LR,,,,,27460202;
5/16-ST-5	08-LR,,,,,27460202;
5/17-ST-5	08-LR,,,,,27460202;
00,,,,,27460201;	
00,,,,,27460201;	
00,,,,,27460201;	
00,,,,,27460201;	
00,,,,,27460201;	
5/ 3-ST-5	08 BK 1RN L,,,,,27460202;

10;;;;;27460202;
10;;;;;27460201;
8;;;;;27460201;

PCN/PDN Number	Customer Number	Company Name	Street
IAA260002	401641	TTI, INC.	2441 NORTHEAST PKWY

Postcode/Zip Code	City	Phoenix Contact Item-Nr. (changed/discontinued article)
76106	FORT WORTH	1762949

Phoenix Contact Item Designation (changed/discontinued article)
MDSTBV 2,5/12-G1

Report Date Substitute Item
28.08.2026

Replacement Product Designation