

Product discontinuation notification (PDN)

Title / short description	Discontinuation due to portfolio streamlining
Affected article category	Terminal blocks
Change category	Discontinuation
Change number	IBE250028-01
Reason for PCN/PDN Revision	Article list adjustment (2 products excluded from discontinuation)

Purpose/objective of the change

Discontinuation

Detailed description of the change

Due to a lack of demand, we will discontinue the listed articles.

Identifying characteristics

See attached item list

Start of Production (SOP)	-	Last Time Delivery (LTD)	2027-07-31
Effective date (EOP)	2027-04-30	End of Service (EOSR)	-
End of Sales (EOS)	2027-04-30		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PDN-IBE250028-01_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1043624	RT 5-T BDRD			3049039	RT 5-T
3030118	FBS 2-4 GY			3030116	FBS 2-4
3030131	FBS 3-4 GY			3030129	FBS 3-4
3030134	FBS 4-4 GY			3030132	FBS 4-4
3030147	FBS 5-4 GY			3030145	FBS 5-4
3030160	FBS 10-4 GY			3030158	FBS 10-4
3030354	FBS 20-4 GY			3030352	FBS 20-4
3049518	RTO 3			3049013	RT 3
3049615	RTO 3-PE			3049411	RT 3-PE
3049660	RTO 3 BU			3049110	RT 3 BU
3049767	RTO 5 BU			3049123	RT 5 BU
3049835	RTO 3-TC BU			3049110	RT 3 BU
3049851	RTO 5-TC BU			3049123	RT 5 BU
3049864	RTO 8 BU			3049148	RT 8 BU
3049929	RTO 8-TC BU			3049148	RT 8 BU
3049945	RTO 3-TC			3049013	RT 3
3049958	RTO 3-PE-TC			3049411	RT 3-PE
3049974	RTO 5-PE-TC			3049628	RTO 5-PE
3240065	NS 35/15 ZN UNPERF 3000MM			1206586	NS 35/15 ZN UNPERF 2000MM
3071081	HV M10/1 M6/1-STL2				
1346749	1XM10/1 NFF-2XM6/2-STL NFF SET				
1346748	2XM10/1 NFF-3XM6/2-STL NFF SET				
3002341	RBO 6-WD			1099418	RBO 6-WD-HC
3205200	DS-QTC 1,5			3205190	D-QTC 1,5-TWIN
3206607	DS-QTC 2,5			3206571	D-QTC 2,5-TWIN
1201455	E/U			1201044	E/1
1227418	E/UK-NS 35 GN			1202577	E/UK-NS 35
1030161	RBO 10-WD			3244614	RBO 10
1053781	W-RBO 16				
1170837	RBOC 10/6-TP DGY				
3049025	W-RT 5				
3212840	PH 1,5/S/12				
3212866	PH 1,5/S/14				
3212879	PH 1,5/S/15				
3209772	PH 2,5/11				
3209808	PH 2,5/14				
3050510	D-QTCU 2,5 TWIN				
1172179	NUT WITH WASHER M5 DIN				

Item no.	Item Type	Hardware / Firmware old	new	Item no.	Substitute item Type
1172177	NUT WITH WASHER M6 DIN				
1172181	NUT WITH WASHER M10 DIN				
1172182	NUT WITH WASHER M12 DIN				
1096337	RBO 8 INW			3213137	RBO 8
0790621	OTTA 6-P/P YE			0790404	OTTA 6-P/P

PCN/PDN Number	Customer Number	Company Name	Street	Postcode/Zip Code
IBE250028-01	401641	TTI, INC.	2441 NORTHEAST PKWY	76106

City	Phoenix Contact Item-Nr. (changed/discontinued article)
FORT WORTH	3030118

Phoenix Contact Item Designation (changed/discontinued article)	Report Date	Substitute Item
FBS 2-4 GY	13.08.2026	3030116

Replacement Product Designation

FBS 2-4

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;
1043624;RT 5-T BDRD;;;3049039;RT 5-T;;
3030118;FBS 2-4 GY;;;3030116;FBS 2-4;27250303;
3030131;FBS 3-4 GY;;;3030129;FBS 3-4;27250303;
3030134;FBS 4-4 GY;;;3030132;FBS 4-4;27250303;
3030147;FBS 5-4 GY;;;3030145;FBS 5-4;27250303;
3030160;FBS 10-4 GY;;;3030158;FBS 10-4;27250303;
3030354;FBS 20-4 GY;;;3030352;FBS 20-4;27250303;
3049518;RTO 3;;;3049013;RT 3;27250101;
3049615;RTO 3-PE;;;3049411;RT 3-PE;27250103;
3049660;RTO 3 BU;;;3049110;RT 3 BU;27250101;
3049767;RTO 5 BU;;;3049123;RT 5 BU;27250101;
3049835;RTO 3-TC BU;;;3049110;RT 3 BU;27250101;
3049851;RTO 5-TC BU;;;3049123;RT 5 BU;27250101;
3049864;RTO 8 BU;;;3049148;RT 8 BU;27250101;
3049929;RTO 8-TC BU;;;3049148;RT 8 BU;27250101;
3049945;RTO 3-TC;;;3049013;RT 3;27250101;
3049958;RTO 3-PE-TC;;;3049411;RT 3-PE;27250103;
3049974;RTO 5-PE-TC;;;3049628;RTO 5-PE;27250103;
3240065;NS 35/15 ZN UNPERF 3000MM;;;1206586;NS 35/15 ZN UNPERF 2000MM;27400602;
3071081;HV M10/1 M6/1-STL2;;;;;27141190;
1346749;1XM10/1 NFF-2XM6/2-STL NFF SET;;;;;27250190;
1346748;2XM10/1 NFF-3XM6/2-STL NFF SET;;;;;27250190;
3002341;RBO 6-WD;;;1099418;RBO 6-WD-HC;27250190;
3205200;DS-QTC 1
3206607;DS-QTC 2
1201455;E/U;;;1201044;E/1;27250302;
1227418;E/UK-NS 35 GN;;;1202577;E/UK-NS 35;27250302;
1030161;RBO 10-WD;;;3244614;RBO 10;27250101;
1053781;W-RBO 16;;;;;
1170837;RBOC 10/6-TP DGY;;;;;27460407;
3049025;W-RT 5;;;;;27141190;
3212840;PH 1
3212866;PH 1
3212879;PH 1
3209772;PH 2
3209808;PH 2
3050510;D-QTCU 2
1172179;NUT WITH WASHER M5 DIN;;;;;
1172177;NUT WITH WASHER M6 DIN;;;;;
1172181;NUT WITH WASHER M10 DIN;;;;;
1172182;NUT WITH WASHER M12 DIN;;;;;
1096337;RBO 8 INW;;;3213137;RBO 8;;
0790621;OTTA 6-P/P YE;;;0790404;OTTA 6-P/P;27250101;

5;;;3205190;D-QTC 1 5-TWIN;27250301;
5;;;3206571;D-QTC 2 5-TWIN;27250301;

5/S/12;;;;;27440202;
5/S/14;;;;;27440202;
5/S/15;;;;;27440202;
5/11;;;;;27440202;
5/14;;;;;27440202;
5 TWIN;;;;;27250301;