

## Product discontinuation notification (PDN)

**Title / short description** Product discontinuation  
**Affected article category** HMIs and industrial PCs  
**Change category** Discontinuation  
**Change number** IDR250004\_DRC\_270831-00  
**Reason for PCN/PDN Revision**

---

**Purpose/objective of the change**  
 Discontinuation

### Detailed description of the change

The Cyber Resilience Act (CRA) introduced in the EU increases the cyber security requirements for the HMI product portfolio. For the listed products, a CRA-compliant continuation is economically and technically not possible. Please contact our sales department to coordinate remaining delivery quantities and final orders. As an alternative for the TP 6000 series we recommend our WP 6000 series.

### Identifying characteristics

<b>Start of Production (SOP)</b>	-	<b>Last Time Delivery (LTD)</b>	2027-08-31
<b>Effective date (EOP)</b>	2026-04-30	<b>End of Service (EOSR)</b>	-
<b>End of Sales (EOS)</b>	2027-02-28		

### Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- |   |   |  |
|---|---|--|
| <input type="checkbox"/> Software / Firmware Bugfix | <input type="checkbox"/> Short-term delivery stop by supplier       | <input type="checkbox"/> Short-term recall by supplier |
| <input type="checkbox"/> Force majeure              | <input type="checkbox"/> Product improvement with customer benefits |  |
| <input type="checkbox"/> Others                     |   |  |

---

### Attachments

- Material\_list.csv
- PDN-IDR250004\_DRC\_270831-00\_EN

### Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1190421	TP 6156-WHPS				
1190423	TP 6185-WHPS				
1190424	TP 6215-WHPS				
1189629	TP 6070-WVPS				
1190420	TP 6121-WXPS				
1190417	TP 6101-WXPS				
1046666	BTP 2070W				
1046667	BTP 2102W				
1050387	BTP 2043W				
1060549	BWP 2043W			1911669	BWP 2043-WQPS
1060632	BWP 2070W			1911671	BWP 2070-WSPS
1060630	BWP 2102W			1911672	BWP 2101-WSPS

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

1190421;TP 6156-WHPS;;;;;27330201;

1190423;TP 6185-WHPS;;;;;27330201;

1190424;TP 6215-WHPS;;;;;27330201;

1189629;TP 6070-WVPS;;;;;27330201;

1190420;TP 6121-WXPS;;;;;27330201;

1190417;TP 6101-WXPS;;;;;27330201;

1046666;BTP 2070W;;;;;27330201;

1046667;BTP 2102W;;;;;27330201;

1050387;BTP 2043W;;;;;27330201;

1060549;BWP 2043W;;;1911669;BWP 2043-WQPS;27330201;

1060632;BWP 2070W;;;1911671;BWP 2070-WSPS;27330201;

1060630;BWP 2102W;;;1911672;BWP 2101-WSPS;27330201;

<b>PCN/PDN Number</b>	<b>Customer Number</b>	<b>Company Name</b>	<b>Street</b>
IDR250004_DRC_270831	401641	TTI, INC.	2441 NORTHEAST PKWY
IDR250004_DRC_270831	401641	TTI, INC.	2441 NORTHEAST PKWY

<b>Postcode/Zip Code</b>	<b>City</b>	<b>Phoenix Contact Item-Nr. (changed/discontinued article)</b>
76106	FORT WORTH	1046667
76106	FORT WORTH	1189629

**Phoenix Contact Item Designation (changed/discontinued article)**

BTP 2102W

TP 6070-WVPS

**Report Date    Substitute Item**

08.06.2026

08.06.2026

## Replacement Product Designation