



<b>Date</b>	6/18/2026
<b>PCN No</b>	85-0593
<b>Type of Change</b>	Product Change
<b>Description of Change</b>	Packaging change
<b>Affected Part Numbers</b>	4503161523000060 4503161793000030 4502840243000050 7039275030 4503161523000050 4503161573000040 4503160993000050 4509581523000030 4509391943500030 4509391570300050 4503160993000030 4503161523000020 4503161793000070 7039313630 7094001130 7039330230 4509930983000050 7039306230 4509391943500040 4509930983000070 70392732 4503161573000050 7039291530 4503161573000060 4503160993000030 4503160993000060 4503160993000060 7038698930 7039308530 7094064630 7039336030 4503161523000030 7094084030 70392362 7039275830 70392340 7039330130 7039313430 4509391593000050 4509391943000050 7115142304 4503161793000060 7039838130 7094047730 7039283530 7039275230 4509391573000070 4503161573000180 7094084130 4503161523000020 7039283330 7134976530 4503160993000080 7115142308 4502D20253101219 7115253304