

Amphenol Product Change Notification

PCN#: 113

Customer: All Customers

Amphenol PN See PN'S Listed on Tab 2

Issue Date: 30.06.2026

Detailed description of proposed change(s):

EOL. These parts are being discontinued. We will no longer be carrying this product line once our current stock is depleted.
GP-IE156327SS-XXX GP-
IE515546DS-XXX

Reason for change(s):

These parts are being discontinued effective immediately due to extremely high manufacturing costs associated with the increased pricing of gold and copper as well as high MOQ's imposed by manufacturing. Once our current stock is depleted, we will no longer be offering them. If you are looking for these parts, you may contact the
manufacturer - Amphenol Interconnect Products at www.amphenol-ipc.com.
Sophia Yi (Customer Service Supervisor) - lijuan.yi@amphenol-ipc.com Jonathan
Fedczuk (Product Manager) - jonathan.fedczuk@amphenol-ipc.com The Manufacturing part
number for these assemblies are 56019XXXX (Single Shielded GPIB)
56020XX02 / 51554XXXX (Double Shielded GPIB)

Proposed Implementation date 6/30/26

Prepared by: Bonnie Atkinson

Date: 30.06.2026



GP-IE156327SS-000.3
GP-IE156327SS-000.5
GP-IE156327SS-001
GP-IE156327SS-002
GP-IE156327SS-003
GP-IE156327SS-004
GP-IE156327SS-005
GP-IE156327SS-006
GP-IE156327SS-008
GP-IE515546DS-000.3
GP-IE515546DS-000.5
GP-IE515546DS-001
GP-IE515546DS-002
GP-IE515546DS-003
GP-IE515546DS-004
GP-IE515546DS-005
GP-IE515546DS-006
GP-IE515546DS-008