


Basics

PCN - 26 058

Release Date: April 24 2026

Product Name:	HPL 560	
	MILLIPACS RA RECEPTACLE SIGNAL 5 ROW	
Product Manager:	JIBU BABU	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	Documentation Change	
Change Description:	Shielding pin position corrected in the drawing.	
Reason for Change:	<p>The shield terminal pin positions are shown differently in the customer drawing compared to the actual position in the physical product, viz. HM2R70PA5108--LF</p> 	
Affected Parts:	HM2R70PA5108AALF;HM2R70PA5108ABLF;HM2R70PA5108ADLF;HM2R70PA5108E9LF;HM2R70PA5108N2LF;HM2R70PA5108N9LF	
Effective Date of Change:	May,20 2026	
Last Time Buy Date:	NA	
Earliest Disty Return Date:	NA	
Last Time Shipment Date	NA	
Datasheet Attached?	Yes	
Qual/Test Data Attached?	Yes	
Samples Availability Date:	NA	
Available Alternatives?		
Questions?	<p>Contact your local ACS Representative, or Product Manager</p> <p>JIBU BABU / Product Manager</p> <p>jibu.babu@amphenol-fci.com</p>	

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date
PCN26058	HM2R70PA5108AALF	DOCUMENTATION CHANGE	MAY 20, 2026
PCN26058	HM2R70PA5108ADLF	DOCUMENTATION CHANGE	MAY 20, 2026
PCN26058	HM2R70PA5108E9LF	DOCUMENTATION CHANGE	MAY 20, 2026
PCN26058	HM2R70PA5108N2LF	DOCUMENTATION CHANGE	MAY 20, 2026
PCN26058	HM2R70PA5108N9LF	DOCUMENTATION CHANGE	MAY 20, 2026
Count:	5		

Last Disty Return date	Last Shipment date	Alternative Parts	Product Family
			560-5HRF-MILLIPACS RA RECEPTACLE SIGNA
			560-5HRF-MILLIPACS RA RECEPTACLE SIGNA
			560-5HRF-MILLIPACS RA RECEPTACLE SIGNA
			560-5HRF-MILLIPACS RA RECEPTACLE SIGNA
			560-5HRF-MILLIPACS RA RECEPTACLE SIGNA

Primary MU	Product Manager	Status
4950-49550	JIBU.BABU@AMPHENOL-F	ACTIVE
4950-49550	JIBU.BABU@AMPHENOL-F	ACTIVE
4950-49550	JIBU.BABU@AMPHENOL-F	ACTIVE
4950-49550	JIBU.BABU@AMPHENOL-F	ACTIVE
4950-49550	JIBU.BABU@AMPHENOL-F	SMARTER SERVICE