

Honeywell Announces Obsolescence of IPM Series Particle Sensors

Honeywell is announcing the Obsolescence of the IPM-series particulate matter sensors with no Last-Time-Buy effectively immediately. This announcement represents a full discontinuation of the impacted part numbers.

Please note there is no replacement for the affected SKUs.

AFFECTED PART NUMBERS

The affected part numbers are listed in the Appendix attached hereto.

REGIONS AFFECTED

- ☒ Asia Pacific and India Sub Continent (APAC)
- ☒ Europe, Middle East, Africa (EMEA)
- ☒ Greater China (GrCH)
- ☒ Latin America (LATAM)
- ☒ North America (NA)

Key dates:

- Last Order Date: N/A
- Last Delivery Date: N/A

Pricing for LTB: N/A

Warranty/Remedy

Subject to the following conditions, Honeywell warrants goods of its manufacture as being free of defective materials and faulty workmanship during the applicable warranty period. Honeywell's standard product warranty applies unless agreed to otherwise by Honeywell in writing; please refer to your order acknowledgement or consult your local sales office for specific warranty details. If warranted goods are returned to Honeywell during the period of coverage, Honeywell will repair or replace, at its option, without charge, those items that Honeywell, in its sole discretion, finds defective. Notwithstanding the foregoing, in the event of a product end-of-life or obsolescence, or inability of Honeywell to manufacture or source materials or component parts for a product, for whatever reason, and/or any associated last-time buy in relation to a product (an "Obsolescence"), Honeywell shall engage in commercially reasonable efforts to repair or replace products in accordance with the terms of its standard warranty, but in no event shall it be liable if it is unable to do so due to the Obsolescence. The foregoing is buyer's sole remedy and is in lieu of all other warranties, expressed or implied, including those of merchantability and fitness for a particular purpose. In no event shall Honeywell be liable for consequential, special, or indirect damages.

Thank you for your attention to this matter.

Honeywell Advanced Sensing Technologies

830 E. Arapaho Road, Richardson, TX 75081, 800-537-6945
sensing.honeywell.com

APPENDIX: AFFECTED SKUs

Item

IH-PMC-001 Honeywell Impact, Particulate Matter Sensor

IH-PMC-002 Laster Particulate Matter Sensor, IN&OUT

IHC-PMC-LED-002 PM 2.5 LED Sensor