

Document Receipt Acknowledgement
Date:
Section:
Name:



Document Number: D09069-A-D7300

Date: Sep. 22, 2025

Attention:

TTI

Product Withdrawal Notice

(Product Type)LDM18,LFB21,LFB2H,LFL18,LDC54,LDC85,LFB32,LFB43,LFB55,LFL55,LDB2H,LFH32,LF L15,LFL32,LDC18,LDD21,LDE18,LDJ0Q,LDJ15,LDJ18,LDM15,LDM21,LFB18,LFD15,LFD18,LF D21,LFD2H,LFH18,LFL21,LFP15,LDB18 Series

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.
 This is the official notification that some of our products will be discontinued as detailed below.
 Please review this, and approve in writing by Approval Due Date.
 Also, please place Last Time Buy Order by the Last Time Order Due Date as needed.
 Your understanding and support are highly appreciated.

1. Product Type, Customer/Murata/Alternative Part Numbers:

(Product

Product Ty Type)LDM18,LFB21,LFB2H,LFL18,LDC54,LDC85,LFB32,LFB43,LFB55,LFL55,LDB 2H,LFH32,LFL15,LFL32,LDC18,LDD21,LDE18,LDJ0Q,LDJ15,LDJ18,LDM15,LDM2 1,LFB18,LFD15,LFD18,LFD21,LFD2H,LFH18,LFL21,LFP15,LDB18 Series

Please refer to the attached documents for detailed Part Numbers' information.

2. Reasons/Background:

The affected product is an old product and sales are already on a downward trend.
 Since substitutes for improved characteristics and miniaturization have become mainstream, future growth potential cannot be expected. The equipment is also aging and it is difficult to continue repairs, so we will proceed with the end of the product.

3. Approval Due: **07, 31, 2026**

Please review this, and reply to Sales for this Notice in writing by Due Date.
 In case we do not get any contacts by the Due Date,
 we will assume that this Notice with all its contents has been accepted.

4. Product Withdrawal Schedule:

Last Time Order Due (*): 09. 30, 2026
 Last Shipment Date: 03. 31, 2027

*: Last Time Order is the subject to Minimum Order Quantity and Package Quantity.
 Order Cancel and Product Return can be accepted only in the case of quality issue.
 Please place Last Time Buy Order by the Last Time Order Due Date as needed.
 We cannot receive any orders after Last Time Order Due.

5. Contact Window:

Should you have any questions or concerns,
 please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.

Business Planning Sec 2./Front End Business Planning Dept./Senior Manager

Tomomi Tsunoda



Document Number: D09069-A-D7300

Confirmation Letter

TTI

Murata Manufacturing, Co., Ltd.

Product Withdrawal Confirmation

(Product Type)LDM18,LFB21,LFB2H,LFL18,LDC54,LDC85,LFB32,LFB43,LFB55,
Product Type: LFL55,LDB2H,LFH32,LFL15,LFL32,LDC18,LDD21,LDE18,LDJ0Q,LDJ1
5,LDJ18,LDM15,LDM21,LFB18,LFD15,LFD18,LFD21,LFD2H,LFH18,LF
L21,LFP15,LDB18 Series

Last Time Order Due: 09. 30, 2026

Last Shipment Date: 03. 31, 2027

Product Withdrawal detailed below is

accepted, and we will not place Last Time Order.

accepted, and we will place Last Time Order as below.

Last Time Order Schedule:

Last Shipment Schedule:

Comments, Questions, etc.

Signature

Date: (MM, DD, YYYY)

Title:

Name:

Murata PN	ALT PN
LFB212G45SG8A127	LFB152G45CB2D320,LFB182G45SG9B740
LFB212G45SG8A127	LFB152G45CB2D320,LFB182G45SG9B740
LFB212G45SG8A166	LFB152G45CD5E890,LFB182G45CL3D264
LFB212G45SG8C341	LFB152G45CB2D320,LFB182G45SG9B740
LFB215G12SG8A183	N/A
LFB215G51SG8A132	N/A
LFB2H1G90SG7C257	N/A
LFB2H2G45SG7A134	LFB152G45CB2D320,LFB182G45SG9B740
LFB2H2G45SG7A158	LFB152G45CD5E890,LFB182G45CL3D264
LFB2H2G45SG7A159	LFB152G45CB2D320,LFB182G45SG9B740
LFB2H2G45SG7B793	LFB152G45CB2D320,LFB182G45SG9B740
LFD21829MDPFC270	N/A
LFL18924MTC1A052	N/A
LFB212G45SG8A127	LFB152G45CB2D320,LFB182G45SG9B740
LFB212G45SG8A166	LFB152G45CD5E890,LFB182G45CL3D264
LFB212G45SG8C341	LFB152G45CB2D320,LFB182G45SG9B740
LFB215G12SG8A183	N/A
LFB215G51SG8A132	N/A
LFB2H1G90SG7C257	N/A
LFB2H2G45SG7A134	LFB152G45CB2D320,LFB182G45SG9B740
LFB2H2G45SG7A158	LFB152G45CD5E890,LFB182G45CL3D264
LFB2H2G45SG7A159	LFB152G45CB2D320,LFB182G45SG9B740
LFB2H2G45SG7B793	LFB152G45CB2D320,LFB182G45SG9B740
LFD21829MDPFC270	N/A
LFL18924MTC1A052	N/A

Murata PN	Alternative Murata PN
LDB184G6AAA9A021	
LDB2H2G4407L-140	
LDC181G9803W-565	
LDC54665M03B-203	
LDC85850M14B-101	
LDD211G3203F-591	
LDE18685MABA-587	
LDJ0Q2G4517CN002	LDJ0Q2G4520CL009
LDJ181G4419BFV01	
LDJ18829M24ACV02	
LDM152C4505FC011	
LDM152G4505FC009	
LDM155G4205FC049	
LDM181G9405CC028	
LDM181G9505CCV01	
LDM182G4502XA012	
LDM182G5010CC001	
LDM211G3510BA022	
LDM211G5510FA017	
LDM212G4501CA011	
LFB182G45BG1D108	
LFB182G45BG4D268	
LFB182G45BG7D948	
LFB184G70CT5F019	
LFB185G78SGAB790	
LFB212G44BB1C141	
LFB212G45SG8A127	LFB152G45CB2D320, LFB182G45SG9B740
LFB212G45SG8A143	LFB152G45CB2D320, LFB182G45SG9B740
LFB212G45SG8A166	LFB152G45CD5E890, LFB182G45CL3D264
LFB212G45SG8A215	LFB152G45CB2D320, LFB182G45SG9B740
LFB212G45SG8B742	LFB152G45CB2D320, LFB182G45SG9B740
LFB212G45SG8C341	LFB152G45CB2D320, LFB182G45SG9B740
LFB212G45SG8V166	
LFB212G45SGKD064	
LFB212G49CC4E790	
LFB212G49SG8B830	
LFB213G50SG8E650	
LFB213G60CT4E748	
LFB213G60SG8B831	
LFB214G48SG8C009	
LFB215G12SG8A178	
LFB215G12SG8A183	
LFB215G37SG8A180	
LFB215G37SG8A185	
LFB215G37SGKE206	LFB155G37CB6D835
LFB215G42SG8A300	LFB185G42CGZE130
LFB215G42SGKD065	LFB185G42CGZE130
LFB215G51SG8A132	
LFB215G78SG8A170	
LFB217G10CFHV549	
LFB21913MSG8B814	
LFB2H1G90SG7C257	

LFB2H2G45BB1A243	LFB152G45CB2D320, LFB182G45SG9B740
LFB2H2G45CC1V005	
LFB2H2G45SG7A134	LFB152G45CB2D320, LFB182G45SG9B740
LFB2H2G45SG7A158	LFB152G45CD5E890, LFB182G45CL3D264
LFB2H2G45SG7A159	LFB152G45CB2D320, LFB182G45SG9B740
LFB2H2G45SG7B734	LFB152G45CB2D320, LFB182G45SG9B740
LFB2H2G45SG7B793	LFB152G45CB2D320, LFB182G45SG9B740
LFB2H2G45SG7C093	LFB152G45CB2D320, LFB182G45SG9B740
LFB2H2G45SG7E759	
LFB2H7G45FA3E987	
LFB321G08CM3D619	
LFB321G16CM3D788	
LFB321G16CM3D789	
LFB321G24CM3D621	
LFB321G40CM8R710	
LFB321G48CM3D625	
LFB321G65SB1A411	
LFB321G84CM3D803	
LFB321G90SN1E638	
LFB32350MSC1-772	
LFB32460MSC1A553	
LFB32575MCM8D605	
LFB32775MSC1A630	
LFB32942MCM3D800	
LFB431G88SN1-733	
LFB431G90AJ1-199	
LFB431G95SN1A364	
LFB43243MAB1-554	
LFB43307MMM1D553	
LFB43312MAB1-375	
LFB43718MAL1-916	
LFB55410MAM1A365	
LFD152G45MU4E417	
LFD181G57DPFE635	
LFD181G65MPHE701	
LFD181G79MP8E105	
LFD18433MDPSE938	
LFD18829MMP1E343	
LFD211G34DKDE081	
LFD211G57MEFE897	
LFD211G79DPFE166	
LFD213G50MPME671	
LFD21829MDPFC270	
LFD21829MMJ8D841	
LFD21829MMV3E151	
LFD2H1G11MZ8E739	
LFD2H1G49MZME959	
LFD2H829MMZ3E424	
LFH183G60RB4E608	
LFH185G42RK2E607	LFH0Q5G37RC1D560
LFH321G96RE2D896	
LFH32942MRA1A517	
LFL15445MTC1A227	

LFL15924MTC1A184	LFL15829MTCTE039
LFL181G35TF1D951	LFL181G35TF1D749
LFL181G43TC1A195	
LFL181G44TC1A065	
LFL181G50TC1B738	
LFL181G50TC1B757	
LFL182G45TC1A202	LFL152G45TC1A219, LFL152G45TC7C309
LFL183G55TC2B908	LFL153G60TF1E817
LFL183G60TC2C359	LFL153G60TF1E817
LFL18503MTH2R010	
LFL18628MTCHD452	LFL18628MTC2C221
LFL18885MTC2A109	LFL18829MTCRD627
LFL18924MTC1A052	
LFL211G95TF2D298	LFL151G95TF1E100, LFL151G81TF1E320
LFL212G20TCLD495	
LFL32352MTL2E330	
LFL32810MTB1-755	
LFL32836MTB1-764	
LFL32865MTQ3E075	
LFL32882MTL4D969	
LFL55240MAE6-208	
LFL55254MAE6-360	
LFL55902MAE5-207	
LFP151G9F045E116	
LFP151G9F105E120	