

Product change notification (PCN)

Title / short description	New side label for VAL-SEC
Affected article category	Surge protection and interference filters
Change category	Marking, Characteristics, Documentation
Change number	CCL240020-01
Reason for PCN/PDN Revision	Addition of several FLT-SEC products.

Purpose/objective of the change

The side label has been changed to printing

Detailed description of the change

Addition of the DEKRA on the now printed label

Identifying characteristics

Identified on the printing

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2026-05-18	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|--|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☒ Product improvement with customer benefits | |
| ☒ Others | | |

We will implement this change at short notice so that the benefits of this change can be realized immediately.

Attachments

- Printing old-new.pdf
- Material_list.csv
- PCN-CCL240020-01_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1033786	VAL-SEC-T2-2+F-48DC-FM	04	05	-	-
1033788	VAL-SEC-T2-2+F-120DC-FM	04	05	-	-
1033789	VAL-SEC-T2-2+F-220DC-FM	03	04	-	-
1033790	VAL-SEC-T2-2+F-380DC-FM	03	04	-	-
1052632	VAL-SEC-T2-GDT-400DC-P	01	02	-	-
1052649	VAL-SEC-T2-GDT-800DC-P	01	02	-	-
1076468	VAL-SEC-T2-4+0-440-FM	02	03	-	-
2800557	VAL-SE-CP-1S-350/40	08	09	-	-
2800558	VAL-SE-CP-1S-350/20	08	09	-	-
2800559	VAL-SE-CP-1S-350/8	08	09	-	-
2800560	VAL-SE-CP-3C-350/40	08	09	-	-
2800561	VAL-SE-CP-3C-350/20	08	09	-	-
2800562	VAL-SE-CP-3C-350/8	08	09	-	-
2800563	VAL-SE-CP-3S-350/40	08	09	-	-
2800564	VAL-SE-CP-3S-350/20	08	09	-	-
2800565	VAL-SE-CP-3S-350/8	08	09	-	-
2800566	VAL-SE-CP-350/40-ST	08	09	-	-
2800568	VAL-SE-CP-350/20-ST	08	09	-	-
2800569	VAL-SE-CP-350/8-ST	08	09	-	-
2800590	VAL-SE-CP-N/PE/40-ST	09	10	-	-
2905333	VAL-SEC-T2-1S-350-FM	06	07	-	-
2905337	VAL-SEC-T2-2C-350-FM	05	06	-	-
2905338	VAL-SEC-T2-2S-350-FM	05	06	-	-
2905339	VAL-SEC-T2-3C-350-FM	05	06	-	-
2905340	VAL-SEC-T2-3S-350-FM	06	07	-	-
2905341	VAL-SEC-T2-1S-350	05	06	-	-
2905342	VAL-SEC-T2-2C-350	05	06	-	-
2905343	VAL-SEC-T2-2S-350	05	06	-	-
2905344	VAL-SEC-T2-3C-350	04	05	-	-
2905345	VAL-SEC-T2-3S-350	04	05	-	-
2905346	VAL-SEC-T2-350-P	06	07	-	-
2905348	VAL-SEC-T2-1S-175-FM	04	05	-	-
2905350	VAL-SEC-T2-2C-175-FM	04	05	-	-
2905351	VAL-SEC-T2-2S-175-FM	04	05	-	-
2905353	VAL-SEC-T2-3C-175-FM	04	05	-	-
2905354	VAL-SEC-T2-3S-175-FM	05	06	-	-
2905355	VAL-SEC-T2-175-P	03	04	-	-
2905356	VAL-SEC-T2-N/PE-175-P	03	04	-	-

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
old	new				
2907865	VAL-SEC-T2-2+0-48DC-FM	03	04	-	-
2907874	VAL-SEC-T2-2+0-120DC-FM	04	05	-	-
2907875	VAL-SEC-T2-2+0-220DC-FM	03	04	-	-
2907876	VAL-SEC-T2-2+0-380DC-FM	02	03	-	-
2907877	VAL-SEC-T2-48DC-P	04	05	-	-
2907878	VAL-SEC-T2-120DC-P	05	06	-	-
2907879	VAL-SEC-T2-220DC-P	03	04	-	-
2907880	VAL-SEC-T2-380DC-P	02	03	-	-
2909590	VAL-SEC-T2-3S-350VF-FM	03	04	-	-
2909591	VAL-SEC-T2-3C-350VF-FM	02	03	-	-
2909592	VAL-SEC-T2-1S-350VF-FM	02	03	-	-
2909596	VAL-SEC-T2-350VF-P	01	02	-	-
2909635	VAL-SEC-T2-3S-350/40-FM	03	04	-	-
2909636	VAL-SEC-T2-N/PE-264/40-P	01	02	-	-
2909637	VAL-SEC-T2-3S-350/40	02	03	-	-
2909968	VAL-SEC-T2-3C-440-FM	03	04	-	-
2909969	VAL-SEC-T2-440-P	01	02	-	-
1044386	FLT-SEC-T1+T2-3IT-350/25-FM	00	01		
1044388	FLT-SEC-T1+T2-2IT-350/25-FM	00	01		
1567353	VAL-SEC-T2-2X2+0-48DC-FM	01	02		
2880448	SYS-SET/ 1	14	15		
2880451	SYS-SET/ 2	13	14		
2905465	FLT-SEC-T1+T2-1C-350/25-FM	01	02		
2905466	FLT-SEC-T1+T2-1S-350/25-FM	02	03		
2905467	FLT-SEC-T1+T2-2C-350/25-FM	01	02		
2905468	FLT-SEC-T1+T2-2S-350/25-FM	02	03		
2905469	FLT-SEC-T1+T2-3C-350/25-FM	01	02		
2905470	FLT-SEC-T1+T2-3S-350/25-FM	03	04		

Change of the label

1

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

1033786;VAL-SEC-T2-2+F-48DC-FM;04;05;-;-;27171302;
1033788;VAL-SEC-T2-2+F-120DC-FM;04;05;-;-;27171302;
1033789;VAL-SEC-T2-2+F-220DC-FM;03;04;-;-;27171302;
1033790;VAL-SEC-T2-2+F-380DC-FM;03;04;-;-;27171302;
1052632;VAL-SEC-T2-GDT-400DC-P;01;02;-;-;27171292;
1052649;VAL-SEC-T2-GDT-800DC-P;01;02;-;-;27171292;
1076468;VAL-SEC-T2-4+0-440-FM;02;03;-;-;27171202;
2800557;VAL-SE-CP-1S-350/40;08;09;-;-;27171202;
2800558;VAL-SE-CP-1S-350/20;08;09;-;-;27171202;
2800559;VAL-SE-CP-1S-350/8;08;09;-;-;27171202;
2800560;VAL-SE-CP-3C-350/40;08;09;-;-;27171202;
2800561;VAL-SE-CP-3C-350/20;08;09;-;-;27171202;
2800562;VAL-SE-CP-3C-350/8;08;09;-;-;27171202;
2800563;VAL-SE-CP-3S-350/40;08;09;-;-;27171202;
2800564;VAL-SE-CP-3S-350/20;08;09;-;-;27171202;
2800565;VAL-SE-CP-3S-350/8;08;09;-;-;27171202;
2800566;VAL-SE-CP-350/40-ST;08;09;-;-;27400501;
2800568;VAL-SE-CP-350/20-ST;08;09;-;-;27171292;
2800569;VAL-SE-CP-350/8-ST;08;09;-;-;27400501;
2800590;VAL-SE-CP-N/PE/40-ST;09;10;-;-;27171292;
2905333;VAL-SEC-T2-1S-350-FM;06;07;-;-;27171202;
2905337;VAL-SEC-T2-2C-350-FM;05;06;-;-;27171202;
2905338;VAL-SEC-T2-2S-350-FM;05;06;-;-;27171202;
2905339;VAL-SEC-T2-3C-350-FM;05;06;-;-;27171202;
2905340;VAL-SEC-T2-3S-350-FM;06;07;-;-;27171202;
2905341;VAL-SEC-T2-1S-350;05;06;-;-;27171202;
2905342;VAL-SEC-T2-2C-350;05;06;-;-;27171202;
2905343;VAL-SEC-T2-2S-350;05;06;-;-;27171202;
2905344;VAL-SEC-T2-3C-350;04;05;-;-;27171202;
2905345;VAL-SEC-T2-3S-350;04;05;-;-;27171202;
2905346;VAL-SEC-T2-350-P;06;07;-;-;27171292;
2905348;VAL-SEC-T2-1S-175-FM;04;05;-;-;27171202;
2905350;VAL-SEC-T2-2C-175-FM;04;05;-;-;27171202;
2905351;VAL-SEC-T2-2S-175-FM;04;05;-;-;27171202;
2905353;VAL-SEC-T2-3C-175-FM;04;05;-;-;27171202;
2905354;VAL-SEC-T2-3S-175-FM;05;06;-;-;27171202;
2905355;VAL-SEC-T2-175-P;03;04;-;-;27171292;
2905356;VAL-SEC-T2-N/PE-175-P;03;04;-;-;27171292;
2907865;VAL-SEC-T2-2+0-48DC-FM;03;04;-;-;27171302;
2907874;VAL-SEC-T2-2+0-120DC-FM;04;05;-;-;27171302;
2907875;VAL-SEC-T2-2+0-220DC-FM;03;04;-;-;27171302;
2907876;VAL-SEC-T2-2+0-380DC-FM;02;03;-;-;27171302;
2907877;VAL-SEC-T2-48DC-P;04;05;-;-;27171292;
2907878;VAL-SEC-T2-120DC-P;05;06;-;-;27171292;
2907879;VAL-SEC-T2-220DC-P;03;04;-;-;27171292;
2907880;VAL-SEC-T2-380DC-P;02;03;-;-;27171292;
2909590;VAL-SEC-T2-3S-350VF-FM;03;04;-;-;27171202;
2909591;VAL-SEC-T2-3C-350VF-FM;02;03;-;-;27171202;
2909592;VAL-SEC-T2-1S-350VF-FM;02;03;-;-;27171202;
2909596;VAL-SEC-T2-350VF-P;01;02;-;-;27171292;

2909635;VAL-SEC-T2-3S-350/40-FM;03;04;-;-;27171202;
2909636;VAL-SEC-T2-N/PE-264/40-P;01;02;-;-;27171292;
2909637;VAL-SEC-T2-3S-350/40;02;03;-;-;27171202;
2909968;VAL-SEC-T2-3C-440-FM;03;04;-;-;27171202;
2909969;VAL-SEC-T2-440-P;01;02;-;-;27171292;
1044386;FLT-SEC-T1+T2-3IT-350/25-FM;00;01;;;27171204;
1044388;FLT-SEC-T1+T2-2IT-350/25-FM;00;01;;;27171204;
1567353;VAL-SEC-T2-2X2+0-48DC-FM;01;02;;;27171302;
2880448;SYS-SET/ 1;14;15;;;27171204;
2880451;SYS-SET/ 2;13;14;;;27171204;
2905465;FLT-SEC-T1+T2-1C-350/25-FM;01;02;;;27171204;
2905466;FLT-SEC-T1+T2-1S-350/25-FM;02;03;;;27171204;
2905467;FLT-SEC-T1+T2-2C-350/25-FM;01;02;;;27171204;
2905468;FLT-SEC-T1+T2-2S-350/25-FM;02;03;;;27171204;
2905469;FLT-SEC-T1+T2-3C-350/25-FM;01;02;;;27171204;
2905470;FLT-SEC-T1+T2-3S-350/25-FM;03;04;;;27171204;