

Product change notification (PCN)

Title / short description	Change of mating face and housing screws
Affected article category	Charging technology for electromobility
Change category	Function
Change number	CXW260037-00
Reason for PCN/PDN Revision	

Purpose/objective of the change

Robustness improvement of mating face screw connection

Detailed description of the change

As part of Phoenix Contact's goal of continuous improvement of our products for charging infrastructure, in our CCS2 375A connector product group (CHARX PT2C-DC375...) the screw connection in the area of the mating face is being improved to increase the mechanical robustness of the assembly during repeated mating and unmating cycles.

The adapted screw design and fastening concept strengthen the resistance of the mating face against mechanical loads occurring during operation. In particular, the change supports improved force retention of the screw connection and load absorption during plugging and unplugging.

This product improvement further enhances the durability and resilience of our connectors over the intended usage and operating cycles. It contributes to increased functional stability by strengthening the mechanical load-bearing capability of the affected area and supporting a more secure screw connection under operational load conditions.

These new screws will feature a different drive with a standard Torx T20 in order to ensure more simple exchange of the mating face, furthermore all repair kits will be available with the new screws and bits in order to allow for an in-field improvement of our connectors. The DC contact screws will remain with the Torx IPR T20 security drive. Documentation for the adjusted exchange process will be made available in the coming days.

Additional product lines are also covered with this PCN, that will be switched over in the coming weeks, in order to bring this robustness increase to more products.

Identifying characteristics

Different screw head visible on the mating face screws with Torx T20 drive

Start of Production (SOP)	2026-07-21	Last Time Delivery (LTD)	-
Effective date (EOP)	2026-07-21	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|--|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☒ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PCN-CXW260037-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1288248	EV-T1CCS-MF-M4X10-C	3	4		
1158266	EV-T1CCS-MF-M4X10-BIT-C	3	4		
1582285	CHARX T2CCS-MFC-M4X10-BIT	2	3		
1085797	EV-T2CCS-MF-M4X10	3	4		
1315148	EV-T2CCS-MF-M4X10-NAB	2	3		
1192781	EV-T1G2CC-DEMO-0,1M1ASBK11	7	8		
1301442	EV-T2HPCC-DC500A-3,5M50-A1C1	13	14		
1087136	EV-T2HPCC-DC500A-4,0M50ECBK11	19	20		
1148234	EV-T2HPCC-DC500A-3,0M50ECBK11	14	15		
1333722	EV-T2HPCC-DC400A-8,0M50ECBK11R	10	11		
1542909	EV-T2HPCC-DC500A-6,0M50ECBK11R	5	6		
1645868	EV-T2HPCC-DC400A-7,5M50ECBK11	6	7		
1197249	EV-T2HPCC-DC500A-3,5M50ECBK11	14	15		
1693106	EV-T2HPCC-DC500A-5,2M50-I1Y1	4	5		
1349015	EV-T2HPCC-DC500A-3,92M50-S1S2	8	9		
1583944	EV-T2HPCC-DC500A-6,0M50EXBK11R	5	6		
1101531	EV-T2HPCC-DC500A-5,5M50ECBK11	16	17		
1369289	EV-T2HPCC-DC500A-3,0M50ECBK11R	9	10		
1089665	EV-T2HPCC-DC500A-5,0M50ECBK11R	11	12		
1368038	EV-T2HPCC-DC500A-5,5M50-A1C1	10	11		
1301445	EV-T2HPCC-DC500A-5,0M50-A1C1	14	15		
1525277	EV-T2HPCC-DC500A-5,0M50-K2L1	6	7		
1349005	EV-T2HPCC-DC500A-5,82M50-S1S2	8	9		
1368042	EV-T2HPCC-DC500A-6,0M50-A1C1	10	11		
1693105	EV-T2HPCC-DC500A-4,5M50-I1Y1	4	5		
1085638	EV-T2HPCC-DC500A-5,0M50ECBK11	19	20		
1085637	EV-T2HPCC-DC500A-5,0M50ECBK11L	11	12		
1101642	EV-T2HPCC-DC500A-6,0M50ECBK11	16	17		
1085631	EV-T2HPCC-DC500A-5,0M50ECBK11S	12	13		
1741749	CHARX PT2C-DC375-7,5M-A1C1	10	11		
1538358	CHARX PT2C-DC375-6,0MES00P1	13	14		
1718043	CHARX PT2C-DC375-9,5MES00P	10	11		
1538067	CHARX PT2C-DC375-7,0MES00P1	13	14		
1669549	CHARX PT2C-DC375-5,91M-S1S1	12	13		

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1531924	CHARX PT2C-DC375-6,0MES00P	13	14		
1531927	CHARX PT2C-DC375-5,5MES00P	13	14		
1886918	CHARX PT2C-DC375-20,5MES00P	5	6		
1773991	CHARX PT2C-DC375-10,5MES00P	9	10		
1538066	CHARX PT2C-DC375-5,0MES00P1	13	14		
1669696	CHARX PT2C-DC375-7,91M-S1S1	12	13		
1531911	CHARX PT2C-DC375-7,5MES00P	13	14		
1741751	CHARX PT2C-DC375-5,5M-A1C1	10	11		
1531908	CHARX PT2C-DC375-8,0MES00P	13	14		
1538354	CHARX PT2C-DC375-8,0MES00P1	13	14		
1790237	CHARX PT2C-DC375-6,0M-A1C1	9	10		
1731209	CHARX PT2C-DC375-8,6MES00P	10	11		
1718048	CHARX PT2C-DC375-4,5MES00P	10	11		
1531913	CHARX PT2C-DC375-6,5MES00P	13	14		
1718047	CHARX PT2C-DC375-8,5MES00P	10	11		
1733064	CHARX PT2C-DC375-25,0MES00P-SA	10	11		
1767363	CHARX PT2C-DC375-15,5MES00P	9	10		
1531919	CHARX PT2C-DC375-4,0MES00P	13	14		
1718044	CHARX PT2C-DC375-9,0MES00P	10	11		
1577408	CHARX PT2C-DC375-10,0MES00P1	12	13		
1737599	CHARX PT2C-DC375-3,5MES00P	10	11		
1396518	CHARX PT2C-DC375-5,0MES00P	17	18		
1531934	CHARX PT2C-DC375-10,0MES00P	13	14		
1531920	CHARX PT2C-DC375-7,0MES00P	13	14		
1885474	CHARX PT2H-DC800-6,0MEC00P	0	1		
1820938	CHARX PT2H-DC800-5,0MEC00P	1	2		
1885476	CHARX PT2H-DC800-7,0MEC00P	0	1		
1430338	EV-T1HPCC-DC500A-6,0M50ECBK11	8	9		
1085642	EV-T1HPCC-DC500A-5,0M50ECBK11L	12	13		
1089931	EV-T1HPCC-DC500A-5,0M50ECBK11R	12	13		
1085800	EV-T1CCS-MF-M4X10	1	2		
1085802	EV-T1CCS-MF-M4X10-BIT-CTS	2	3		
1085799	EV-T2CCS-MF-M4X10-BIT-CTS	4	5		
1101121	EV-T1G2CC-DC200A-25FT1ASBK11	11	12		
1051695	EV-T1G2CC-DC200A-5,0M1ASBK11	13	14		
1885527	CHARX PT1H-DC500-25FMEC00P	0	1		
1386211	EV-T1HPCC-DC500A-5,0M50-A1C1	11	12		

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1385752	EV-T1HPCC-DC500A-3,5M50-A1C1	11	12		
1851395	CHARX PT1H-DC500-6,0MEC00P	1	2		
1881961	CHARX PT1H-DC500-5,0MEC00P	0	1		
1885522	CHARX PT1H-DC500-8,0MEC00P	0	1		
1818297	CHARX PT1H-DC500A-6,0MES00P	2	3		
1281251	EV-T1CCS-MF-M4X10-CTS	3	4		
1582262	CHARX T2CCS-MFC-M4X10	2	3		
1281249	EV-T2CCS-MF-M4X10-CTS	3	4		
1085641	EV-T1HPCC-DC500A-5,0M50ECBK11S	10	11		
1085658	EV-T1HPCC-DC500A-5,0M50ECBK11	10	11		
1674635	EV-T2HPCC-DC500A-5,5M50-H1W1	1	2		
1387212	EV-T1G2CC-DC200A-8,5M1ASBK11	9	10		
1397567	EV-T1G2CC-DC200A-3,8M1-A1C1	10	11		
1101122	EV-T1G2CC-DC200A-6,0M1ASBK11	12	13		
1544353	EV-T1G2CC-DC200A-8,6M1ASBK11	3	4		
1391732	EV-T1G2CC-DC200A-5,3M1-A1C1	10	11		
1435005	EV-T1G2CC-DC200A-10,0M1ASBK11	9	10		
1483491	EV-T1G2CC-DC200A-8,0M1ASBK11	6	7		
1311324	EV-T1G2CC-DC200A-7,0M1ASBK11	9	10		
1718010	EV-T2HPCC-DC500A-6,0M50ECBK11M	6	7		
1718008	EV-T2HPCC-DC500A-2,0M50ECBK11M	4	5		
1494471	EV-T2HPCC-DC500A-5,0M50ECBK11M	5	6		
1085801	EV-T1CCS-MF-M4X10-BIT	2	3		
1085798	EV-T2CCS-MF-M4X10-BIT	3	4		
1673036	CHARX PT2HS-DC800-5,0-A1C1-SRA	0	1		
1673036	CHARX PT2HS-DC800-5,0-A1C1-SRA	3	4		

Phoenix Contact Art.Nr.;Phoenix Contact Art.Bez.;Bemerkung

1288248	;EV-T1CCS-MF-M4X10-C;HW/FW alt: 3
1158266	;EV-T1CCS-MF-M4X10-BIT-C;HW/FW alt: 3
1582285	;CHARX T2CCS-MFC-M4X10-BIT;HW/FW alt: 2
1085797	;EV-T2CCS-MF-M4X10;HW/FW alt: 3
1315148	;EV-T2CCS-MF-M4X10-NAB;HW/FW alt: 2
1192781	;EV-T1G2CC-DEMO-0
1301442	;EV-T2HPCC-DC500A-3
1087136	;EV-T2HPCC-DC500A-4
1148234	;EV-T2HPCC-DC500A-3
1333722	;EV-T2HPCC-DC400A-8
1542909	;EV-T2HPCC-DC500A-6
1645868	;EV-T2HPCC-DC400A-7
1197249	;EV-T2HPCC-DC500A-3
1693106	;EV-T2HPCC-DC500A-5
1349015	;EV-T2HPCC-DC500A-3
1583944	;EV-T2HPCC-DC500A-6
1101531	;EV-T2HPCC-DC500A-5
1369289	;EV-T2HPCC-DC500A-3
1089665	;EV-T2HPCC-DC500A-5
1368038	;EV-T2HPCC-DC500A-5
1301445	;EV-T2HPCC-DC500A-5
1525277	;EV-T2HPCC-DC500A-5
1349005	;EV-T2HPCC-DC500A-5
1368042	;EV-T2HPCC-DC500A-6
1693105	;EV-T2HPCC-DC500A-4
1085638	;EV-T2HPCC-DC500A-5
1085637	;EV-T2HPCC-DC500A-5
1101642	;EV-T2HPCC-DC500A-6
1085631	;EV-T2HPCC-DC500A-5
1741749	;CHARX PT2C-DC375-7
1538358	;CHARX PT2C-DC375-6
1718043	;CHARX PT2C-DC375-9
1538067	;CHARX PT2C-DC375-7
1669549	;CHARX PT2C-DC375-5
1531924	;CHARX PT2C-DC375-6
1531927	;CHARX PT2C-DC375-5
1886918	;CHARX PT2C-DC375-20
1773991	;CHARX PT2C-DC375-10
1538066	;CHARX PT2C-DC375-5
1669696	;CHARX PT2C-DC375-7
1531911	;CHARX PT2C-DC375-7
1741751	;CHARX PT2C-DC375-5
1531908	;CHARX PT2C-DC375-8
1538354	;CHARX PT2C-DC375-8
1790237	;CHARX PT2C-DC375-6
1731209	;CHARX PT2C-DC375-8
1718048	;CHARX PT2C-DC375-4

1531913	;CHARX PT2C-DC375-6
1718047	;CHARX PT2C-DC375-8
1733064	;CHARX PT2C-DC375-25
1767363	;CHARX PT2C-DC375-15
1531919	;CHARX PT2C-DC375-4
1718044	;CHARX PT2C-DC375-9
1577408	;CHARX PT2C-DC375-10
1737599	;CHARX PT2C-DC375-3
1396518	;CHARX PT2C-DC375-5
1673036	;CHARX PT2HS-DC800-5
1673036	;CHARX PT2HS-DC800-5
1531934	;CHARX PT2C-DC375-10
1531920	;CHARX PT2C-DC375-7
1885474	;CHARX PT2H-DC800-6
1820938	;CHARX PT2H-DC800-5
1885476	;CHARX PT2H-DC800-7
1430338	;EV-T1HPCC-DC500A-6
1085642	;EV-T1HPCC-DC500A-5
1089931	;EV-T1HPCC-DC500A-5
1085800	;EV-T1CCS-MF-M4X10;HW/FW alt: 1
1085802	;EV-T1CCS-MF-M4X10-BIT-CTS;HW/FW alt: 2
1085799	;EV-T2CCS-MF-M4X10-BIT-CTS;HW/FW alt: 4
1101121	;EV-T1G2CC-DC200A-25FT1ASBK11;HW/FW alt: 11
1051695	;EV-T1G2CC-DC200A-5
1885527	;CHARX PT1H-DC500-25FMEC00P;
1386211	;EV-T1HPCC-DC500A-5
1385752	;EV-T1HPCC-DC500A-3
1851395	;CHARX PT1H-DC500-6
1881961	;CHARX PT1H-DC500-5
1885522	;CHARX PT1H-DC500-8
1818297	;CHARX PT1H-DC500A-6
1281251	;EV-T1CCS-MF-M4X10-CTS;HW/FW alt: 3
1582262	;CHARX T2CCS-MFC-M4X10;HW/FW alt: 2
1281249	;EV-T2CCS-MF-M4X10-CTS;HW/FW alt: 3
1085641	;EV-T1HPCC-DC500A-5
1085658	;EV-T1HPCC-DC500A-5
1674635	;EV-T2HPCC-DC500A-5
1387212	;EV-T1G2CC-DC200A-8
1397567	;EV-T1G2CC-DC200A-3
1101122	;EV-T1G2CC-DC200A-6
1544353	;EV-T1G2CC-DC200A-8
1391732	;EV-T1G2CC-DC200A-5
1435005	;EV-T1G2CC-DC200A-10
1483491	;EV-T1G2CC-DC200A-8
1311324	;EV-T1G2CC-DC200A-7
1718010	;EV-T2HPCC-DC500A-6
1718008	;EV-T2HPCC-DC500A-2
1494471	;EV-T2HPCC-DC500A-5

1085801	;EV-T1CCS-MF-M4X10-BIT;HW/FW alt: 2
1085798	;EV-T2CCS-MF-M4X10-BIT;HW/FW alt: 3

HW/FW neu: 4	eCl@ss 13.0: 27144792	
HW/FW neu: 4	eCl@ss 13.0: 27144792	
HW/FW neu: 3	eCl@ss 13.0: 27144792	
HW/FW neu: 4	eCl@ss 13.0: 27144792	
HW/FW neu: 3	eCl@ss 13.0: 27144792	
1M1ASBK11;HW/FW alt: 7	HW/FW neu: 8	eCl@ss 13.0: 27144792
5M50-A1C1;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
0M50ECBK11;HW/FW alt: 19	HW/FW neu: 20	eCl@ss 13.0: 27144705
0M50ECBK11;HW/FW alt: 14	HW/FW neu: 15	eCl@ss 13.0: 27144705
0M50ECBK11R;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
0M50ECBK11R;HW/FW alt: 5	HW/FW neu: 6	eCl@ss 13.0: 27144705
5M50ECBK11;HW/FW alt: 6	HW/FW neu: 7	eCl@ss 13.0: 27144705
5M50ECBK11;HW/FW alt: 14	HW/FW neu: 15	eCl@ss 13.0: 27144705
2M50-I1Y1;HW/FW alt: 4	HW/FW neu: 5	eCl@ss 13.0: 27144705
92M50-S1S2;HW/FW alt: 8	HW/FW neu: 9	eCl@ss 13.0: 27144705
0M50EXBK11R;HW/FW alt: 5	HW/FW neu: 6	eCl@ss 13.0: 27144705
5M50ECBK11;HW/FW alt: 16	HW/FW neu: 17	eCl@ss 13.0: 27144705
0M50ECBK11R;HW/FW alt: 9	HW/FW neu: 10	eCl@ss 13.0: 27144705
0M50ECBK11R;HW/FW alt: 11	HW/FW neu: 12	eCl@ss 13.0: 27144705
5M50-A1C1;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
0M50-A1C1;HW/FW alt: 14	HW/FW neu: 15	eCl@ss 13.0: 27144705
0M50-K2L1;HW/FW alt: 6	HW/FW neu: 7	eCl@ss 13.0: 27144705
82M50-S1S2;HW/FW alt: 8	HW/FW neu: 9	eCl@ss 13.0: 27144705
0M50-A1C1;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
5M50-I1Y1;HW/FW alt: 4	HW/FW neu: 5	eCl@ss 13.0: 27144705
0M50ECBK11;HW/FW alt: 19	HW/FW neu: 20	eCl@ss 13.0: 27144705
0M50ECBK11L;HW/FW alt: 11	HW/FW neu: 12	eCl@ss 13.0: 27144705
0M50ECBK11;HW/FW alt: 16	HW/FW neu: 17	eCl@ss 13.0: 27144705
0M50ECBK11S;HW/FW alt: 12	HW/FW neu: 13	eCl@ss 13.0: 27144705
5M-A1C1;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
0MES00P1;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
5MES00P;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
0MES00P1;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
91M-S1S1;HW/FW alt: 12	HW/FW neu: 13	eCl@ss 13.0: 27144705
0MES00P;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
5MES00P;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
5MES00P;		
5MES00P;HW/FW alt: 9	HW/FW neu: 10	eCl@ss 13.0: 27144705
0MES00P1;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
91M-S1S1;HW/FW alt: 12	HW/FW neu: 13	eCl@ss 13.0: 27144705
5MES00P;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
5M-A1C1;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
0MES00P;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
0MES00P1;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
0M-A1C1;HW/FW alt: 9	HW/FW neu: 10	eCl@ss 13.0: 27144705
6MES00P;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
5MES00P;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705

5MES00P;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
5MES00P;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
0MES00P-SA;		
5MES00P;HW/FW alt: 9	HW/FW neu: 10	eCl@ss 13.0: 27144705
0MES00P;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
0MES00P;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
0MES00P1;HW/FW alt: 12	HW/FW neu: 13	eCl@ss 13.0: 27144705
5MES00P;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
0MES00P;HW/FW alt: 17	HW/FW neu: 18	eCl@ss 13.0: 27144705
0-A1C1-SRA;HW/FW alt: 0	HW/FW neu: 1	eCl@ss 13.0: 27144705
0-A1C1-SRA;HW/FW alt: 3	HW/FW neu: 4	eCl@ss 13.0: 27144705
0MES00P;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
0MES00P;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
0MEC00P;		
0MEC00P;HW/FW alt: 1	HW/FW neu: 2	eCl@ss 13.0: 27144705
0MEC00P;		
0M50ECBK11;HW/FW alt: 8	HW/FW neu: 9	eCl@ss 13.0: 27144705
0M50ECBK11L;HW/FW alt: 12	HW/FW neu: 13	eCl@ss 13.0: 27144705
0M50ECBK11R;HW/FW alt: 12	HW/FW neu: 13	eCl@ss 13.0: 27144705
HW/FW neu: 2	eCl@ss 13.0: 27144792	
HW/FW neu: 3	eCl@ss 13.0: 27144792	
HW/FW neu: 5	eCl@ss 13.0: 27144792	
HW/FW neu: 12	eCl@ss 13.0: 27144705	
0M1ASBK11;HW/FW alt: 13	HW/FW neu: 14	eCl@ss 13.0: 27144705
0M50-A1C1;HW/FW alt: 11	HW/FW neu: 12	eCl@ss 13.0: 27144705
5M50-A1C1;HW/FW alt: 11	HW/FW neu: 12	eCl@ss 13.0: 27144705
0MEC00P;HW/FW alt: 1	HW/FW neu: 2	eCl@ss 13.0: 27144705
0MEC00P;		
0MEC00P;		
0MES00P;HW/FW alt: 2	HW/FW neu: 3	eCl@ss 13.0: 27144705
HW/FW neu: 4	eCl@ss 13.0: 27144792	
HW/FW neu: 3	eCl@ss 13.0: 27144792	
HW/FW neu: 4	eCl@ss 13.0: 27144792	
0M50ECBK11S;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
0M50ECBK11;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
5M50-H1W1;		
5M1ASBK11;HW/FW alt: 9	HW/FW neu: 10	eCl@ss 13.0: 27144705
8M1-A1C1;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
0M1ASBK11;HW/FW alt: 12	HW/FW neu: 13	eCl@ss 13.0: 27144705
6M1ASBK11;HW/FW alt: 3	HW/FW neu: 4	eCl@ss 13.0: 27144705
3M1-A1C1;HW/FW alt: 10	HW/FW neu: 11	eCl@ss 13.0: 27144705
0M1ASBK11;HW/FW alt: 9	HW/FW neu: 10	eCl@ss 13.0: 27144705
0M1ASBK11;HW/FW alt: 6	HW/FW neu: 7	eCl@ss 13.0: 27144705
0M1ASBK11;HW/FW alt: 9	HW/FW neu: 10	eCl@ss 13.0: 27144705
0M50ECBK11M;HW/FW alt: 6	HW/FW neu: 7	eCl@ss 13.0: 27144705
0M50ECBK11M;HW/FW alt: 4	HW/FW neu: 5	eCl@ss 13.0: 27144705
0M50ECBK11M;HW/FW alt: 5	HW/FW neu: 6	eCl@ss 13.0: 27144705

HW/FW neu: 3

HW/FW neu: 4

eCl@ss 13.0: 27144792

eCl@ss 13.0: 27144792

Kunde;Name 1;Name 2;Name 3;Name 4;Straße;PLZ;Stadt;Phoenix Contact Art.Nr.;Phoenix Contact Art.Bez.;Ihre |
49786 ;TTI
49786 ;TTI

Materialnr.;Menge 2024 ST;Menge 2025 ST;Menge 2026 ST;AE 2026 ST
Inc.;;;Ganghoferstraße 34;82216;Maisach;1531934;CHARX PT2C-DC375-10
Inc.;;;Ganghoferstraße 34;82216;Maisach;1820938;CHARX PT2H-DC800-5

0MES00P;PHX1531934;;;10 ST;10 ST

0MEC00P;PHX1820938;;;15 ST;15 ST

Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;
1288248;EV-T1CCS-MF-M4X10-C;3;4;;;27144792;
1158266;EV-T1CCS-MF-M4X10-BIT-C;3;4;;;27144792;
1582285;CHARX T2CCS-MFC-M4X10-BIT;2;3;;;27144792;
1085797;EV-T2CCS-MF-M4X10;3;4;;;27144792;
1315148;EV-T2CCS-MF-M4X10-NAB;2;3;;;27144792;
1192781;EV-T1G2CC-DEMO-0
1301442;EV-T2HPCC-DC500A-3
1087136;EV-T2HPCC-DC500A-4
1148234;EV-T2HPCC-DC500A-3
1333722;EV-T2HPCC-DC400A-8
1542909;EV-T2HPCC-DC500A-6
1645868;EV-T2HPCC-DC400A-7
1197249;EV-T2HPCC-DC500A-3
1693106;EV-T2HPCC-DC500A-5
1349015;EV-T2HPCC-DC500A-3
1583944;EV-T2HPCC-DC500A-6
1101531;EV-T2HPCC-DC500A-5
1369289;EV-T2HPCC-DC500A-3
1089665;EV-T2HPCC-DC500A-5
1368038;EV-T2HPCC-DC500A-5
1301445;EV-T2HPCC-DC500A-5
1525277;EV-T2HPCC-DC500A-5
1349005;EV-T2HPCC-DC500A-5
1368042;EV-T2HPCC-DC500A-6
1693105;EV-T2HPCC-DC500A-4
1085638;EV-T2HPCC-DC500A-5
1085637;EV-T2HPCC-DC500A-5
1101642;EV-T2HPCC-DC500A-6
1085631;EV-T2HPCC-DC500A-5
1741749;CHARX PT2C-DC375-7
1538358;CHARX PT2C-DC375-6
1718043;CHARX PT2C-DC375-9
1538067;CHARX PT2C-DC375-7
1669549;CHARX PT2C-DC375-5
1531924;CHARX PT2C-DC375-6
1531927;CHARX PT2C-DC375-5
1886918;CHARX PT2C-DC375-20
1773991;CHARX PT2C-DC375-10
1538066;CHARX PT2C-DC375-5
1669696;CHARX PT2C-DC375-7
1531911;CHARX PT2C-DC375-7
1741751;CHARX PT2C-DC375-5
1531908;CHARX PT2C-DC375-8
1538354;CHARX PT2C-DC375-8
1790237;CHARX PT2C-DC375-6
1731209;CHARX PT2C-DC375-8
1718048;CHARX PT2C-DC375-4

1531913;CHARX PT2C-DC375-6
1718047;CHARX PT2C-DC375-8
1733064;CHARX PT2C-DC375-25
1767363;CHARX PT2C-DC375-15
1531919;CHARX PT2C-DC375-4
1718044;CHARX PT2C-DC375-9
1577408;CHARX PT2C-DC375-10
1737599;CHARX PT2C-DC375-3
1396518;CHARX PT2C-DC375-5
1531934;CHARX PT2C-DC375-10
1531920;CHARX PT2C-DC375-7
1885474;CHARX PT2H-DC800-6
1820938;CHARX PT2H-DC800-5
1885476;CHARX PT2H-DC800-7
1430338;EV-T1HPCC-DC500A-6
1085642;EV-T1HPCC-DC500A-5
1089931;EV-T1HPCC-DC500A-5
1085800;EV-T1CCS-MF-M4X10;1;2;;;27144792;
1085802;EV-T1CCS-MF-M4X10-BIT-CTS;2;3;;;27144792;
1085799;EV-T2CCS-MF-M4X10-BIT-CTS;4;5;;;27144792;
1101121;EV-T1G2CC-DC200A-25FT1ASBK11;11;12;;;27144705;
1051695;EV-T1G2CC-DC200A-5
1885527;CHARX PT1H-DC500-25FMCC00P;0;1;;;;
1386211;EV-T1HPCC-DC500A-5
1385752;EV-T1HPCC-DC500A-3
1851395;CHARX PT1H-DC500-6
1881961;CHARX PT1H-DC500-5
1885522;CHARX PT1H-DC500-8
1818297;CHARX PT1H-DC500A-6
1281251;EV-T1CCS-MF-M4X10-CTS;3;4;;;27144792;
1582262;CHARX T2CCS-MFC-M4X10;2;3;;;27144792;
1281249;EV-T2CCS-MF-M4X10-CTS;3;4;;;27144792;
1085641;EV-T1HPCC-DC500A-5
1085658;EV-T1HPCC-DC500A-5
1674635;EV-T2HPCC-DC500A-5
1387212;EV-T1G2CC-DC200A-8
1397567;EV-T1G2CC-DC200A-3
1101122;EV-T1G2CC-DC200A-6
1544353;EV-T1G2CC-DC200A-8
1391732;EV-T1G2CC-DC200A-5
1435005;EV-T1G2CC-DC200A-10
1483491;EV-T1G2CC-DC200A-8
1311324;EV-T1G2CC-DC200A-7
1718010;EV-T2HPCC-DC500A-6
1718008;EV-T2HPCC-DC500A-2
1494471;EV-T2HPCC-DC500A-5
1085801;EV-T1CCS-MF-M4X10-BIT;2;3;;;27144792;
1085798;EV-T2CCS-MF-M4X10-BIT;3;4;;;27144792;

1673036;CHARX PT2HS-DC800-5

1673036;CHARX PT2HS-DC800-5

1M1ASBK11;7;8;;;27144792;
5M50-A1C1;13;14;;;27144705;
0M50ECBK11;19;20;;;27144705;
0M50ECBK11;14;15;;;27144705;
0M50ECBK11R;10;11;;;27144705;
0M50ECBK11R;5;6;;;27144705;
5M50ECBK11;6;7;;;27144705;
5M50ECBK11;14;15;;;27144705;
2M50-l1Y1;4;5;;;27144705;
92M50-S1S2;8;9;;;27144705;
0M50EXBK11R;5;6;;;27144705;
5M50ECBK11;16;17;;;27144705;
0M50ECBK11R;9;10;;;27144705;
0M50ECBK11R;11;12;;;27144705;
5M50-A1C1;10;11;;;27144705;
0M50-A1C1;14;15;;;27144705;
0M50-K2L1;6;7;;;27144705;
82M50-S1S2;8;9;;;27144705;
0M50-A1C1;10;11;;;27144705;
5M50-l1Y1;4;5;;;27144705;
0M50ECBK11;19;20;;;27144705;
0M50ECBK11L;11;12;;;27144705;
0M50ECBK11;16;17;;;27144705;
0M50ECBK11S;12;13;;;27144705;
5M-A1C1;10;11;;;27144705;
0MES00P1;13;14;;;27144705;
5MES00P;10;11;;;27144705;
0MES00P1;13;14;;;27144705;
91M-S1S1;12;13;;;27144705;
0MES00P;13;14;;;27144705;
5MES00P;13;14;;;27144705;
5MES00P;5;6;;;;
5MES00P;9;10;;;27144705;
0MES00P1;13;14;;;27144705;
91M-S1S1;12;13;;;27144705;
5MES00P;13;14;;;27144705;
5M-A1C1;10;11;;;27144705;
0MES00P;13;14;;;27144705;
0MES00P1;13;14;;;27144705;
0M-A1C1;9;10;;;27144705;
6MES00P;10;11;;;27144705;
5MES00P;10;11;;;27144705;

5MES00P;13;14;;;27144705;
5MES00P;10;11;;;27144705;
0MES00P-SA;10;11;;;;
5MES00P;9;10;;;27144705;
0MES00P;13;14;;;27144705;
0MES00P;10;11;;;27144705;
0MES00P1;12;13;;;27144705;
5MES00P;10;11;;;27144705;
0MES00P;17;18;;;27144705;
0MES00P;13;14;;;27144705;
0MES00P;13;14;;;27144705;
0MEC00P;0;1;;;;
0MEC00P;1;2;;;27144705;
0MEC00P;0;1;;;;
0M50ECBK11;8;9;;;27144705;
0M50ECBK11L;12;13;;;27144705;
0M50ECBK11R;12;13;;;27144705;

0M1ASBK11;13;14;;;27144705;

0M50-A1C1;11;12;;;27144705;
5M50-A1C1;11;12;;;27144705;
0MEC00P;1;2;;;27144705;
0MEC00P;0;1;;;;
0MEC00P;0;1;;;;
0MES00P;2;3;;;27144705;

0M50ECBK11S;10;11;;;27144705;
0M50ECBK11;10;11;;;27144705;
5M50-H1W1;1;2;;;;
5M1ASBK11;9;10;;;27144705;
8M1-A1C1;10;11;;;27144705;
0M1ASBK11;12;13;;;27144705;
6M1ASBK11;3;4;;;27144705;
3M1-A1C1;10;11;;;27144705;
0M1ASBK11;9;10;;;27144705;
0M1ASBK11;6;7;;;27144705;
0M1ASBK11;9;10;;;27144705;
0M50ECBK11M;6;7;;;27144705;
0M50ECBK11M;4;5;;;27144705;
0M50ECBK11M;5;6;;;27144705;

0-A1C1-SRA;0;1;;;27144705;

0-A1C1-SRA;3;4;;;27144705;