

Product change notification (PCN)

Title / short description	New equipment
Affected article category	Electronics housing
Change category	Form and appearance
Change number	PAC260010-00
Reason for PCN/PDN Revision	

Purpose/objective of the change

New plastic tool

Detailed description of the change

The previous plastic tool has reached the end of its service life and must be replaced with a new tool. As part of this, a product improvement will be introduced in the form of optimized radii and draft angles. The implemented modifications are minor and limited to small geometric optimizations. These changes do not affect the fit, form, or function of the component. All technical and functional properties remain unchanged, and full compatibility is maintained.

Due to the minimal nature of the change, no separation of production batches will be introduced. Mixed deliveries of components from the previous and the new version may occur, including within one packaging unit. Interchangeability is fully ensured.

Identifying characteristics

Not applicable

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2027-02-01	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- PAC260010 BC UT old_new.pdf
- Material_list.csv
- PCN-PAC260010-00_EN

Material list


Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
2202951	BC 107,6 UT HBUS KMGY	00	00		
2203517	BC 107,6 UT HBUS KMGY/RD	02	02		
1311017	BC 107,6-KIT-RPI-7035+PCB	01	01		
1107460	RPI-BC 107,6 EXT DEV-KIT KMGY	02	02		
1270285	RPI-BC 107,6 DEV-KIT KMGY S1596	02	02		
1311017	BC 107,6-KIT-RPI-7035+PCB	03	03		
1270285	RPI-BC 107,6 DEV-KIT KMGY S1596	01	01		
2202874	RPI-BC 107,6 DEV-KIT KMGY	02	02		
2202951	BC 107,6 UT HBUS KMGY	02	02		
2202874	RPI-BC 107,6 DEV-KIT KMGY	00	00		
1311013	BC 107,6-KIT-RPI-7035	03	03		
2202951	BC 107,6 UT HBUS KMGY	01	01		
1311017	BC 107,6-KIT-RPI-7035+PCB	01	01		
1311013	BC 107,6-KIT-RPI-7035	02	02		
2202874	RPI-BC 107,6 DEV-KIT KMGY	01	01		
2203517	BC 107,6 UT HBUS KMGY/RD	01	01		
1270285	RPI-BC 107,6 DEV-KIT KMGY S1596	00	00		
1107460	RPI-BC 107,6 EXT DEV-KIT KMGY	04	04		
1311013	BC 107,6-KIT-RPI-7035	01	01		
1107460	RPI-BC 107,6 EXT DEV-KIT KMGY	03	03		
1311017	BC 107,6-KIT-RPI-7035+PCB	02	02		
1107460	RPI-BC 107,6 EXT DEV-KIT KMGY	01	01		
2203517	BC 107,6 UT HBUS KMGY/RD	00	00		
1385674	BC 107,6 UT HBUS GY7021	01	01		
1385674	BC 107,6 UT HBUS GY7021	00	00		
1385674	BC 107,6 UT HBUS GY7021	02	02		
1749649	BC 107,6 UT HBUS GY W/ORG CLP	00	00		
1441368	BC 107,6-KIT-U11-7035+4SPTA10	00	00		
2203299	BC 107,6 OT U11 SET S984	02	02		
1311010	BC 107,6-KIT-U22-7035+4PTDA9	02	02		
1456991	BC 107,6-SKT-U11-7035+4SPTA10	01	01		
2202064	BC 107,6 UT HBUS BK S726	02	02		
1461391	BC 107,6 UT HBUS BK S1761	00	00		
1311010	BC 107,6-KIT-U22-7035+4PTDA9	01	01		
1006953	BC 107,6 UT HBUS FS BK VPE80	01	01		
2203815	BC 107,6 UT HBUS BK W/ORG CLP	01	01		
1441368	BC 107,6-KIT-U11-7035+4SPTA10	01	01		
2896270	BC 107,6 UT HBUS BK	04	04		

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1461391	BC 107,6 UT HBUS BK S1761	02	02		
2203411	BC 107,6 UT HBUS BK S996	01	01		
1089833	BC 107,6 OT/UT U11 SET S1324	00	00		
2203411	BC 107,6 UT HBUS BK S996	00	00		
2203299	BC 107,6 OT U11 SET S984	01	01		
2203411	BC 107,6 UT HBUS BK S996	02	02		
1441373	BC 107,6-KIT-U22-7035+4PTDA8	00	00		
1311009	BC 107,6-KIT-U11-7035+4SPTA12	01	01		
1456991	BC 107,6-SKT-U11-7035+4SPTA10	00	00		
2202064	BC 107,6 UT HBUS BK S726	00	00		
1089833	BC 107,6 OT/UT U11 SET S1324	02	02		
1089833	BC 107,6 OT/UT U11 SET S1324	02	02		
2896270	BC 107,6 UT HBUS BK	02	02		
2203299	BC 107,6 OT U11 SET S984	00	00		
1089833	BC 107,6 OT/UT U11 SET S1324	01	01		
1461391	BC 107,6 UT HBUS BK S1761	01	01		
2896270	BC 107,6 UT HBUS BK	03	03		
1311009	BC 107,6-KIT-U11-7035+4SPTA12	02	02		
1441373	BC 107,6-KIT-U22-7035+4PTDA8	01	01		
2202525	BC 107,6 DEV-KIT KMGY	01	01		
2202525	BC 107,6 DEV-KIT KMGY	02	02		
1006953	BC 107,6 UT HBUS FS BK VPE80	00	00		
2202525	BC 107,6 DEV-KIT KMGY	00	00		
2202064	BC 107,6 UT HBUS BK S726	01	01		
2203815	BC 107,6 UT HBUS BK W/ORG CLP	02	02		
1311007	BC 71,6-KIT-U11-7035 + 4SPTA8	00	00		
2202907	BC 71,6 SET KMGY S907	02	02		
2202907	BC 71,6 SET KMGY S907	00	00		
1006950	BC 71,6 UT HBUS FS BK VPE160	01	01		
2896267	BC 71,6 UT HBUS BK	02	02		
1455660	BC 71,6-KIT-U11-7035+4SPTA6	00	00		
2896267	BC 71,6 UT HBUS BK	02	02		
2202593	BC 71,6 SET KMGY S854	01	01		
1456985	BC 71,6-SKT-U11-7035+4SPTA6	00	00		
2202907	BC 71,6 SET KMGY S907	01	01		
2896267	BC 71,6 UT HBUS BK	03	03		
2202907	BC 71,6 SET KMGY S907	00	00		
2896267	BC 71,6 UT HBUS BK	02	02		
1456985	BC 71,6-SKT-U11-7035+4SPTA6	01	01		


Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1311008	BC 71,6-KIT-U22-7035 + 4PTDA6	00	00		
2202593	BC 71,6 SET KMGY S854	03	03		
1456985	BC 71,6-SKT-U11-7035+4SPTA6	00	00		
1006950	BC 71,6 UT HBUS FS BK VPE160	00	00		
2202593	BC 71,6 SET KMGY S854	00	00		
1311008	BC 71,6-KIT-U22-7035 + 4PTDA6	00	00		
1311008	BC 71,6-KIT-U22-7035 + 4PTDA6	01	01		
2202907	BC 71,6 SET KMGY S907	01	01		
2202593	BC 71,6 SET KMGY S854	00	00		
2896267	BC 71,6 UT HBUS BK	04	04		
1455660	BC 71,6-KIT-U11-7035+4SPTA6	01	01		
1311007	BC 71,6-KIT-U11-7035 + 4SPTA8	00	00		
1311008	BC 71,6-KIT-U22-7035 + 4PTDA6	00	00		
2202593	BC 71,6 SET KMGY S854	02	02		
2202593	BC 71,6 SET KMGY S854	04	04		
2202593	BC 71,6 SET KMGY S854	02	02		
1006950	BC 71,6 UT HBUS FS BK VPE160	00	00		
2202593	BC 71,6 SET KMGY S854	03	03		
1050448	BC 71,6 UT HBUS BU5015 VPE160	00	00		
1050448	BC 71,6 UT HBUS BU5015 VPE160	00	00		
1738320	BC 71,6 UT HBUS FS BU VPE160	00	00		
1050448	BC 71,6 UT HBUS BU5015 VPE160	02	02		
1050448	BC 71,6 UT HBUS BU5015 VPE160	01	01		
2200648	BC 71,6 UTSM 7035	01	01		
2200648	BC 71,6 UTSM 7035	02	02		
2200648	BC 71,6 UTSM 7035	01	01		
2896267	BC 71,6 UT HBUS BK	01	01		
1791396	BC 107,6 UT HBUS WH9016	00	00		
1227344	BC 71,6 UT HBUS KMGY	02	02		
1227344	BC 71,6 UT HBUS KMGY	00	00		
1227344	BC 71,6 UT HBUS KMGY	00	00		
1227344	BC 71,6 UT HBUS KMGY	01	01		

PAC260010 / BC 107,6+71,6

old




new




PAC260010 / BC 107,6+71,6

old




new




PAC260010 / BC 107,6+71,6

old




new




PAC260010 / BC 107,6+71,6

old




new




PAC260010 / BC 107,6+71,6

old



new



Item no.;Type;old;new;Substitute item;Replacement product designation;eCl@ss 13.0;

2202951;BC 107

2203517;BC 107

1311017;BC 107

1107460;RPI-BC 107

1270285;RPI-BC 107

1311017;BC 107

1270285;RPI-BC 107

2202874;RPI-BC 107

2202951;BC 107

2202874;RPI-BC 107

1311013;BC 107

2202951;BC 107

1311017;BC 107

1311013;BC 107

2202874;RPI-BC 107

2203517;BC 107

1270285;RPI-BC 107

1107460;RPI-BC 107

1311013;BC 107

1107460;RPI-BC 107

1311017;BC 107

1107460;RPI-BC 107

2203517;BC 107

1385674;BC 107

1385674;BC 107

1385674;BC 107

1749649;BC 107

1441368;BC 107

2203299;BC 107

1311010;BC 107

1456991;BC 107

2202064;BC 107

1461391;BC 107

1311010;BC 107

1006953;BC 107

2203815;BC 107

1441368;BC 107

2896270;BC 107

1461391;BC 107

2203411;BC 107

1089833;BC 107

2203411;BC 107

2203299;BC 107

2203411;BC 107

1441373;BC 107

1311009;BC 107

1456991;BC 107

2202064;BC 107
1089833;BC 107
1089833;BC 107
2896270;BC 107
2203299;BC 107
1089833;BC 107
1461391;BC 107
2896270;BC 107
1311009;BC 107
1441373;BC 107
2202525;BC 107
2202525;BC 107
1006953;BC 107
2202525;BC 107
2202064;BC 107
2203815;BC 107
1311007;BC 71
2202907;BC 71
2202907;BC 71
1006950;BC 71
2896267;BC 71
1455660;BC 71
2896267;BC 71
2202593;BC 71
1456985;BC 71
2202907;BC 71
2896267;BC 71
2202907;BC 71
2896267;BC 71
1456985;BC 71
1311008;BC 71
2202593;BC 71
1456985;BC 71
1006950;BC 71
2202593;BC 71
1311008;BC 71
1311008;BC 71
2202907;BC 71
2202593;BC 71
2896267;BC 71
1455660;BC 71
1311007;BC 71
1311008;BC 71
2202593;BC 71
2202593;BC 71
2202593;BC 71
1006950;BC 71
2202593;BC 71

1050448;BC 71
1050448;BC 71
1738320;BC 71
1050448;BC 71
1050448;BC 71
2200648;BC 71
2200648;BC 71
2200648;BC 71
2896267;BC 71
1791396;BC 107
1227344;BC 71
1227344;BC 71
1227344;BC 71
1227344;BC 71

6 UT HBUS KMGY;00;00;;;27190601;
6 UT HBUS KMGY/RD;02;02;;;27190601;
6-KIT-RPI-7035+PCB;01;01;;;27190301;
6 EXT DEV-KIT KMGY;02;02;;;27190201;
6 DEV-KIT KMGY S1596;02;02;;;27190201;
6-KIT-RPI-7035+PCB;03;03;;;27190301;
6 DEV-KIT KMGY S1596;01;01;;;27190201;
6 DEV-KIT KMGY;02;02;;;27190201;
6 UT HBUS KMGY;02;02;;;27190601;
6 DEV-KIT KMGY;00;00;;;27190201;
6-KIT-RPI-7035;03;03;;;27190301;
6 UT HBUS KMGY;01;01;;;27190601;
6-KIT-RPI-7035+PCB;01;01;;;27190301;
6-KIT-RPI-7035;02;02;;;27190301;
6 DEV-KIT KMGY;01;01;;;27190201;
6 UT HBUS KMGY/RD;01;01;;;27190601;
6 DEV-KIT KMGY S1596;00;00;;;27190201;
6 EXT DEV-KIT KMGY;04;04;;;27190201;
6-KIT-RPI-7035;01;01;;;27190301;
6 EXT DEV-KIT KMGY;03;03;;;27190201;
6-KIT-RPI-7035+PCB;02;02;;;27190301;
6 EXT DEV-KIT KMGY;01;01;;;27190201;
6 UT HBUS KMGY/RD;00;00;;;27190601;
6 UT HBUS GY7021;01;01;;;27190601;
6 UT HBUS GY7021;00;00;;;27190601;
6 UT HBUS GY7021;02;02;;;27190601;
6 UT HBUS GY W/ORG CLP;00;00;;;27190601;
6-KIT-U11-7035+4SPTA10;00;00;;;27190301;
6 OT U11 SET S984;02;02;;;27190603;
6-KIT-U22-7035+4PTDA9;02;02;;;27190301;
6-SKT-U11-7035+4SPTA10;01;01;;;27190301;
6 UT HBUS BK S726;02;02;;;27190601;
6 UT HBUS BK S1761;00;00;;;27190601;
6-KIT-U22-7035+4PTDA9;01;01;;;27190301;
6 UT HBUS FS BK VPE80;01;01;;;27190601;
6 UT HBUS BK W/ORG CLP;01;01;;;27190601;
6-KIT-U11-7035+4SPTA10;01;01;;;27190301;
6 UT HBUS BK;04;04;;;27190601;
6 UT HBUS BK S1761;02;02;;;27190601;
6 UT HBUS BK S996;01;01;;;27190601;
6 OT/UT U11 SET S1324;00;00;;;27190301;
6 UT HBUS BK S996;00;00;;;27190601;
6 OT U11 SET S984;01;01;;;27190603;
6 UT HBUS BK S996;02;02;;;27190601;
6-KIT-U22-7035+4PTDA8;00;00;;;27190301;
6-KIT-U11-7035+4SPTA12;01;01;;;27190301;
6-SKT-U11-7035+4SPTA10;00;00;;;27190301;

6 UT HBUS BK S726;00;00;;;27190601;
6 OT/UT U11 SET S1324;02;02;;;27190301;
6 OT/UT U11 SET S1324;02;02;;;27190301;
6 UT HBUS BK;02;02;;;27190601;
6 OT U11 SET S984;00;00;;;27190603;
6 OT/UT U11 SET S1324;01;01;;;27190301;
6 UT HBUS BK S1761;01;01;;;27190601;
6 UT HBUS BK;03;03;;;27190601;
6-KIT-U11-7035+4SPTA12;02;02;;;27190301;
6-KIT-U22-7035+4PTDA8;01;01;;;27190301;
6 DEV-KIT KMGY;01;01;;;27190301;
6 DEV-KIT KMGY;02;02;;;27190301;
6 UT HBUS FS BK VPE80;00;00;;;27190601;
6 DEV-KIT KMGY;00;00;;;27190301;
6 UT HBUS BK S726;01;01;;;27190601;
6 UT HBUS BK W/ORG CLP;02;02;;;27190601;
6-KIT-U11-7035 + 4SPTA8;00;00;;;27190301;
6 SET KMGY S907;02;02;;;27190201;
6 SET KMGY S907;00;00;;;27190201;
6 UT HBUS FS BK VPE160;01;01;;;27190601;
6 UT HBUS BK;02;02;;;27190601;
6-KIT-U11-7035+4SPTA6;00;00;;;27190301;
6 UT HBUS BK;02;02;;;27190601;
6 SET KMGY S854;01;01;;;27190301;
6-SKT-U11-7035+4SPTA6;00;00;;;27190301;
6 SET KMGY S907;01;01;;;27190201;
6 UT HBUS BK;03;03;;;27190601;
6 SET KMGY S907;00;00;;;27190201;
6 UT HBUS BK;02;02;;;27190601;
6-SKT-U11-7035+4SPTA6;01;01;;;27190301;
6-KIT-U22-7035 + 4PTDA6;00;00;;;27190301;
6 SET KMGY S854;03;03;;;27190301;
6-SKT-U11-7035+4SPTA6;00;00;;;27190301;
6 UT HBUS FS BK VPE160;00;00;;;27190601;
6 SET KMGY S854;00;00;;;27190301;
6-KIT-U22-7035 + 4PTDA6;00;00;;;27190301;
6-KIT-U22-7035 + 4PTDA6;01;01;;;27190301;
6 SET KMGY S907;01;01;;;27190201;
6 SET KMGY S854;00;00;;;27190301;
6 UT HBUS BK;04;04;;;27190601;
6-KIT-U11-7035+4SPTA6;01;01;;;27190301;
6-KIT-U11-7035 + 4SPTA8;00;00;;;27190301;
6-KIT-U22-7035 + 4PTDA6;00;00;;;27190301;
6 SET KMGY S854;02;02;;;27190301;
6 SET KMGY S854;04;04;;;27190301;
6 SET KMGY S854;02;02;;;27190301;
6 UT HBUS FS BK VPE160;00;00;;;27190601;
6 SET KMGY S854;03;03;;;27190301;

6 UT HBUS BU5015 VPE160;00;00;;;27190601;
6 UT HBUS BU5015 VPE160;00;00;;;27190601;
6 UT HBUS FS BU VPE160;00;00;;;27190601;
6 UT HBUS BU5015 VPE160;02;02;;;27190601;
6 UT HBUS BU5015 VPE160;01;01;;;27190601;
6 UTSM 7035;01;01;;;27190601;
6 UTSM 7035;02;02;;;27190601;
6 UTSM 7035;01;01;;;27190601;
6 UT HBUS BK;01;01;;;27190601;
6 UT HBUS WH9016;00;00;;;27190601;
6 UT HBUS KMGY;02;02;;;27190601;
6 UT HBUS KMGY;00;00;;;27190601;
6 UT HBUS KMGY;00;00;;;27190601;
6 UT HBUS KMGY;01;01;;;27190601;

PCN/PDN Number	Customer Number	Company Name	Street	Postcode/Zip Code
PAC260010	401641	TTI, INC.	2441 NORTHEAST PKWY	76106

City	Phoenix Contact Item-Nr. (changed/discontinued article)
FORT WORTH	2896270

Phoenix Contact Item Designation (changed/discontinued article)

BC 107,6 UT HBUS BK

Report Date Substitute Item

13.08.2026

Replacement Product Designation