

Radiall Italia S.r.l. a socio unico - Società soggetta a direzione e coordinamento di Radiall Sa
Corso Europa 292 - 20017 Rho MILANO - Italia

TEL +39 (02) 356 993 1 | FAX +39 (02) 382 042 05 | EMAIL infoit@radiall.com

Date 07/05/2026

**Subject: Product Change Notification
SPPC-PWL-2.0 contacts COO India**


Dear Customer,

We thank you for the confidence you have shown in Radiall by placing orders on the products referenced above.

In the way of continuous quality improvement, Radiall may modify the design or the manufacturing process of our products.

We would like to inform you of the modification of the country of origin (COO) concerning the contacts of the SPPC-PWL-2.0 connectors. The recent years have been very challenging in terms of cost control and price management. In order to keep our cost stable and to continue to deliver high-quality products at competitive prices, we have decided to relocate some sub-assembly operations to our plant in India.

We also inform you that the packaging of the contacts produced in India has been improved. The blue net will be replaced with a special multi-metal paper that prevents damage from corrosion, temperature changes and humidity:



We assure you there will be no change in the quality, characteristics and performances of the products.

The change of COO will come into effect for deliveries starting from Q3 2026.

Radiall Italia S.r.l. a socio unico - Società soggetta a direzione e coordinamento di Radiall Sa
Corso Europa 292 - 20017 Rho MILANO - Italia
TEL +39 (02) 356 993 1 | **FAX** +39 (02) 382 042 05 | **EMAIL** infoit@radiall.com

Together with this letter, you will also receive the list of P/Ns you purchased in the last 3 years and involved in the COO change.

Please do not hesitate to contact your local sales representative or authorized distributors if you require any further information.

Sincerely,

Luca Basilico,
Quality Manager



Dear All,

Please find attached an information letter regarding the modification of the country of origin (COO) concerning the **contacts** of the SPPC-PWL-2.0 connectors.

Below the part numbers that are concerned and purchased in the past by TTI:

VS392501

VS392502

VS392503

VS392504

VS392505

Do not hesitate to contact us if you have any questions or concerns.

Kind regards

Eva Fuchs