

**1 Products affected**

Product hierarchy no. *				Part no.	SBU	Product Type	Customer part no.
SBU	PG	PUG	Type				
02	007	043	0000002290	See list below	Connectors	4790	
02	007	043	0000002295	See list below	Connectors	4795	

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected for type 4790

4790.1100	4790.1200		
-----------	-----------	--	--





List of part numbers affected for type 4795

4795.0000	4790.0100		
-----------	-----------	--	--

**2 Type of change**

- Change of product design
- Change of material

**3 Detailed description of change**

Current product appearance 4790	New product appearance 4790
	
Current product appearance 4795	New product appearance 4795
	

- Change of design for contacts L, N and PE.
- Change of material for cable guards from PVC to Silicone.

Engineering Documentation					PCN 4790/4795 - New contacts, material of cable guards		
owner	creation date	release date	released by	change order	rev	page	D10-096-327
huberth	09.12.2025	16.03.2026	gassmael		A	1 of 2	

**4 Reason of change**

- Improved withdrawal forces
- Enhanced material specification (non-halogen)

**5 Release date**

The change takes effect in ww 40/2026 (Date code 2640 or higher on label).  
Parts on stock will be used upon depletion.

**6 Impact of change and recommended action**

- Form                                      Note new appearance of contacts and new material of cable guard
- Fit
- Function
- Manufacturing
- Label
- Packaging

**7 Reference Documents**

Kind of document	Document Title
<a href="#">Data Sheet 4790</a>	
<a href="#">Data Sheet 4795</a>	

Engineering Documentation					PCN 4790/4795 - New contacts, material of cable guards		
owner	creation date	release date	released by	change order	rev	page	D10-096-327
huberth	09.12.2025	16.03.2026	gassmael		A	2 of 2	