

PRODUCT CHANGE NOTICE

PCN Number: 2025-INT-02 Issue Date: 06/03/2025

PCN Type: Product/Process Change

Discontinued Product

Part Number(s) Affected: Smiths P/N 305330-000 / Catalog P/N

Description of the Change: The solder cup hole depth has changed from .100 +/- .005 inches to .109 +/- .015

Reason for the Change: To improve manufacturability and keep the cost down.

Effective Date: June 3, 2025

Availability of New Samples: Immediately

For more information contact: Kevin Deford
Senior Product Line Manager
kevin.deford@smithsinterconnect.com

Hello

Please take action and contact all customer we shipped.

Vendor **IDI** part# **PI-5330**

Vendor **IDI** part# **305330-000-1012**