

July 24, 2026

Information Note

CeraDiode / Voltage Protection Devices

Notice regarding changes to customs-relevant master data Harmonized System (HS) – Code information

In accordance with the binding tariff information letter [ATBTI2026000033-DEC dated June 5, 2026](#), issued by the Austrian customs authority and valid until June 4, 2029, the HS-code information will change in the TDK shipping documents as follows:

Affected products

Ordering code	Type	Old HS-code (European Standard)	New HS-code (European Standard)
B72440D*	CeraDiode / Voltage Protection Devices	85411000	85332100
B72500D*			
B72570D*			
B72590C*			
B72590D*			
B72714D*			
B72724D*			
B72735D*			

The change will take effect with one of our next deliveries of the products with the affected ordering codes. All other specified product and delivery features remain unchanged.

We kindly ask you to forward this letter internally to your customs/shipping department to update the HS-code information accordingly, considering your national tariff classification, for which additional and/or partly different regulations may apply.

Please note that the above information is based on the present status as of July 20, 2026, and is provided by us for the sake of information. National tariff classifications are subject to changes. Importers are responsible for maintaining awareness of the currently valid regulations and following them.

Contact Carlos Schlabit, PPD ML PM, Munich

Customers are asked to address inquiries directly to their sales contacts.

Multilayer Components TDK Electronics AG

Rosenheimer Strasse 141 e, 81671 Munich · Post: P.O.Box 80 17 09, 81617 Munich, Germany
Headquarters: Munich · Commercial register of the local court (Amtsgericht): Munich HRB 127250
Chairman of the Supervisory Board: Joachim Zichlarz
Management Board: Dr. Werner Lohwasser, Chairman · Konrad Beck
www.tdk-electronics.tdk.com

PPD

CeraDiodes and TVS
diodes
Internal / External

260724PPD1e

July 24 2026

IN - CeraDiode/Voltage Protection Devices Notice regarding changes to customs-relevant master data-H

Affected Parts

B72500D50A60V9
B72500D150A60V9
B72500D200A60V9
B72500D50H160V9
B72590D150A60V9
B72590D160H60V9
B72590D50A60V9
B72590D50H160V9
B72724D200A62V9
B72500D90A60V9
B72570D120A60V9
B72500D160H60V9
B72500D300H60V9
B72724D160H62V9
B72735D50H62V9
B72570D160H60V9
B72714D160H60V9
B72590D50H260V9
B72590D360B60V9
B72590D150H60V9

Harmanized System (HS) code information