



Product Change Notification

Current Date: 29-May-2026

TE Connectivity

Product Change Notification: P-26-030410

PCN Date: 28-MAY-26

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

improvement the retention force between the Mate AX 4P casting and the HSG.

Description of Changes

Adding a rib to each of the four sides of the HSG increases the interference fit, thereby enhancing the pull-out strength between the casting and the HSG.

Reason for Changes:

Product improvement. Adding a rib to each of the four sides of the HSG increases the interference fit, thereby enhancing the pull-out strength between the casting and the HSG.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	20-JUN-2026
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-JUN-2026

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2378550-9	NO						



Product Change Notification

Current Date: 29-May-2026

TE Connectivity

Product Change Notification: P-26-030410

PCN Date: 28-MAY-26

Customer: TTI Inc (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

improvement the retention force between the Mate AX 4P casting and the HSG.

Description of Changes

Adding a rib to each of the four sides of the HSG increases the interference fit, thereby enhancing the pull-out strength between the casting and the HSG.

Reason for Changes:

Product improvement. Adding a rib to each of the four sides of the HSG increases the interference fit, thereby enhancing the pull-out strength between the casting and the HSG.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	20-JUN-2026
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-JUN-2026

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2378550-9	NO						