



Product Change Notification

Current Date: 25-Jun-2026

TE Connectivity

Product Change Notification: P-26-030583

PCN Date: 23-JUN-26

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

070 MLC W-W 4P Plug Hsg(PN:174922-1,2,7)

Description of Changes

- Two molds are in mass production at TEK Korea. - One additional mold has been newly fabricated. - This is PCN for a newly Mold.

Other attachments:

[Information for the new tooling\(PN:174922-1,2,7\)](#)

Reason for Changes:

New specification. '- The current two molds are aged. - There are frequent quality issues. - This is linked less productivity. ** A new tool has been manufactured to improve productivity and quality, and to expand capacity(CAPA).** - There are two different points when comparing the existing product.(There is no functional impact, and it is not easily identifiable by visual inspection)

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-OCT-2026
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
174922-1	NO		TYC174922-1	"0-0174922-1"			



Product Change Notification

Current Date: 25-Jun-2026

TE Connectivity

Product Change Notification: P-26-030583

PCN Date: 23-JUN-26

Customer: TTI Inc (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

070 MLC W-W 4P Plug Hsg(PN:174922-1,2,7)

Description of Changes

- Two molds are in mass production at TEK Korea. - One additional mold has been newly fabricated. - This is PCN for a newly Mold.

Other attachments:

[Information for the new tooling\(PN:174922-1,2,7\)](#)

Reason for Changes:

New specification. '- The current two molds are aged. - There are frequent quality issues. - This is linked less productivity. ** A new tool has been manufactured to improve productivity and quality, and to expand capacity(CAPA).** - There are two different points when comparing the existing product.(There is no functional impact, and it is not easily identifiable by visual inspection)

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-OCT-2026
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
174922-1	NO		TYC174922-1	"0-0174922-1"			