



The DNA of tech.™

Product Change Notification

Product Group: DI/Thursday April 23, 2026/PCN-DI-00002-2026-REV-0



additional manufacturing location for the IHHP Series

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas

Nick Schade
1505 East Highway 50
-
YANKTON SD United States 57078
Phone: 605-665-9301
Fax: 605-665-1627
nick.schade@vishay.com

Europe

Jessica Braun
Dr. Felix-Zandman-Platz 1
-
Selb Germany 95100
Phone: 49-9287-71-2117
Fax: 49-9287-8188
jessica.braun@vishay.com

Asia

Jacky Kim
9th Floor, Central Place
50 Seosomun-ro, Jung-gu
Seoul Korea, Republic of 04505
Phone: 82-2-3270-8837
Fax: 82-2-3270-8815
jacky.kim@vishay.com

Description of Change: An additional manufacturing location for product series (IHHP-0805ZH-01, IHHP-0806AB-01, IHHP-0806AZ-01, IHHP-0806ZH-01, IHHP-1008AB-01, IHHP-1008AZ-01) is being changed effective immediately.

Reason for Change: Current location has increased cost and MOQ to an unsustainable level.

Expected Influence on Quality/Reliability/Performance: No impact on quality of existing product.

Part Numbers/Series/Families Affected: Please see materials list on the succeeding page.

Vishay Brand(S): Vishay Dale

Time Schedule:

Start Shipment Date: Friday May 1, 2026

Sample Availability: 5/1/2026

Product Identification: N/A

Qualification Data: N/A

This PCN is considered approved, without further notification, unless we receive specific customer concerns before Monday June 1, 2026 or as specified by contract.

Issued By: Nick Schade, nick.schade@vishay.com



The DNA of tech.™

Product Change Notification

Product Group: DI/Thursday April 23, 2026/PCN-DI-00002-2026-REV-0



IHHP0805ZHERR47M01	IHHP0805ZHER1R0M01	IHHP0805ZHER2R2M01	IHHP0806ABERR22M01	IHHP0806ABERR24M01
IHHP0806ABERR47M01	IHHP0806ABER1R0M01	IHHP0806ABER1R5M01	IHHP0806ABER2R2M01	IHHP0806AZERR22M01
IHHP0806AZERR24M01	IHHP0806AZERR47M01	IHHP0806AZER1R0M01	IHHP0806AZER1R5M01	IHHP0806AZER2R2M01
IHHP0806AZERR47M01	IHHP0806AZER1R0M01	IHHP0806AZER2R2M01	IHHP1008ABERR22M01	IHHP1008ABERR24M01
IHHP1008ABERR33M01	IHHP1008ABERR47M01	IHHP1008ABER1R0M01	IHHP1008ABER1R5M01	IHHP1008ABER2R2M01
IHHP1008AZERR22M01	IHHP1008AZERR24M01	IHHP1008AZERR47M01	IHHP1008AZER1R0M01	IHHP1008AZER1R5M01
IHHP1008AZER2R2M01				

Vishay Material Code	Customer Material	Location
IHHP0805ZHER1R0M01	DALIHHP0805ZHER1R0M01	Ft Worth
IHHP0805ZHER2R2M01	DALIHHP0805ZHER2R2M01	Ft Worth
IHHP0806ABERR24M01	DALIHHP0806ABERR24M01	Ft Worth
IHHP0806AZER1R0M01	DALIHHP0806AZER1R0M01	Ft Worth
IHHP0806AZER2R2M01	DALIHHP0806AZER2R2M01	Ft Worth
IHHP0806AZERR47M01	DALIHHP0806AZERR47M01	Ft Worth
IHHP1008ABER1R0M01	DALIHHP1008ABER1R0M01	Ft Worth
IHHP1008ABER1R5M01	DALIHHP1008ABER1R5M01	Ft Worth
IHHP1008ABERR47M01	DALIHHP1008ABERR47M01	Ft Worth
IHHP0805ZHER1R0M01	DALIHHP0805ZHER1R0M01	Maisach Gernlinden
IHHP1008ABER2R2M01	DALIHHP1008ABER2R2M01	Maisach Gernlinden
IHHP1008ABERR33M01	DALIHHP1008ABERR33M01	Maisach Gernlinden
IHHP0806AZERR47M01	IHHP0806AZERR47M01	Singapore
IHHP1008ABER1R0M01	IHHP1008ABER1R0M01	Singapore
IHHP1008AZER2R2M01	IHHP1008AZER2R2M01	Singapore